

PROJECT UPDATE REPORT		
<div>2013 Bond Contingency Approved Projects</div> <div>Board Approvals: <u>March 27, 2017</u> \$9,964,000 and <u>May 22, 2017</u> \$30,662,000 <u>December 18, 2017</u> (Remaining funds from these contingency approved projects may be used to address similar critical needs within specific categories.)</div>		
Active Projects as of January 14, 2022		
Campus	Project Name	STATUS
District-wide	BSZ Pond Repair & Remediation 19RFP037	In Progress
Multiple Campuses	Boiler Replacement Various Schools	In Progress
Multiple Campuses	HVAC Controls System Improvements at Austin ISD	In Progress
Service Center	Service Center Site Water Improvements	In Progress
Completed Projects as of January 14, 2022		
Campus	Project Name	STATUS
Akins High School	Bleacher Repair at Bowie HS & 2nd Repair at Akins HS	Complete
Akins High School	Akins HS - Safety Fence, STEM Building	Complete
Akins High School	Akins Social Services: Office Relocation	Complete
Akins High School	Weight Room Expansion / Athletic Field Improvement at Akins	Complete
Akins High School	Akins HS - Theater Flooring	Complete
Allison Elementary School	Roofing Improvements at Allison ES	Complete
Allison Elementary School	Playground Canopy Allison	Complete
Allison Elementary School	Allison ES - Safety Fence	Complete
Anderson High School	Rigging & Lighting Inspection at Anderson HS	Complete
Anderson High School	Anderson HS - Sidewalk Accessibility Baseball Field	Complete
Anderson High School	Anderson Theater House Lighting Repairs	Complete
Anderson High School	Anderson HS - Band Tower Replacement	Complete
Anderson High School	Replacement of Weight Room Roof at Anderson HS	Complete
Anderson High School	Anderson HS - Library Flooring	Complete
Andrews Elementary School	Andrews ES - Front Fence	Complete
Andrews Elementary School	ADA Access Ramp and guardrails at Andrews ES	Complete
Austin High School	Office Conversion at Austin HS	Complete
Austin High School	Roofing - Upper Deck Repair	Complete
Austin High School	Replace (2) Elevators, New Doors, Accessible Route at Austin HS	Complete
Austin High School	Austin HS - AP Office Flooring	Complete
Baldwin Elementary School	Drainage Improvements at Baldwin ES	Complete
Baranoff Elementary School	Baranoff ES - ADA Curb Ramp	Complete
Baranoff Elementary School	Playground Equipment - Swings for Baranoff	Complete
Becker Elementary School	Replace carpet with Taraflex at Becker ES Gym	Complete

Becker Elementary School	Becker ES - Library Flooring, Abatement & Moving Services	Complete
Bedichek Middle School	Fire lane and parking lot striping at Bedichek MS	Complete
Boone Elementary School	Boone ES - Gym Floor Replacement	Complete
Boone Elementary School	Boone ES - Main Office Flooring	Complete
Boone Elementary School	Replacement Retainer Panels at Boone ES	Complete
Bowie High School	Motorized Security Gate at Bowie HS Ag Complex	Complete
Bowie High School	Repair Gym Bleachers at Bowie HS	Complete
Bowie High School	Bowie HS - Library Flooring	Complete
Bowie High School	Bowie HS - Ag Farm Fencing	Complete
Bowie High School	Creation of Counselors Office at Bowie HS	Complete
Bowie High School	Bowie HS - Book Room Flooring	Complete
Brown Elementary School	Demolition of TA Brown ES	Complete
Bryker Woods Elementary School	Safety Fence and Gates for Bryker Woods ES	Complete
Bryker Woods Elementary School	Bryker Woods ES - Gym Flooring Replacement	Complete
Burger Athletic Complex	Burger Stadium Repairs	Complete
Burnet Middle School	Burnet MS - Library & Office Flooring and Moving Services	Complete
Burnet Middle School	Burnet MS - Safety Fencing	Complete
Carruth Administration Center	Parking Garage Repairs at Carruth Administration Center	Complete
Central Warehouse	Move Food Service to the Central Warehouse	Complete
Cook Elementary School	Roof Repair or Replacement	Complete
Cook Elementary School	Roof Repair Replacement at Cook ES	Complete
Covington Middle School	Replacement of exterior exit door and door hardware at Covington MS	Complete
Covington Middle School	Revise Underfloor Kitchen Piping and Replace Grease Trap at Covington MS.	Complete
Covington Middle School	Covington MS - New Library Flooring	Complete
Covington Middle School	Covington MS - Bleacher Repair (Safety)	Complete
Cowan Elementary School	Replace Partition Between Cafe & Gym at Cowan ES	Complete
Cowan Elementary School	Cowan ES - Library Flooring & Moving Services	Complete
Cowan Elementary School	Cowan ES - Music Room Flooring	Complete
Crockett Early College High School	Repair of Bleachers at Crockett ECHS	Complete
Cunningham Elementary School	New Fire Door in Library at Cunningham ES	Complete
Cunningham Elementary School	Playscape Cover Replacement at Cunningham ES	Complete
Davis Elementary School	Davis ES - Safety Fence	Complete
District-wide	Roof Inspection and Data Base Development	Complete
District-wide	Annual Inspection of Playgrounds - District-wide	Complete
Eastside Memorial High School	Eastside Memorial - Chiller Swap Out	Complete
Eastside Memorial High School	Yellow Jacket Stadium - New Fence	Complete
Garcia Young Men's Leadership Academy	Urgent Repairs to building envelope and doors	Complete

Gullett Elementary School	Accessibility Changing Room - Life Skills Restroom Renovations	Complete
Gullett Elementary School	Gullett ADA Playground Equipment	Complete
Harris Elementary School	Harris ES - Library Flooring, Gym Floor & Moving Services	Complete
Hart Elementary School	Replacement of Playscape at Hart ES	Complete
Houston Elementary School	Roofing replacement in selected areas at Houston ES	Complete
Jordan ES and Overton ES	Barbara Jordan ES and Overton ES LED Upgrade	Complete
Kiker Elementary School	Secure Vestibule AT Kiker ES	Complete
Kiker Elementary School	Conversion of Resource Room into Office and Smaller Resource Room at Kiker ES	Complete
Kiker Elementary School	Kiker ES - Gym Flooring	Complete
Langford Elementary School	Replace and Install New Gym Floors at Langford ES	Complete
Langford Elementary School	Langford ES - Admin Office Flooring	Complete
LBJ High School	Resurfacing of Tennis Court at LBJ	Complete
LBJ HS and Northeast ECHS	TEA Innovative Academies at LBJ and Northeast ECHS	Complete
Lively Middle School	Lively MS - Safety Entrance Gates	Complete
Maplewood Elementary School	Drainage Improvements at Maplewood ES	Complete
Martin Middle School	Martin MS - Abate and Repair Gym Floor	Complete
Mathews Elementary School	Mathews ES - Gym Floor Replacement	Complete
McBee Elementary School	Replace Gym Floor at McBee ES Gym	Complete
McBee Elementary School	McBee ES - Main Office and Cafeteria Flooring	Complete
McCallum High School	McCallum Stage Curtain & Rigging Inspection	Complete
McCallum High School	McCallum Large Theater Curtain Damage Replacement	Complete
McCallum High School	Replace Damaged Windows at McCallum HS	Complete
McCallum High School	HVAC Repair/Replacement at McCallum HS	Complete
McCallum High School	McCallum HS - Call Box and Cameras	Complete
Means Young Women's Leadership Academy	Roofing replacement in selected areas at Means YWLA	Complete
Menchaca Elementary School	Roofing replacement in selected areas at Menchaca ES	Complete
Mendez Middle School	Mendez MS - Heat Exchanger Replacement	Complete
Mendez Middle School	Mendez MS - Library & Office Flooring and Moving Services	Complete
Mills Elementary School	Mills PreK Playground Renovation EQUIPMENT	Complete
Mills Elementary School	Mills PreK Playground Renovation INSTALL	Complete
Mills Elementary School	Mills ES - Gym Flooring	Complete
Mills Elementary School	Mills ES - Cafe Stage Stairs	Complete
Multiple Campuses	Replacement of Obsolete Furniture at Various Campuses	Complete
Multiple Campuses	Replacement of Non-Functional Window Coverings at Various Campuses	Complete
Multiple Campuses	Detention Ponds Old NOV's	Complete
Multiple Campuses	Replacement of Shade Canopy Covers at Various Campuses	Complete
Multiple Campuses	Urgent Roof Repairs and Various AISD Facilities	Complete

Multiple Campuses	Playground Equipment for Various Campuses	Complete
Multiple Campuses	2019-2020 Canopy Repair & Replacement - 8 Campuses	Complete
Multiple Campuses	Detention Ponds NOV's 2018-2019	Complete
Multiple Campuses	Master Planning for Admin. Centers	Complete
Multiple Campuses	Pest Exclusion at Various Campuses	Complete
Multiple Campuses	Installation of Playscape at Various Locations	Complete
Multiple Campuses	Repair and Replacement of Floor Coverings at Various Locations	Complete
Multiple Campuses	Repair of Mendez MS and Ann Richards SYW Repair of Bleachers	Complete
Multiple Campuses	Playground Fiber at Various Campuses	Complete
Multiple Campuses	Urgent Roofing/Waterproofing Repairs at Various AISD Campuses	Complete
Multiple Campuses	Portable Roof Repair and Replace	Complete
Multiple Campuses	Replacement of Approximately 100 Portable Classroom AC Units	Complete
Multiple Campuses	Flexible Furnishings for Upcoming School Renovations	Complete
Multiple Campuses	Urgent Replacement of Failed or Failing Mechanical Systems	Complete
Multiple Campuses	Urgent Mechanical Boiler Replacements	Complete
Multiple Campuses	Structural Repairs at Various Campuses	Complete
Multiple Campuses	Detention Pond Maintenance/Repairs at Various Campuses	Complete
Multiple Campuses	Replacement of Shade Canopy Covers at Various Campuses	Complete
Multiple Campuses	Roofing replacement in selected areas at Crockett ECHS, Travis ECHS, and Pillow ES	Complete
Multiple Campuses	Replacement of Exterior Door Exist Hardware at Selected Campuses	Complete
Multiple Campuses	New Outside Air Units and Humidity Sensors at various locations	Complete
Multiple Campuses	Abatement of Floors and Replacement of Floor Coverings at Selected Campuses	Complete
Multiple Campuses	Summer 2019 (20) School EWF Replacement	Complete
Multiple Campuses	Playground Replacement Install at Reilly, Boone and Harris	Complete
Multiple Campuses	Elementary School Gym Floor Striping	Complete
Multiple Campuses	Repair of Running Tracks at Burger Center, Austin HS, Lively MS, Lamar MS	Complete
Multiple Campuses	Playscape replacement at Cook ES, Ortega ES, Rodriguez ES, and St. Elmo ES	Complete
Multiple Campuses	Partitions at Clayton, Cook, McBee, and Boone Elementary Schools	Complete
Murchison Middle School	Roof Repairs to Gym Stage Roof Murchison ES	Complete
Murchison Middle School	Guardrail Re-enforcement at Murchison MS	Complete
Murchison Middle School	Cooling Tower Repairs at Murchison MS	Complete
Navarro Early College High School	New Air Handler Units in Gymnasium at Navarro ECHS	Complete
Navarro Early College High School	Navarro ECHS - Library Flooring, Abatement & Moving Services	Complete
Noack Sports Complex	Noack Sports Complex Fence Relocation	Complete
Northeast Early College High School	Northeast ECHS - Library Flooring, Abatement & Moving Services	Complete
Northeast Early College High School	Office Conversion at Northeast ECHS	Complete
Northeast Early College High School	New gymnasium lighting at Northeast ECHS	Complete

Northeast Early College High School	New lighting in the New Mall at Northeast ECHS	Complete
O.Henry Middle School	New gymnasium lighting at O.Henry MS	Complete
Oak Hill Elementary School	Oak Hill ES - Cafe Flooring	Complete
Oak Springs Elementary School	Replace Playscape at Oak Springs ES	Complete
Overton ES, Garcia YMLA and Delco Center	Repair Detention Ponds at Overton, Garcia and Delco	Complete
Paredes Middle School	Paredes MS - Library Flooring & Moving Services	Complete
Patton Elementary School	Playground Equipment at Patton	Complete
Pease Elementary School	Pease ES - Replacement Flooring Ramp	Complete
Perez Elementary School	Perez ES - Library Flooring & Moving Services	Complete
Pickle Elementary School	Addition/Renovations at Pickle ES	Complete
Pickle Elementary School	Cooling Tower Rebuild at Pickle ES	Complete
Pickle Elementary School	Roof Leak Repairs Pickle ES	Complete
Pillow Elementary School	Pillow ES - Sidewalk Replacement	Complete
Pleasant Hill Annex	Roofing replacement at Pleasant Hill Annex	Complete
Pleasant Hill Elementary	Replacement of Playscape	Complete
Pleasant Hill Elementary	Motor Control Repair at Pleasant Hill ES	Complete
Reilly ES and Ridgetop ES	Partial Roof Replacement at Reilly ES and Ridgetop ES	Complete
Rodriguez Elementary School	Rodriguez ES - Music Room and Stage Stairs	Complete
Rodriguez Elementary School	Rodriguez ES - Flooring For 6 Classrooms	Complete
Sadler Means Young Women's Leadership Academy	Leaning Canopy – Touch up Door at Means YWLA	Complete
Saegert Bus Terminal	Roof Improvements to Saegert Bus Shop	Complete
Sanchez Elementary School	Boiler Replacement at Sanchez ES	Complete
Service Center	Master Planning Admin. Centers: Move Transportation to the Service Center	Complete
Small Middle School	Installation of Bleachers at Small Middle School	Complete
Small Middle School	Small MS - Band Rooms, Flooring	Complete
St. Elmo Elementary School	Flooring Repairs at St Elmo	Complete
St. Elmo Elementary School	St. Elmo ES - Safety Fencing	Complete
Summitt Elementary School	Summitt ES - ADA Ramp Repair	Complete
Summitt Elementary School	Summitt ES - Annex Flooring Replacement	Complete
Summitt Elementary School	Parking Lot Striping	Complete
Sunset Valley Elementary School	Sunset Valley ES - Cafe Flooring	Complete
Sunset Valley Elementary School	Sunset Valley ES - ADA Life Skills Bathroom Remodel	Complete
Travis Early College High School	Installation Stairwell Railings at Travis High School	Complete
Travis Early College High School	Install Fence and Gate at Travis Near Large Portable	Complete
Travis Early College High School	Travis HS - Stained Carpet Flooring Project	Complete
Travis Early College High School	Travis HS - Chiller Swap-out	Complete
Travis Early College High School	Travis HS - Teacher's Lounge Flooring	Complete

Travis Heights Elementary School	Travis Heights ES - Gym Flooring & Striping	Complete
Travis Heights Elementary School	Sidewalk Damage Repair at Travis Heights	Complete
Travis Heights Elementary School	Travis Heights ES - Library & Office Flooring and Moving Services	Complete
Travis Heights Elementary School	Fire lane and parking lot striping at Travis Heights ES	Complete
Walnut Creek Elementary School	Replace Failed Fresh Air Units Walnut Creek ES	Complete
Walnut Creek Elementary School	Replace carpet with Taraflex at Walnut Creek ES Gym	Complete
Walnut Creek Elementary School	Walnut Creek ES - Small Office Flooring Replacement	Complete
Walnut Creek Elementary School	Walnut Creek ES - Parent Support Office (WO# 31484)	Complete
Webb Middle School	Roofing Improvements at Webb MS	Complete
Webb Middle School	Webb MS - Library Flooring	Complete
Webb Middle School	Install of PA horns at Webb	Complete
Webb Middle School	Webb MS - Gym Floor Repair (Safety)	Complete
Widen Elementary School	Widen ES - Cafeteria Flooring	Complete
Williams Elementary School	Swing Playground Equipment at Williams	Complete
Williams Elementary School	Swing Playground Equipment INSTALL at Williams	Complete
Williams Elementary School	Install New Partition at Cowan ES & Williams ES	Complete
Williams Elementary School	Williams ES - Library Flooring, Abatement & Moving Services	Complete
Winn Elementary School	Winn ES - Cafeteria and Gym Flooring	Complete
Wooten Elementary School	Wooten ES Library Flooring	Complete
Zilker Elementary School	Replace carpet with Taraflex at Zilker ES Gym	Complete
Zilker Elementary School	Zilker ES - Safety Fencing	Complete
Zilker Elementary School	ADA Ramp at Zilker ES	Complete