

2016 Facility Condition Assessment and Educational Suitability Assessment

CASEY ELEMENTARY SCHOOL


Facility Site

9400 Texas Oaks Drive
Austin, TX 78748

Building Area: 81,506 Square Feet
Site: 18 Acres
Date of First Construction: 1998

Assessment Timeline

Facility Condition Interview: 07/25/16
Facility Condition Field Visit: 07/25/16
Educational Suitability Interview: 08/08/16
Educational Suitability Field Visit: 08/08/16



Facility Summary



Casey Elementary School was first established in 1998. This facility includes classrooms, library, kitchen, cafeteria, and gymnasium. This is a two-story facility that includes a high bay area that houses the cafeteria and gymnasium.

Facility Condition Assessment (FCA)

The FCA is a process that is used to understand the deficiencies of a facility. It is conducted by a team of architects and engineers of various disciplines. The FCA is performed using existing data, facility staff interviews, facility walk-through assessments, analysis, and cost estimating.

FCA REPORT CARD

Casey Elementary School

34

*The FCA score is equal to 100 minus the Facility Condition Index (FCI). The FCI is equal to the cost to maintain, repair and replace deficiencies of a facility divided by the current replacement value of the facility.

Educational Suitability Assessment (ESA)

The ESA measures the degree to which the facility supports teaching and learning considering the exterior and site, academic spaces, support spaces, future-ready spaces, library and media center, security, technology, storage, fixtures, furniture and equipment, environmental quality, and controllability of lighting and HVAC systems.

ESA REPORT CARD

Casey Elementary School

72

*The FCA and ESA scores are not a representation of the school's academic performance and does not reflect any construction or improvements performed after the assessment date.
*These are draft scores pending AISD feedback.

Links to Online Surveys:

[AISD Educational Suitability Survey](https://www.surveymonkey.com/r/AISD_Educational_Suitability_Survey) - https://www.surveymonkey.com/r/AISD_Educational_Suitability_Survey

[AISD Cuestionario para la Condicion de Instalacion y Conveniencia Educativa](https://www.surveymonkey.com/r/AISD_Educational_Suitability_Espanol) - https://www.surveymonkey.com/r/AISD_Educational_Suitability_Espanol

2016 Facility Condition Assessment and Educational Suitability Assessment

Rev. 11/30/2016

Facility Condition Assessment

Rating Scale:



Excellent



Good



Average



Poor



Fail

BLDG-173A
Main School Building

Mechanical / HVAC

Mechanical / HVAC

P

Domestic Water Distribution

A

Plumbing Fixtures

A

Elevators & Lifts

G

Electrical

Electrical Distribution

A

Lighting

P

Communications & Security

A

Fire Alarm

A

Fire Protection / Suppression

A

Exterior Architecture

Exterior Doors

A

Exterior Walls

A

Exterior Windows

G

Exterior Stairs

G

Roofing

P

Interior Architecture

Interior Ceiling Finishes

P

Interior Doors

A

Interior Floor Finishes

A

Interior Walls

A

Interior Wall Finishes

A

Interior Stairs

G

Site / Civil

Roadways

G

Parking Lots

G

Pedestrian Paving (Sidewalks)

G

Site Development

G

Landscaping

A

Play Fields

A

Crawl Space

Drainage Below Building

N/A

Access / Ventilation

N/A

Foundation

N/A

Exposed Pipes

N/A

Exposed Ductwork

N/A

Education Suitability Assessment

Rating Scale



Excellent
81-100



Good
66-80



Average
51-65



Unsatisfactory
36-50



Very Unsatisfactory
20-35

| Assessment Area | Score |
|--|-------|
| Exterior | 72 |
| General Building | 87 |
| General Academic & Elective Spaces | 71 |
| Future Ready Student Development | 78 |
| Library / Media Center | 65 |
| Security | 65 |
| Technology | 70 |
| Storage | 60 |
| Furniture, Fixtures & Equipment | 62 |
| Environmental Quality (Lighting, Odors, Pests) | 84 |
| Controllability of Systems (Lights, Temps, Blinds) | 84 |