

2016 Facility Condition Assessment and Educational Suitability Assessment

WALNUT CREEK ELEMENTARY SCHOOL

WALNUT CREEK ELEMENTARY SCHOOL



<u>Facility Site</u> 401 W. Braker Lane Austin, TX 78753

Building Area: 79,223 Square Feet

Site: 12 Acres

Date of First Construction: 1961

Assessment Timeline

Facility Condition Interview: 08/04/16
Facility Condition Field Visit: 08/08/16
Educational Suitability Interview: 08/04/16
Educational Suitability Field Visit: 08/04/16

Facility Summary



Walnut Creek Elementary School was established in 1961, and consists of two permanent campus buildings. The Main School Building (BLDG-141A) includes administration offices, classrooms, gymnasium and cafeteria. The other permanent campus building is the Separate Building (BLDG-141B), which is a classroom addition constructed in 1999.

Facility Condition Assessment (FCA)

The FCA is a process that is used to understand the deficiencies of a facility. It is conducted by a team of architects and engineers of various disciplines. The FCA is performed using existing data, facility staff interviews, facility walk-though assessments, analysis, and cost estimating.

FCA REPORT CARD

Walnut Creek Elementary School

45

*The FCA score is equal to 100 minus the Facility Condition Index (FCI). The FCI is equal to the cost to maintain, repair and replace deficiencies of a facility divided by the current replacement value of the facility.

Educational Suitability Assessment (ESA)

The ESA measures the degree to which the facility supports teaching and learning considering the exterior and site, academic spaces, support spaces, future-ready spaces, library and media center, security, technology, storage, fixtures, furniture and equipment, environmental quality, and controllability of lighting and HVAC systems.

ESA REPORT CARD

Walnut Creek Elementary School

57

*The FCA and ESA scores are not a representation of the school's academic performance and does not reflect any construction or improvements performed after the assessment date.

*These are draft scores pending AISD feedback.

Links to Online Surveys:

AISD Educational Suitability Survey - https://www.surveymonkey.com/r/AISD_Educational_Suitability_Survey

AISD Cuestionario para la Condicion de Instalacion y Conveniencia Educativa - https://www.survekymonkey.com/r/AISD_Educational_Suitability_Espanol



2016 Facility Condition Assessment and Educational Suitability Assessment

WALNUT CREEK ELEMENTARY SCHOOL

Rev. 11/22/2016

Facility Condition Assessment		
Rating Scale: God Average Poor Fail	BLDG-141A Main School Building	BLDG-141B Classroom Building
Mechanical / HVAC		
Mechanical / HVAC	<u>A</u>	(A)
Domestic Water Distribution	A	A
Plumbing Fixtures	<u>A</u>	A
Elevators & Lifts	N/A	N/A
Electrical		
Electrical Distribution	A	©
Lighting	A	G
Communications & Security	©	©
Fire Alarm	G	G
Fire Protection / Suppression	©	(A)
Exterior Architecture		
Exterior Doors	(A)	(A)
Exterior Walls	©	G
Exterior Windows	P	©
Exterior Stairs	A	N/A
Roofing	<u>(A)</u>	<u>(A</u>)
Interior Architecture		_
Interior Ceiling Finishes	A	©
Interior Doors	A	<u>G</u>
Interior Floor Finishes	A	<u>©</u>
Interior Walls	A	<u>G</u>
Interior Wall Finishes	<u>©</u>	©
Interior Stairs	A	N/A
Site / Civil	Crawl Space	
Roadways	Drainage Below Building	g N/A
Parking Lots	Access / Ventilation	N/A
Pedestrian Paving (Sidewalks)	Foundation	N/A
Site Development P	Exposed Pipes	N/A
Landscaping	Exposed Ductwork	N/A
Play Fields		

Rating Scale

Excellent 81-100

Good 66-80

Average 51-65

Unsatisfactory 36-50

Very Unsatisfactory 20-35

Assessment Area	Score
Exterior	54
General Building	53
General Academic & Elective Spaces	43
Future Ready Student Development	58
Library / Media Center	75
Security	60
Technology	50
Storage	53
Furniture, Fixtures & Equipment	75
Environmental Quality (Lighting, Odors, Pests)	72
Controllability of Systems (Lights, Temps, Blinds)	44)

