

Site: 28 Acres

2016 Facility Condition Assessment and Educational Suitability Assessment





Assessment Timeline

Facility Condition Interview: 08/11/16 **Facility Condition Field Visit:** 08/08/16 Educational Suitability Interview: 08/11/16 **Educational Suitability Field Visit: 08/11/16**

Facility Summary



Eastside Memorial High School was established in 1960, and consists of four permanent buildings which include the Main School Building (BLDG-019A), Theater Building (BLDG-019B), the Separate Classroom Building (BLDG-019C), and Mechanical Building (BLDG-019D). The Main School Building and the Separate Classroom Building are connected to one another by a covered sidewalk. The Theater Building and the Mechanical Building are located directly adjacent to the Main School Building.

Facility Condition Assessment (FCA)

The FCA is a process that is used to understand the deficiencies of a facility. It is conducted by a team of architects and engineers of various disciplines. The FCA is performed using existing data, facility staff interviews, facility walk-though assessments, analysis, and cost estimating.

FCA REPORT CARD

Eastside Memorial High School



*The FCA score is equal to 100 minus the Facility Condition Index (FCI). The FCI is equal to the cost to maintain, repair and replace deficiencies of a facility divided by the current replacement value of the facility.

Educational Suitability Assessment (ESA)

The ESA measures the degree to which the facility supports teaching and learning considering the exterior and site, academic spaces, support spaces, future-ready spaces, library and media center, security, technology, storage, fixtures, furniture and equipment, environmental quality, and controllability of lighting and HVAC systems.

ESA REPORT CARD

Eastside Memorial High School

*The FCA and ESA scores are not a representation of the school's academic performance and does not reflect any construction or improvements performed after the assessment date. *These are draft scores pending AISD feedback.

Links to Online Surveys:

AISD Educational Suitability Survey - https://www.surveymonkey.com/r/AISD_Educational_Suitability_Survey

AISD Cuestionario para la Condicion de Instalacion y Conveniencia Educativa - https://www.survekymonkey.com/r/AISD_Educational_Suitability_Espanol



2016 Facility Condition Assessment and Educational Suitability Assessment

Facility Condition Assessment



Rev. 11/22/2016

I acility Collution Assessment				
g Scale: 📵 🌀 🔥 P 🛑	BLDG-019A	BLDG-019B	BLDG-019C	
Excellent Good Average Poor Fail	Main School Building	Theater Building	Separate Classroom Bldg.	
Mechanical / HVAC				
Mechanical / HVAC	A	A	G	
Domestic Water Distribution	A	G	A	
Plumbing Fixtures	P	G	G	
Elevators & Lifts	3	N/A	A	
Electrical				
Electrical Distribution	P	A	A	
Lighting	G	G	P	
Communications & Security	G	A	G	
Fire Alarm	G	G	A	
Fire Protection / Suppression	A	G	A	
Exterior Architecture				
Exterior Doors	A	A	A	
Exterior Walls	A	G	G	
Exterior Windows	P	A	G	
Exterior Stairs	A	G	N/A	
Roofing	A	P	G	
nterior Architecture				
Interior Ceiling Finishes	A	A	G	
Interior Doors	P	A	G	
Interior Floor Finishes	A	A	G	
Interior Walls	A	A	G	
Interior Wall Finishes	A	A	G	
Interior Stairs	A	G	G	
Site / Civil		Crawl Space		
Roadways	A	Drainage Below Building	N/A	
Parking Lots	P	Access / Ventilation	N/A	
	P	Foundation	N/A	

Education Suitability Assessment

Exposed Pipes

Exposed Ductwork

G

A

A

Rating Scale

Site Development

Landscaping

Play Fields

Excellent 81-100

Good 66-80

Average 51-65

Unsatisfactory 36-50

Very Unsatisfactory 20-35

Assessment Area	Score
Exterior	(46)
General Building	50
General Academic & Elective Spaces	34
Future Ready Student Development	50
Library / Media Center	62
Security	48
Technology	50
Storage	33
Furniture, Fixtures & Equipment	49
Environmental Quality (Lighting, Odors, Pests)	60
Controllability of Systems (Lights, Temps, Blinds)	52



N/A

N/A