## **Bedichek Middle School**



## Educational Suitability and Facility Condition Assessments - 2021



### **Facility Summary**

Bedichek Middle School serves a student enrollment of approximately 780 students in south Austin and has a high percentage of students with special education needs. The school comprises a large central courtyard and spacious open-air hallways. Technology is well distributed through the campus, with large screens and projectors in all studios, and an abundance of screens and projectors in the library. Most studios lack sufficient access to daylight and have only two small windows. Several studios have no windows. Science Lab furniture needs to be updated, while the art studios are under construction and currently not accessible.

Building Address: 6800 Bill Hughes Road Austin, TX 78745

Building Square Footage: 136,400 SF Site Acreage: 28 Acres Date of First Construction: 1972


#### **Student Demographics:**


Demographic	Percentage
African American	5.0%
Hispanic	86.3%
White	6.0%
American Indian	0.0%
Asian	0.8%
Pacific Islander	0.0%
Two or More Races	1.9%
Economically Disadvantaged	85.1%
English Language Learners	34.8%
Special Education	22.7%
Enrollment	779

# Educational Suitability Assessment Score:

– – District MiddleSchool's ESA Average: 62










### Facility Condition Assessment Score:

– District MiddleSchool's FCA Average: 66



Questions/Comments? Email: Assessments@perkinswill.com

## **Bedichek Middle School**



### Educational Suitability and Facility Condition Assessments - 2021

The ESA evaluates how well a facility supports teaching and learning using the district's Educational Specifications as the standard. It includes items such as the exterior, general building, security, controllability of lighting, furniture, academic and administrative spaces, and technology.

The FCA evaluates the physical condition of a facility to measure what systems are broken, aging, etc. This includes items such as roofing, heating and air conditioning, plumbing, electrical, site drainage, and parking.

Both assessments incorporate data, staff interviews, facility walk-throughs, cost-estimating, and analysis.

#### **FSA Score:**

District Middle School's ESA Average: 62



### General Building

1 - Exterior 2 - Outdoor Learning and Activity

3 - General Building

4 - Security

5 - Environmental Quality

6 - Controllability of Systems

7 - Furniture, Fixtures, Equipment



#### Campus-wide

1 - Exterior Architecture

2 - Interior Architecture

3 - Structural

4 - Mechanical / HVAC

5 - Electrical


6 - Plumbing


7 - Site / Civil

8 - Crawlspace

### **FCA Score:**

District Middle School's FCA Average: 66





8 - Academics & Learning

9 - CTE Career Connected Learning

10 - Visual and Performing Arts

11 - Athletics and Wellness

12 - Food Service

13 - Media Resources

14 - Technology

15 - Administration Spaces















Very Unsatisfactory 0-35

Unsatisfactory 36-50

**Average** 51-65

Satisfactory 66-80

Very Satisfactory 81-100

> Questions/Comments? Email: Assessments@perkinswill.com