Pickle Elementary School



Educational Suitability and Facility Condition Assessments - 2021



Facility Summary


Pickle Elementary School, serving an enrollment of approximately 445 students in northeast Austin, is known for its close ties to the St. John Community Center. The campus includes the school, community center, community clinic and a public library. The school and community center share several key spaces. The shared resources mean that the campus and gym are quite large in comparison to other elementary schools in the district.

Building Address: 1101 Wheatley Ave Austin, TX 78752

Building Square Footage:	88,000 SF
Site Acreage:	17 acres
Date of First Construction:	2001

Student Demographics:

Demographic	Percentage
African American	8.3%
Hispanic	83.6%
White	3.8%
American Indian	0.0%
Asian	3.2%
Pacific Islander	0.7%
Two or More Races	0.5%
Economically Disadvantaged	92.3%
English Language Learners	81.5%
Special Education	7.4%
Enrollment	444



Jacobs Perkins&Will

Pickle Elementary School



Educational Suitability and Facility Condition Assessments - 2021

The ESA evaluates how well a facility supports teaching and learning using the district's Educational Specifications as the standard. It includes items such as the exterior, general building, security, controllability of lighting, furniture, academic and administrative spaces, and technology.

The FCA evaluates the physical condition of a facility to measure what systems are broken, aging, etc. This includes items such as roofing, heating and air conditioning, plumbing, electrical, site drainage, and parking.

Both assessments incorporate data, staff interviews, facility walk-throughs, cost-estimating, and analysis.

