# **Williams Elementary School**



## Educational Suitability and Facility Condition Assessments - 2021



### **Facility Summary**


Williams Elementary School, serving an enrollment of approximately 410 students, is in southeast Austin. It was built in 1976 and consists of approximately 64,000 SF on nearly 14 acres. The school is known for its two-way bilingual, AVID, creative learning initiative, social and emotional learning, and early childhood development programs. Since the school was constructed in the mid-70's, separate studios have been created within the footprint of the original open concept plan. The typical layout is a cluster of four studios connected by an opening in the walls with no doors.

Building Address: 500 Mairo St Austin, TX 78748

Building Square Footage:	64,800 SF
Site Acreage:	14 Acres
Date of First Construction:	1976

#### Student Demographics:

Demographic	Percentage
African American	5.6%
Hispanic	76.0%
White	10.5%
American Indian	0.0%
Asian	4.2%
Pacific Islander	0.0%
Two or More Races	3.7%
Economically Disadvantaged	72.6%
English Language Learners	28.1%
Special Education	23.2%
Enrollment	409



#### Jacobs Perkins&Will

## **Williams Elementary School**



### Educational Suitability and Facility Condition Assessments - 2021

The ESA evaluates how well a facility supports teaching and learning using the district's Educational Specifications as the standard. It includes items such as the exterior, general building, security, controllability of lighting, furniture, academic and administrative spaces, and technology.

The FCA evaluates the physical condition of a facility to measure what systems are broken, aging, etc. This includes items such as roofing, heating and air conditioning, plumbing, electrical, site drainage, and parking.

Both assessments incorporate data, staff interviews, facility walk-throughs, cost-estimating, and analysis.

