

# **Educational Suitability Summary Report**

**Bailey Middle School** 

Date: 12/21/2020 Score 63% Average

Bailey Middle School, serving an enrollment of approximately 925 students in southwest Austin, is known for its award-winning band program, native plants and animals program, and its successful robotics team. The school opened in 1993 and has approximately 150,000 square feet of building space on 41 acres.

In general, the two-story middle school exterior looks well-maintained and is attractive and inviting. The site is quite large and can accommodate a variety of outdoor sport courts and playfields. The school does not meet the current Education Specifications standards for collaboration as studios are along a central corridor, with little to no flexibility or visibility between it and adjacent studios. In addition, there are few breakout rooms to host small groups or independent study. Most studios do not have casework to provide for storage.

The campus cafetorium is large and appears to function well. The band and orchestra rooms appear to be too small. The choir room is in a repurposed studio with nonreconfigurable risers. The dance and robotics programs are in portables.

#### Interview Overview

An interview was conducted with Principal John Rocha, Assistant Principal Floretta Andrews, and staff members Kathleen Legrand, Rachael Belinda and Brook Beasley. One challenge administrators face is the lack of small group areas and spaces for visiting specialists and other itinerant staff. Currently, small groups and itinerant staff are hosted in portables. If made available, these small group spaces could also be used for social services such as counseling or support for students and their families.

The robotics program, dance, sixth-grade band, and steel drums do not have permanent spaces. The robotics program has gained popularity in the last few years and is now one of the most popular school programs, hosting and winning many regional competitions. The band is also award winning but due to lack of storage, the program utilizes ensemble rooms for instruments and chairs and supplies are stored in stairwells and corridors. Staff noted there is a lack of storage throughout campus.

Likely due to lack of space within the fine arts area, choir used to be in the portables but has since moved to a standard studio. The theater room does not have a true practice stage and is missing storage for costumes and equipment.

The administrators highlighted several items that would help position the school for future learning needs. They said that facilities for computer programming, AR/VR and e-sports would be valuable since these fields interest the students and could provide valuable job skills. They also noted the need

## **Educational Suitability Summary Report**

**Bailey Middle School** 

for adequate Wi-Fi coverage campus-wide and dedicated space in each wing for teacher workspace. They also commented that the athletic locker rooms and weight room need updates and new equipment.

When asked what ideas should be considered today to better prepare Bailey Middle School for 20 years from now, the administrative team focused on updated technology. Allowing for the blend of in-person and remote learning was deemed critical, since one teacher could more easily teach multiple students in a virtual space. Updated science and technology labs to better prepare students for real world occupations are desired. Charging stations and workstations outside of the studios for independent study would be very beneficial to teachers and students.

## **Assessment Findings**

The Educational Suitability Assessment of Bailey Middle School earned a 63% overall score and places the campus in a category of Average. The assessment consists of seven General Building categories and eight Academic categories to determine areas that need more attention.

### **Unsatisfactory Categories (36-50%):**

## **Visual and Performing Arts**

Score is unsatisfactory.

The band and orchestra spaces are well-maintained but are deficient in size, storage and acoustics. Choir and dance lack appropriate facilities for the programs.

#### **Technology**

Score is unsatisfactory.

Audio/visual equipment was observed in the library and cafeteria. Most studios are missing adequate charging and power outlets for devices.

#### **Academics & Learning**

Score is unsatisfactory.

There is little to no flexibility or visibility between adjacent studios and the corridor. Studios lack storage. Maker spaces, STEAM and professional learning centers are missing. There are limited opportunities for independent study or flexible teaching space.

#### Average Categories (51-65%):

#### **Media Resources**

Score is average.

The library is not easy for visitors to access from the exterior or for after-hours use due to its location and inadequate signage but is centrally located for students. It is well-sized, and audio/visual technology and a variety of furniture are present. There are small rooms off the stack area that could be used for student group work or teacher planning.

## **Controllability of Systems**

Score is average.

The studio thermostats can be controlled individually, but lighting is typically tied to two switches with no dimming. Blinds appear to be missing from several studios.

## **Educational Suitability Summary Report**

**Bailey Middle School** 

### Furniture, Fixtures and Equipment

Score is average.

The campus has little variety in furniture types. Most work surfaces are desks with detached chairs, which appear to be reconfigurable.

#### Security

Score is average.

## **Environmental Quality**

Score is average.

All learning studios have access to natural light and exterior views (except band halls, choir and orchestra rooms). Windows are small, and some rooms only have one window. Acoustics are average with some noise from other studios or corridors.

### **CTE and Career Connected Learning**

Score is average.

Food/agriculture/hospitality programs have some pathways into high school programs.

## Satisfactory Categories (66-80%):

#### **Outdoor Learning and Activity**

Score is satisfactory.

Farm animals, gardens, outdoor pond and playing fields provide opportunities for hands-on learning.

#### **Administration Spaces**

Score is satisfactory.

Reception area is welcoming and a good size.

#### **Athletics and Wellness**

Score is satisfactory.

Athletics facilities (interior and exterior) are in good shape and are ready for UIL competitions.

## **Food Services**

Score is satisfactory.

The dining area is a good size and functions well. The area needs more storage for tables and chairs.

#### **General Building**

Score is satisfactory.

Corridors are generous and the exterior of the building is well-maintained. The band, orchestra and cafeteria wing can be sectioned off from the remainder of the school for after-hours events.

# **Educational Suitability Summary Report**

Bailey Middle School


## Very Satisfactory Categories (81-100%):

## **Exterior**

Score is very satisfactory.

Building exterior is well-maintained. Parent drop-off and bus drop-off are separated and appear to function well. There is a monument sign at the street and the main entry of the school is easily identified. There is access to dumpster and the compost is next to the cafeteria and easy to access.

**Bailey Middle School** 



Attractive and well-maintained building exterior.




Large commons area serves as a reception space during school and for after-hours programming.



Choir facilities are makeshift and not suitable for the program.



The administrative suite is well-sized but could benefit from updated finishes.



Storage is lacking in many spaces throughout the school.



Generous corridors could be reconfigured for flexible, independent learning.

**Bailey Middle School** 



There is a large stage and generous cafeteria seating.



Orchestra and band spaces are undersized.

**Bailey Middle School** 



The gym is large and functions well but needs updates to finishes.



Tennis courts are in disrepair.



# Austin ISD Educational Suitability Assessment Criteria

# **General Building**

| School Name | Walk Attendees:                         | Date:      |
|-------------|---|------------|
| Bailey MS   | Angela Whitaker-Williams and Lane Green | 12/15/2020 |

| 1 - E | xterior                    |   | 1 | 2 | 3 | 4 | 5 | N/A |   | 8.75 | 94%  |
|-------|----------------------------|---|---|---|---|---|---|-----|---|------|------|
| 1.1   | Does the sit<br>pedestrian | te permit desirable separation of vehicular, bus and traffic?   |   |   |   |   | 5 |     | Comments                                  | 1.00 | 5.00 |
|       | 1                          | Very unsatisfactory - Bus, car and pedestrian all happen at the same location                                   |   |   |   |   |   |     | Separation between all modes of drop-off. |      |      |
|       | 2                          | Unsatisfactory - Cars and buses mix, pedestrians are<br>separated   |   |   |   |   |   |     |   |      |      |
|       | 3                          | Average - Buses, cars, and pedestrians are separate but stack space is small                                    |   |   |   |   |   |     |   |      |      |
|       | 4                          | Satisfactory - Buses, cars, and pedestrians are separate but drop off does not have a canopy or a holding place |   |   |   |   |   |     |   |      |      |
|       | _                          | like a commons or cafeteria   |   |   |   |   |   |     |   |      |      |
|       | 5                          | Very satisfactory - Buses, cars, and pedestrians are separate and drop off area has a canopy and destination    |   |   |   |   |   |     |   |      |      |
|       | N/A                        | Does not apply  |   |   |   |   |   |     |   |      |      |
| 1.2   |                            | ing easily identified with appropriate signage and wayfinding?  |   |   |   |   | 5 |     | Comments                                  | 0.25 | 1.25 |
|       | 1                          | Very unsatisfactory - Campus has no signage / wayfinding  |   |   |   |   |   |     | School is easy to identify.               |      |      |
|       | 2                          | Unsatisfactory - Signage/wayfinding is faded/hidden   |   |   |   |   |   |     |   |      |      |
|       | 3                          | Average - Signage / wayfinding visible but not apparent   |   |   |   |   |   |     |   |      |      |
|       | 4                          | Satisfactory - Signage / wayfinding is visible but not good condition   |   |   |   |   |   |     |   |      |      |
|       | 5                          | Very satisfactory - Signage and wayfinding is visible and easy to use   |   |   |   |   |   |     |   |      |      |
|       | N/A                        | Does not apply  |   |   |   |   |   |     |   |      |      |

O2/11/2022 <sup>2</sup>

| 1 - E | xterior (co           | nt.)  | 1        | 2 | 3 | 4 | 5 | , N | N/A  |   |       |      |
|-------|-----------------------|---|----------|---|---|---|---|-----|------|---|-------|------|
| 1.3   | Is the dump           | oster accessible for trash / compost disposal?  |          |   |   | 4 |   |     |      | Comments  | 0.50  | 2.00 |
|       | 1<br>2<br>3<br>4<br>5 | Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpste Unsatisfactory - Compost is present. Route has obstacles to dumpster Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent. Satisfactory - Compost and dumpster are directly adjacent and route is barrier free Very Satisfactory - Compost and dumpster are directly |          |   |   |   |   | •   |      | Dumpster access is satisfactory.                      |       |      |
|       | 3                     | adjacent and route is barrier free. Dumpster are shaped /   |          |   |   |   |   |     |      |   |       |      |
|       | N1/A                  | positioned so people of all heights can access it.  |          |   |   |   |   |     | L    |   |       |      |
| 2 - 0 | N/A<br>Outdoor Le     | Does not apply arning and Activity  | 1        | 2 | 3 | 4 | 5 |     | N/A  |   | 10.00 | 70%  |
|       |                       | or studios and support spaces appropriately configured per  | <u>'</u> | 1 |   | 1 | T | T   | 1/ / |   | 10.00 | 7076 |
| 2.1   | the ed spec           |   |          | 2 |   |   |   |     |      | Comments  | 1.00  | 2.00 |
|       | 1                     | Very unsatisfactory - No dedicated outdoor studios  |          |   |   |   |   |     |      | Outdoor studios spaces are limited and not per ed spe | ec.   |      |
|       | 2                     | Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no shade provided  |          |   |   |   |   |     |      |   |       |      |
|       | 3                     | Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less  |          |   |   |   |   |     |      |   |       |      |
|       | 4                     | shade coverage over studio area Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade coverage over studio area   |          |   |   |   |   |     |      |   |       |      |
|       | 5                     | Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full shade coverage over studio area   |          |   |   |   |   |     |      |   |       |      |
|       | N/A                   | Does not apply  |          |   |   |   |   |     | L    |   |       |      |
| 2.2   |                       | playgrounds (elementary only) and support spaces per the ed spec?   |          |   |   |   |   | ١   | N/A  | Comments  | 0.00  | 0.00 |
|       | 1                     | Very unsatisfactory - No dedicated active playground  |          |   |   |   |   |     |      |   |       |      |
|       | 2                     | Unsatisfactory - Too small, poor condition, no shade provided   |          |   |   |   |   |     |      |   |       |      |
|       | 3                     | Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less  |          |   |   |   |   |     |      |   |       |      |
|       | 4                     | shade coverage over play structure Satisfactory - Good size, good condition, more than 50% shade coverage over play structure   |          |   |   |   |   |     |      |   |       |      |
|       | 5                     | Very satisfactory - Generous size, excellent condition, full shade coverage over play structure   |          |   |   |   |   |     |      |   |       |      |
|       | N/A                   | Does not apply  |          |   |   |   |   |     | L    |   |       |      |

| 2 - 0 | Outdoor Le            | arning and Activity (cont)  | 1        | 2 | 3 | 4 | 5 | N/A | A   |                |          |
|-------|-----------------------|---|----------|---|---|---|---|-----|---|----------------|----------|
| 2.3   |                       | s and support spaces appropriately configured per the eduation on infrastructure not condition of plants)   |          |   |   | 4 |   |     | Comments  | 0.00           | 0.00     |
|       | 1 2                   | Very unsatisfactory - No dedicated gardens Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no accessible water                       |          |   |   |   |   |     | Recording answer, does not affect the score of Outdo<br>Activity.   | or Learning ar | nd       |
|       | 3                     | source Average - Adequate size, adequate condition, needs some renovations or updates to function well, water source is difficult to access   |          |   |   |   |   |     | Gardens are of good size and condition.   |                |          |
|       | 4                     | Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, water source is accessible with 100 ft hose   | )        |   |   |   |   |     |   |                |          |
|       | 5                     | Very Satisfactory - Generous size, excellent condition,<br>connected to learning spaces, excellent flexibility, water<br>source is less than 50ft from the garden or has irrigation |          |   |   |   |   |     |   |                |          |
|       | N/A                   | Does not apply  |          |   | 1 |   |   |     |   |                |          |
| 2.4   | Are the rain ed spec? | gardens and/or cisterns appropriately configured per the  |          |   | 3 |   |   |     | Comments  | 0.00           | 0.00     |
|       | 1<br>2<br>3           | Very unsatisfactory - No rain gardens or cisterns Unsatisfactory - Too small, poor condition, not functioning, disconnected Average - Adequate size, adequate condition, is         |          |   |   |   |   |     | Recording answer, does not affect the score of Outdo Activity.  No rain garden; two cisterns in front of building not c | · ·            |          |
|       | 4                     | connected, needs some renovations or updates to<br>function well<br>Satisfactory - Good size, good condition, functions   |          |   |   |   |   |     | spaces.   | omiceted to ic | arriirig |
|       | 5                     | properly Very Satisfactory - Generous size, excellent condition, exceptional functionality, connected to learning spaces, educational signage provided                              |          |   |   |   |   |     |   |                |          |
|       | N/A                   | Does not apply  |          |   |   |   |   |     |   |                |          |
| 2.5   |                       | hool have animal husbandry? (optional)  |          |   |   |   | 5 |     | Comments  | 0.00           | 0.00     |
|       | 1                     | No  |          |   |   |   |   |     |   |                |          |
|       | 5                     | Yes   | -        |   |   |   |   |     |   |                |          |
| 2.6   | Does the sci          | nool have nature loop trails? (optional)  No  |          |   |   |   | L |     | Comments  | 0.00           | 0.00     |
|       | 5                     | Yes   |          |   |   |   |   |     |   |                |          |
| 2.7   |                       | nool have a learning pond? (optional)   |          |   |   |   | 5 |     | Comments  | 0.00           | 0.00     |
|       | 1                     | No  |          |   |   |   |   |     |   |                |          |
|       | 5                     | Yes   |          |   |   |   |   |     |   |                |          |
| 2.8   | Does the scl          | hool have a grass play field and walking trail?   | <u> </u> |   |   |   | 5 |     | Comments  | 1.00           | 5.00     |
|       | 1                     | No<br>V   |          |   |   |   |   |     |   |                |          |
|       | 5                     | Yes   |          |   |   |   |   |     |   |                |          |

| 3 - General Bu   | ilding   | 1 | 2 | 3 | 4 | 5 | N/A |  | 11.25          | 73%   |
|------------------|--|---|---|---|---|---|-----|--|----------------|-------|
| 131              | r circulation routes wide enough to safely and effectively late student movement?                            |   |   |   |   | 5 |     | Comments   | 0.50           | 2.50  |
| 1                | Very unsatisfactory - Primary circulation is 5'-0" to 6'-0"  |   |   |   |   |   |     | Corridors appear spacious and at least 10 feet wide.   |                |       |
|                  | wide   |   |   |   |   |   |     |  |                |       |
| 2                | Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide  |   |   |   |   |   |     |  |                |       |
| 3                | Average - Primary circulation is 7'-0" to 8'-0" wide   |   |   |   |   |   |     |  |                |       |
| 4                | Satisfactory - Primary circulation is 8'-0"-10'-0" wide  |   |   |   |   |   |     |  |                |       |
| 5                | Very satisfactory - Primary circulation is 10'-0"+ wide  |   |   |   |   |   |     |  |                |       |
| N/A              | Does not apply   |   |   |   |   |   |     |  |                |       |
| Are commu        | unity use areas arranged so that the school can allow night  |   |   |   | 4 |   |     | Comments   |                |       |
| 3.2 functions w  | vithout full school access?  |   |   |   | 4 |   |     | Comments   | 0.75           | 3.00  |
| 1                | Very unsatisfactory - Cafeteria, gym, and library cannot   |   |   |   |   |   |     | The cafeteria, band and orchestra spaces are able to   | be partitioned | d off |
|                  | be accessed after hours  |   |   |   |   |   |     | from the rest of the school, allowing for a designated | after-hours sp | ace.  |
| 2                | Unsatisfactory - Only one of the public spaces (Cafeteria,   |   |   |   |   |   |     |  |                |       |
|                  | Gym and Library) can be accessed from parking and  |   |   |   |   |   |     |  |                |       |
|                  | secured after hours  |   |   |   |   |   |     |  |                |       |
| 3                | Average - Only two of the public spaces can be accessed  |   |   |   |   |   |     |  |                |       |
| 4                | from parking and secured after hours Satisfactory - All of the public spaces can be accessed                 |   |   |   |   |   |     |  |                |       |
| 4                | from parking and secured from the rest of the building but   |   |   |   |   |   |     |  |                |       |
|                  | not individually   |   |   |   |   |   |     |  |                |       |
| 5                | Very satisfactory - Cafeteria, gym, and library can be   |   |   |   |   |   |     |  |                |       |
| Ĭ                | accessed from parking and locked off from rest of campus   |   |   |   |   |   |     |  |                |       |
|                  | for night/evening use with their own entrance  |   |   |   |   |   |     |  |                |       |
| N/A              | Does not apply   |   |   |   |   |   |     |  |                |       |
| ls there a c     | ommunity room that is a dedicated meeting space outside  |   |   |   |   |   |     |  |                |       |
| 3.3 of school fu | unction?   |   | 2 |   |   |   |     | Comments   | 0.75           | 1.50  |
| 1                | Very unsatisfactory - No dedicated community room  |   |   |   |   |   |     | This was not noted on the site visit.                  |                |       |
| 2                | Unsatisfactory - Community room but within school  |   |   |   |   |   |     |  |                |       |
|                  | function, no access after school hours   |   |   |   |   |   |     |  |                |       |
| 3                | Average - Community room, moderate size, but need  |   |   |   |   |   |     |  |                |       |
|                  | some renovations or updates to function wel  |   |   |   |   |   |     |  |                |       |
| 4                | Satisfactory - Community room, good size /layout, meets  |   |   |   |   |   |     |  |                |       |
| F                | needs /functions well  |   |   |   |   |   |     |  |                |       |
| 5                | Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school |   |   |   |   |   |     |  |                |       |
|                  | function   |   |   |   |   |   |     |  |                |       |
| N/A              | Does not apply   |   |   |   |   |   | J   |  |                |       |
| Does the g       | eneral appearance of the school convey pride for the   |   |   |   |   |   |     |  |                |       |
| 1 :X ZL -        | nd community?  |   |   |   |   | 5 |     | Comments   | 0.25           | 1.25  |
| <br>1            | Very unsatisfactory - General appearance is poor   |   |   |   |   |   |     | Building exterior and grounds look well-maintained.    |                |       |
| 2                | Unsatisfactory - General appearance is aged but ok   |   |   |   |   |   |     |  |                |       |
| 3                | Average - General appearance is good   |   |   |   |   |   |     |  |                |       |
| 4                | Satisfactory - General appearance shows pride in campus  |   |   |   |   |   |     |  |                |       |
|                  | and student works  |   |   |   |   |   |     |  |                |       |
| 5                | Very Unsatisfactory - General appearance shows pride in  |   |   |   |   |   |     |  |                |       |
|                  | campus and student works and is welcoming to the   |   |   |   |   |   |     |  |                |       |
| <b>N</b> 1/1     | community  |   |   |   |   |   |     |  |                |       |
| N/A              | Does not apply   |   |   |   |   |   |     |  |                |       |

| 4 - Security     |  | 1 2 | 2 ; | 3 4 | 5 | N/A |   | 16.25 |      |
|------------------|--|-----|-----|-----|---|-----|---|-------|------|
| 4.1 Does the fo  | acility have key card access at all major entries?   |     |     |     |   |     | Comments  | 0.25  |      |
| 1                | Very unsatisfactory - No entries   |     |     |     |   |     |   |       | ·    |
| 2                | Unsatisfactory - 1/4 of major entries  |     |     |     |   |     |   |       |      |
| 3                | Average - 1/2 of major entries   |     |     |     |   |     |   |       |      |
| 4                | Satisfactory - 3/4 of major entries  |     |     |     |   |     |   |       |      |
| 5                | Very satisfactory - All of major entries   |     |     |     |   |     |   |       |      |
| N/A              | Does not apply   | 1   |     |     |   |     |   |       |      |
| 4.2 How adequ    | uate is site lighting and security for the campus overall?   |     |     |     |   |     | Comments  | 1.00  |      |
| 1                | Very unsatisfactory - No exterior lighting, no secure perimeter  |     |     |     |   |     |   |       |      |
| 2                | Unsatisfactory - Lighting is limited to front entry only,<br>parking lot lighting poor, security is minimal            |     |     |     |   |     |   |       |      |
| 3                | Average - Lighting at all night-use entries and parking lot, but poor condition. Security is moderate                  |     |     |     |   |     |   |       |      |
| 4                | Satisfactory - Lighting at all night-use entries and parking   |     |     |     |   |     |   |       |      |
|                  | lots, good condition, signage less visible, perimeter is well secured but needs updates                                |     |     |     |   |     |   |       |      |
| 5                | Very satisfactory - Signage, parking lots, and entries are well lit, visible and easy to use, perimeter is very secure |     |     |     |   |     |   |       |      |
| N/A              | Does not apply   |     |     |     |   |     |   |       |      |
| Is the main      | office located at the school entry and configured with a   |     |     |     |   |     | _   |       |      |
| 1 4 3            | ibule to the main corridor?  |     |     |     |   |     | Comments  | 1.00  |      |
| 1                | Very unsatisfactory - No secure vestibule, office located  |     |     |     |   |     |   |       |      |
|                  | far from main entry, allows visitors access to school  |     |     |     |   |     |   |       |      |
|                  | unsupervised   |     |     |     |   |     |   |       |      |
| 2                | Unsatisfactory - No secure vestibule, office located   |     |     |     |   |     |   |       |      |
|                  | somewhat far from main entry, minimal supervision of   |     |     |     |   |     |   |       |      |
| 3                | visitors  Average - Office close to entry, views of front door, but no   |     |     |     |   |     |   |       |      |
| Ů                | secure vestibule   |     |     |     |   |     |   |       |      |
| 4                | Satisfactory - Office is well-located with a secure  |     |     |     |   |     |   |       |      |
|                  | vestibule, but needs updates   |     |     |     |   |     |   |       |      |
| 5                | Very satisfactory - Office well-located with secure  |     |     |     |   |     |   |       |      |
|                  | vestibule and all appropriate security features  |     |     |     |   |     |   |       |      |
| N/A              | Does not apply   |     |     |     |   |     |   |       |      |
| 4.4 Is there end | ough interior transparency for faculty to passively supervise  | 1   |     |     |   |     | Comments  |       |      |
| learners an      | nd their activities who are not in studios?  | '   |     |     |   |     | Comments  | 1.00  | 1.00 |
| 1                | Very unsatisfactory - No transparency of walls   |     |     |     |   |     | There is little to no visibility from studios to corridors. |       |      |
| 2                | Unsatisfactory - Limited transparency in certain locations   |     |     |     |   |     |   |       |      |
| 3                | Average - Good transparency in certain locations but   |     |     |     |   |     |   |       |      |
|                  | inadequate or missing in other locations of school   |     |     |     |   |     |   |       |      |
| 4                | Satisfactory - Adequate transparency throughout the  |     |     |     |   |     |   |       |      |
| -                | school   |     |     |     |   |     |   |       |      |
| 5                | Very satisfactory - Excellent transparency throughout the school   |     |     |     |   |     |   |       |      |
| N/A              | Does not apply   |     |     |     |   |     |   |       |      |
| ,                |  |     |     |     |   |     |   |       |      |

|   | 5 - Environmer               | ital Quality   | 1 | 2 | 3 | 4 | 5 | N/A |   | 25.00 | 60%  |
|---|------------------------------|--|---|---|---|---|---|-----|---|-------|------|
|   | 5.1 How are ac               | coustics in studios in general?  |   | 2 |   |   |   |     | Comments  | 1.00  | 2.00 |
| L | 1 2 3 4 5 N/A                | Very unsatisfactory - Recognized word/sound from adjacent studio/corridor Unsatisfactory - Audible sound from adjacent studio/corridor Average - Slight sound from outside room Satisfactory - Walls to deck insulated only white noise from mechanical system Very satisfactory - Able to hear quiet speaking from across the room Does not apply     | • |   |   |   |   |     | Studio wall acoustics are good but AC is loud.      |       |      |
|   | 5.2 Is the studio            | o artificial lighting adequate quality?  |   | 2 |   |   |   |     | Comments  | 1.00  | 2.00 |
| L | 1<br>2<br>3<br>4<br>5<br>N/A | Very unsatisfactory - Sporadic lights work, glare, less than<br>20 FC<br>Unsatisfactory - 10-19 FC or serious glare<br>Average- 20-29 FC minor glare<br>Satisfactory - 30-39 FC and no glare<br>Very satisfactory - 40+ FC and no glare<br>Does not apply  |   |   |   | • |   |     | Light quality appears to be below standard.         |       |      |
|   | 5.3 Is there acc             | ess to natural light in studios?   |   |   | 3 |   |   |     | Comments  | 1.00  | 3.00 |
| L | 1<br>2<br>3<br>4<br>5        | Very unsatisfactory - No learning spaces have natural light Unsatisfactory - 1-25% of learning spaces have natural light or windows are too small to let in light Average - 26-50% of learning spaces have natural light Satisfactory - 51-75% of learning spaces have natural light Very satisfactory - 76-100% of learning spaces have natural light |   |   |   |   |   |     | Studios have windows but other learning areas do no | ot.   |      |
| ſ | N/A                          | Does not apply   | I | 1 | I | l | I |     | T   |       |      |
|   | 5.4 Is there acc             | ess to outside views from learning spaces?   |   |   | 3 |   |   |     | Comments  | 1.00  | 3.00 |
|   | 1<br>2<br>3<br>4<br>5        | Very unsatisfactory - No learning spaces have views Unsatisfactory - 1-25% of learning spaces have views or windows are too small to see out Average - 26-50% of learning spaces have views Satisfactory - 51-75% of learning spaces have views Very satisfactory - 76-100% of learning spaces have views  |   |   |   |   |   |     | Views are standard.                                 |       |      |
|   | N/A                          | Does not apply   |   |   |   |   |   |     |   |       |      |

| 5 | - Environme     | ntal Quality (cont.)                                      | 1 | 2 | 3 | 4 | 5 | N/A | 1   |       |      |
|---|-----------------|---|---|---|---|---|---|-----|---|-------|------|
|   | 5.5 Does the b  | uilding have odor or pest problems?                       |   |   |   |   | 5 |     | Comments  | 1.00  | 5.00 |
|   | 1               | Very unsatisfactory - Evidence of both pests and odors    |   |   |   |   |   |     | No evidence of odors or pests.                        |       |      |
|   | 2               | Unsatisfactory - Evidence of pests or odors               |   |   |   |   |   |     |   |       |      |
|   | 3               | Average - Limited evidence of pests, no odors             |   |   |   |   |   |     |   |       |      |
|   | 4               | Satisfactory - No evidence of pests / odors, school       |   |   |   |   |   |     |   |       |      |
|   |                 | cleanliness in good condition                             |   |   |   |   |   |     |   |       |      |
|   | 5               | Very Satisfactory - No evidence, school cleanliness in    |   |   |   |   |   |     |   |       |      |
|   |                 | excellent condition                                       |   |   |   |   |   |     |   |       |      |
|   | N/A             | Does not apply  |   |   |   |   |   |     |   |       |      |
| 6 | - Controllabi   | ility of Systems  | 1 | 2 | 3 | 4 | 5 | N/A | A   | 12.50 | 52%  |
|   | 6.1 Does the st | tudio thermostat allow for individual control?            |   |   |   |   | 5 |     | Comments  | 0.50  | 2.50 |
|   | 1               | No  |   |   |   |   |   |     |   |       |      |
|   | 5               | Yes   |   |   |   |   |   |     |   |       |      |
|   | 6.2 Are shades  | s provided to control natural light in learning spaces?   |   | 2 |   |   |   |     | Comments  | 1.00  | 2.00 |
|   | 1               | Very unsatisfactory - No, windows are covered with        |   |   |   |   |   |     | Many studios do not have light control via blinds/sha | ides. |      |
|   | _               | boards/paper  |   |   |   |   |   |     |   |       |      |
|   | 2               | Unsatisfactory - No, windows have no light control        |   |   |   |   |   |     |   |       |      |
|   | 3               | Average - Yes, but poor condition blinds                  |   |   |   |   |   |     |   |       |      |
|   | 4               | Satisfactory - Yes, blinds                                |   |   |   |   |   |     |   |       |      |
|   | 5               | Very satisfactory - Blackout shades                       |   |   |   |   |   |     |   |       |      |
| _ | N/A             | Does not apply  |   |   |   |   | 1 |     | 1   |       |      |
| , | 6.3 What is the | e quality of lighting controls in the studios?            |   | 2 |   |   |   |     | Comments  | 1.00  | 2.00 |
|   | 1               | Very unsatisfactory - Single switch only per room         |   |   |   |   |   |     | Double switch for alternating light control.          |       |      |
|   | 2               | Unsatisfactory - Alternating rows switch off              |   |   |   |   |   |     |   |       |      |
|   | 3               | Average - Alternating lamps in single fixtures switch off |   |   |   |   |   |     |   |       |      |
|   | 4               | Satisfactory - Tri level switching                        |   |   |   |   |   |     |   |       |      |
|   | 5               | Very satisfactory - Dimmable                              |   |   |   |   |   |     |   |       |      |
|   | N/A             | Does not apply  |   |   |   |   |   |     |   |       |      |

| 7 - F | urniture, F           | ixtures & Equipment  | 1 | 2 | 3 | 4 | 5 | N/A |   | 18.75           | 64%  |
|-------|-----------------------|--|---|---|---|---|---|-----|---|-----------------|------|
| 7.1   | What is the           | current condition of the furniture?  |   |   |   | 4 |   |     | Comments  | 0.75            | 3.00 |
|       | 1<br>2<br>3<br>4<br>5 | Very unsatisfactory - Damaged or broken, non-<br>functioning<br>Unsatisfactory - Torn/ bent/ wrong size<br>Average - Scratched/dented/marked<br>Satisfactory - Not new, but sturdy and clean |   |   |   |   |   |     | Furniture appears sturdy and clean.                       |                 |      |
|       | N/A                   | Very satisfactory - New  Does not apply  |   |   |   |   |   |     |   |                 |      |
| 7.2   | Are a varie           | ty of furniture types being accommodated throughout the urning commons, dining commons, other multi-use spaces?  |   | 2 |   |   |   |     | Comments  | 1.00            | 2.00 |
|       | 1                     | Very Unsatisfactory - Same furniture used in all spaces  |   |   |   |   |   |     | Very little variety.                                      |                 |      |
|       | 2                     | Unsatisfactory - Furniture variety in one multi-use space  |   |   |   |   |   |     |   |                 |      |
|       | 3                     | Average - Furniture variety in more than one multi-use space   |   |   |   |   |   |     |   |                 |      |
|       | 4                     | Satisfactory - All multi-use spaces have greater than one type of furniture  |   |   |   |   |   |     |   |                 |      |
|       | 5                     | Very satisfactory - All multi-use spaces have greater than two types of furniture  |   |   |   |   |   |     |   |                 |      |
|       | N/A                   | Does not apply   | 1 |   |   |   |   |     |   |                 |      |
| 7.3   | How well d space?     | oes furniture accommodate rapid reconfiguration of a   |   |   | 3 |   |   |     | Comments  | 1.00            | 3.00 |
|       | 1<br>2                | Very Unsatisfactory - Furniture is fixed or very heavy<br>Unsatisfactory - Furniture does not allow desks to be<br>configured as individuals, small groups, or large groups                  |   |   |   |   |   |     | Cafeteria furniture is not flexible. Studios have desks v | with loose chai | irs. |
|       | 3                     | Average - Mix of furniture that can reconfigure but is<br>cumbersome to move<br>Satisfactory - Furniture is flexible for multiple  |   |   |   |   |   |     |   |                 |      |
|       | 5                     | configurations of space  Very satisfactory - Furniture is flexible for multiple configurations of space, easy to move and stack  |   |   |   |   |   |     |   |                 |      |
|       | N/A                   | Does not apply   |   |   |   |   |   |     |   |                 |      |
| 7.4   | ls the furnit         | rure ergonomic and size appropriate for grade level?   |   |   |   | 4 |   |     | Comments  | 1.00            | 4.00 |
|       | 1                     | Very unsatisfactory - Desk with attached chair combinations too small for grade leve   |   |   |   |   |   |     | Tables with loose chairs were observed.                   |                 |      |
|       | 2                     | Unsatisfactory - Desk with attached chair combinations   |   |   |   |   |   |     |   |                 |      |
|       | 3                     | Average - Mix of studios with tables/loose chairs and desks with fixed seats   |   |   |   |   |   |     |   |                 |      |
|       | 4                     | Very satisfactory - Tables with loose chairs   |   |   |   |   |   |     |   |                 |      |
|       | 5                     | Very satisfactory - Tables with loose chairs that allow students to be active  |   |   |   |   |   |     |   |                 |      |
|       | N/A                   | Does not apply   |   |   |   |   |   |     |   |                 |      |

| o Waste   | 1 | 2 | 3 | 4 | 5 | N/A | 5.0  | )   | 30% |
|---|---|---|---|---|---|-----|--|-----|-----|
| Do studios and corridors have blue recycle bins with bilingual instructions and/or image sorting instructions?  |   | 2 |   |   |   |     | Comments 0.5   | )   | 1.0 |
| 1 Very unsatisfactory - There are no recycling and landfill bins and signage are sparse or infrequent, OR there are only landfill bins with no recycling bins. 2 Unsatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage. 3 Average - 50% of corridors and studios have both a landfill bin and a recycle bin in an accessible location. The containers have clear signage. 4 Satisfactory - 75% of studios and corridors have a visible landfill and recycle collection containers in an accessible location. The containers have clear signage. 5 Very satisfactory - All studios / corridors (100%) have visible landfill and recycle collection containers in accessible locations. The containers have clear signage, and the style and format is consistent and uniform across campus.  N/A Does not apply |   |   |   |   |   |     | A score for this category is being recorded, but this category is calculated in the overall ESA average.  No bilingual signage.                                  | not |     |
| Does the cafeteria (or wherever meals are served) have at least one of each: green compost bin, blue recycle bin, and landfill bin? Are the bins labelled clearly with bilingual and/or image sorting?  | 1 |   |   |   |   |     | Comments 0.5   | n   | 0.5 |
| 1 Very unsatisfactory- There may be landfill bins, but there are no compost and/or recycle bins. There is not clear sorting signage. 2 Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located next to one another. Signage is absent or inconsistent. 3 Average- There is at least one waste station with all three bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and consistent. 4 Satisfactory- There are several waste stations as described above 5 Very Satisfactory - There are several waste stations as described above, and additional signage in the cafeteria   |   |   |   |   |   |     | A score for this category is being recorded, but this category is calculated in the overall ESA average.  No bins were in the cafeteria at the time of the walk. | not |     |



# **Austin ISD Educational Suitability Assessment Criteria**

Academics - Middle School / High School

| School No               | ame   |   |   |   |   |   |     | Walk Attendees:                                    | Date:              |      |
|-------------------------|---|---|---|---|---|---|-----|--|--------------------|------|
| Bailey MS               | 3   |   |   |   |   | - |     | Angela Whitaker-Williams & Lane Green              | 12/15/2            | 20   |
| 8 - Academics           | & Learning  | 1 | 2 | 3 | 4 | 5 | N/A | 4  | 65.00              | 46%  |
| 8.1 Are studios         | s appropriately configured per the ed spec?   |   | 2 |   |   |   |     | Comments   | 1.00               | 2.00 |
| 2                       | Very unsatisfactory - Too small, no flexibility,<br>disconnected<br>Unsatisfactory - Too small, only one area for all teaching<br>methods, limited flexibility, disconnected  | ı | • | • |   | ı |     | Studios have no transparency and are set up for li | mited flexibility. |      |
| 3                       | Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.                 |   |   |   |   |   |     |  |                    |      |
| 4                       | Satisfactory - Good size, multiple areas for different<br>teaching methods, good flexibility, good transparency<br>and connection to other studios and shared learning<br>spaces  |   |   |   |   |   |     |  |                    |      |
| 5                       | Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces |   |   |   |   |   |     |  |                    |      |
| N/A                     | Does not apply  |   |   |   |   |   |     |  |                    |      |
| 8.2 Do studios ed spec? | have appropriate support spaces such as storage per the   | 1 |   |   |   |   |     | Comments   | 1.00               | 1.00 |
| 1                       | Very unsatisfactory - None provided   |   |   |   |   |   |     | Little to no storage is provided within studios.   |                    |      |
| 2                       | Unsatisfactory - Too small, disconnected, poor condition  |   |   |   |   |   |     |  |                    |      |
| 3                       | Neutral - Adequate size, average condition, needs updates or renovations to function well   |   |   |   |   |   |     |  |                    |      |
| 4                       | Satisfactory - Good size, connected, good condition   |   |   |   |   |   |     |  |                    |      |
| 5                       | Very Satisfactory - Generous size, connected, excellent condition   |   |   |   |   |   |     |  |                    |      |
| N/A                     | Does not apply  |   |   |   |   |   |     |  |                    |      |

Perkins&Will 02/11/2022 <sup>2</sup>

| 8 - 1    | Academics    | & Learning (cont.)   | 1 | 2        | 3 | 4 | 5 | N/A |  |      |      |
|----------|--------------|--|---|----------|---|---|---|-----|--|------|------|
| 8.3      | Do typical I | earning neighborhoods have small and medium (high  | 1 |          |   |   |   |     | Comments   |      |      |
| 8.3      | school only  | ) group rooms and open collaboration space?  | ı |          |   |   |   |     | Comments   | 1.00 | 1.00 |
|          | 1            | Very unsatisfactory - No breakout rooms or open  |   |          |   |   |   |     |  |      |      |
|          |              | collaboration spaces are provided  |   |          |   |   |   |     |  |      |      |
|          | 2            | Unsatisfactory - Too small or too few, poor condition, no                                  |   |          |   |   |   |     |  |      |      |
|          |              | flexibility, lacks visual connection to learning   |   |          |   |   |   |     |  |      |      |
|          |              | neighborhood, poor acoustic privacy  |   |          |   |   |   |     |  |      |      |
|          | 3            | Average - Adequate size, adequate condition, needs   |   |          |   |   |   |     |  |      |      |
|          |              | some renovations or updates to function well   |   |          |   |   |   |     |  |      |      |
|          | 4            | Satisfactory - Good size, good condition and flexibility,                                  |   |          |   |   |   |     |  |      |      |
|          |              | transparency and connection to learning neighborhood,                                      |   |          |   |   |   |     |  |      |      |
|          |              | acoustic privacy   |   |          |   |   |   |     |  |      |      |
|          | 5            | Very Satisfactory - Generous size, excellent condition and                                 |   |          |   |   |   |     |  |      |      |
|          |              | flexibility, transparency and connection to learning                                       |   |          |   |   |   |     |  |      |      |
|          |              | neighborhood, acoustic privacy   |   |          |   |   |   |     |  |      |      |
|          | N/A          | Does not apply   |   |          |   |   |   |     |  |      |      |
| 8.4      |              | e Labs and support spaces appropriately configured per                                     |   |          |   | 4 |   |     | Comments   |      |      |
| <u> </u> | the ed spec  |  |   |          |   |   |   |     |  | 1.00 | 4.00 |
|          | 1            | Very unsatisfactory - No dedicated science room  |   |          |   |   |   |     | Science labs need power and technology upgrades. |      |      |
|          | 2            | Unsatisfactory - Too small, poor condition, no connected                                   |   |          |   |   |   |     |  |      |      |
|          |              | support space  |   |          |   |   |   |     |  |      |      |
|          | 3            | Average - Adequate size, adequate condition, needs   |   |          |   |   |   |     |  |      |      |
|          |              | some renovations or updates to function well   |   |          |   |   |   |     |  |      |      |
|          | 4            | Satisfactory - Good size, good condition, connected  |   |          |   |   |   |     |  |      |      |
|          | _            | support spaces   |   |          |   |   |   |     |  |      |      |
|          | 5            | Very Satisfactory - Generous size, excellent condition,                                    |   |          |   |   |   |     |  |      |      |
|          | N/A          | connected support spaces  Does not apply   |   |          |   |   |   |     |  |      |      |
|          |              | ,  |   | 1        |   |   |   |     |  |      |      |
| 8.5      |              | Spaces and support spaces appropriately configured per c? (cross reference with CTE below) |   | 2        |   |   |   |     | Comments   | 1.00 | 2.00 |
|          | ı ı          | · · · · · · · · · · · · · · · · · · ·  |   | <u> </u> |   |   |   |     | Niek weg end en ee                               | 1.00 | 2.00 |
|          | 0            | Very unsatisfactory - No dedicated maker spaces  |   |          |   |   |   |     | Not per ed spec                                  |      |      |
|          | 2            | Unsatisfactory - Too small, poor condition, disconnected                                   |   |          |   |   |   |     |  |      |      |
|          | 3            | from learning spaces, no flexibility  Average - Adequate size, adequate condition, needs   |   |          |   |   |   |     |  |      |      |
|          | 3            | some renovations or updates to function well   |   |          |   |   |   |     |  |      |      |
|          | 4            | Satisfactory - Good size, good condition, connected to                                     |   |          |   |   |   |     |  |      |      |
|          | 4            | learning spaces  |   |          |   |   |   |     |  |      |      |
|          | 5            | Very Satisfactory - Generous size, excellent condition,                                    |   |          |   |   |   |     |  |      |      |
|          | 3            | connected to learning spaces   |   |          |   |   |   |     |  |      |      |
|          | N/A          | Does not apply   |   |          |   |   |   |     |  |      |      |

Perkins&Will 02/11/2022 <sup>3</sup>

| 8 - Academics & Learning (cont.)  | 1        | 2 | 3        | 4 | 5 | N/A | Ą  |                  |      |
|---|----------|---|----------|---|---|-----|--|------------------|------|
| 8.6 Is there a Professional Learning Center in the learning neighborhood?   | 1        |   |          |   |   |     | Comments   | 1.00             | 1.00 |
| Very unsatisfactory - No dedicated space for     Professional Learning Center                                     |          |   |          |   |   |     | None noted.  |                  |      |
| <ol> <li>Unsatisfactory - Too small, poor condition, disconnected</li> </ol>                                      |          |   |          |   |   |     |  |                  |      |
| 3 Average - Adequate size, adequate condition, needs  |          |   |          |   |   |     |  |                  |      |
| some renovations or updates to function well  |          |   |          |   |   |     |  |                  |      |
| 4 Satisfactory - Good size, good condition, connected   |          |   |          |   |   |     |  |                  |      |
| 5 Very Satisfactory - Generous size, excellent condition,   |          |   |          |   |   |     |  |                  |      |
| connected   |          |   |          | 1 |   |     |  |                  |      |
| Are there adequate places to display the evidence and artifacts of  |          |   |          |   | 5 |     | Comments   |                  |      |
| learning (both 2D and 3D)?  | <u> </u> |   |          |   |   |     |  | 1.00             | 5.00 |
| 1 Very unsatisfactory - No dedicated space  |          |   |          |   |   |     | Many display areas were noted throughout the buildi    | ng.              |      |
| Unsatisfactory - Too small, non-dedicated, poor   |          |   |          |   |   |     |  |                  |      |
| condition  3 Average - Adequate size, adequate condition, needs   |          |   |          |   |   |     |  |                  |      |
| updates or renovations to function well   |          |   |          |   |   |     |  |                  |      |
| 4 Satisfactory - Good size, good condition  |          |   |          |   |   |     |  |                  |      |
| 5 Very Satisfactory - Generous size, excellent condition  |          |   |          |   |   |     |  |                  |      |
| N/A Does not apply  |          |   |          |   |   |     |  |                  |      |
| Does the building / learning neighborhood provide adequate  |          |   |          |   |   |     |  |                  |      |
| 8.8 opportunities for students/teachers to collaborate in varying group   | 1        |   |          |   |   |     | Comments   |                  |      |
| sizes?  |          |   |          |   |   |     |  | 1.00             | 1.00 |
| Very unsatisfactory - No space to support collaboration   |          |   | <u> </u> | 1 |   |     | No; studios are contained and located off of corridor. |                  |      |
| in various sizes.   |          |   |          |   |   |     |  |                  |      |
| 2 Unsatisfactory - Too small, inflexible, only one option,  |          |   |          |   |   |     |  |                  |      |
| does not support a variety of group sizes   |          |   |          |   |   |     |  |                  |      |
| 3 Average - Adequate space for collaboration, needs   |          |   |          |   |   |     |  |                  |      |
| updates or renovations to function well.  |          |   |          |   |   |     |  |                  |      |
| 4 Satisfactory - Good size, good condition, multiple options  |          |   |          |   |   |     |  |                  |      |
| to support a variety of group sizes  5 Very Satisfactory - Generous size, excellent condition.                    |          |   |          |   |   |     |  |                  |      |
| 5 Very Satisfactory - Generous size, excellent condition,<br>multiple options to support a variety of group sizes |          |   |          |   |   |     |  |                  |      |
| N/A Does not apply  |          |   |          |   |   |     | <u> </u>   |                  |      |
| ,   |          |   |          |   |   |     |  |                  |      |
| 8.9 Does the building provide opportunities for informal interaction?   |          | 2 |          |   |   |     | Comments   | 1.00             | 2.00 |
| 1 Very unsatisfactory - No space  |          |   |          |   |   |     | Best collaboration area is in the student commons, wh  | nich is not near |      |
| <ol> <li>Unsatisfactory - Too small, poor condition, layout and</li> </ol>  |          |   |          |   |   |     | studios.   |                  |      |
| furnishings do not support informal interaction well  |          |   |          |   |   |     |  |                  |      |
| Average - Adequate size and condition, needs updates  |          |   |          |   |   |     |  |                  |      |
| or renovations to function well.  |          |   |          |   |   |     |  |                  |      |
| 4 Satisfactory - Good size, good condition, layout and furnishings support informal interactions                  |          |   |          |   |   |     |  |                  |      |
| 5 Very Satisfactory - Generous size, excellent condition,   |          |   |          |   |   |     |  |                  |      |
| layout and furnishings support informal interactions  |          |   |          |   |   |     |  |                  |      |
| N/A Does not apply  |          |   |          |   |   |     |  |                  |      |

| 8 - A | caaemics a         | k Learning (cont.)  | - 1 | 2 | 3 | 4 |   | 5 | N/A |  |                  |      |
|-------|--------------------|---|-----|---|---|---|---|---|-----|--|------------------|------|
| 8.10  | Does the bu        | uilding provide adequate opportunities for students to endently?  | 1   |   |   |   |   |   |     | Comments   | 1.00             | 1.00 |
|       | 1<br>2<br>3<br>4   | Very unsatisfactory - No breakout rooms/small study spaces Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood Average - Adequate size and condition, needs updates or renovations to function well. Satisfactory - Good size and condition, acoustic privacy,  |     |   |   |   |   | 1 |     | No independent work areas are available.                                     |                  |      |
|       | 5<br>N/A           | variety of independent work space options, connected to learning neighborhood  Very Satisfactory - Generous size, excellent condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood  Does not apply  |     |   |   |   |   |   |     |  |                  |      |
|       | Special Edu        | cation  |     |   |   |   |   |   |     |  |                  |      |
| 8.11  | •                  | Education spaces appropriately configured per the ed  |     |   | 3 |   |   |   |     | Comments   | 1.00             | 3.00 |
|       | 1<br>2<br>3<br>4   | Very unsatisfactory - Too small, no flexibility, disconnected  Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected  Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.  Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces  Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces |     |   |   |   |   |   |     | Special education is not located with studio spaces; it administration wing. | t is adjacent to | the  |
| 8.12  | N/A<br>Are Special | Does not apply Education support spaces, such as storage, space for   |     | 2 |   |   | T |   |     | Comments   |                  |      |
| 0.12  | washer/dry         | er, appropriately configured per the ed spec?   |     |   |   |   |   |   |     | Comments   | 1.00             | 2.00 |
|       | 1                  | Very unsatisfactory - None provided   |     |   |   |   |   |   |     | Storage is lacking and no washer and dryer are avail                         | · ·              | ıs,  |
|       | 2<br>3<br>4<br>5   | Unsatisfactory - Too small, disconnected, poor condition Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent condition  |     |   |   |   |   |   |     | washer / dryer shown in room 123, but was not obsert assessment walk.)       | ved during       |      |
|       | N/A                | Does not apply  |     |   |   |   |   |   |     |  |                  |      |

**Perkins&Will** 02/11/2022 <sup>5</sup>

| 8 - Academics                | & Learning (cont.)   | 1 | 2 | 2 3 | 4 | 5 | N/A | l e e e e e e e e e e e e e e e e e e e                |        |      |
|------------------------------|--|---|---|-----|---|---|-----|--|--------|------|
| N 1.3                        | ible restrooms and changing rooms readily available to the ucation spaces?   |   |   |     |   | 5 |     | Comments   | 1.00   | 5.00 |
| 1 -                          | No   |   |   |     |   |   |     | The area also has a nice accessible shower.            |        |      |
| 5<br>STEAM Cei               | Yes  |   |   |     |   |   |     |  |        |      |
|                              | ampus have space to support a "STEAM" center?  | 1 |   |     |   |   |     | Comments   | 0.00   | 0.00 |
| 1<br>2<br>3<br>4<br>5        | Very unsatisfactory - No available space for STEAM center and inadequate studio / collaborative space Unsatisfactory - Collaborative areas / studios for CTE/CCL are completely separate but adequate size Neutral - Collaborative areas / studios for CTE/CCL are adjacent but function separately Satisfactory - Collaborative areas / studios for CTE/CCL function and have space availability to create STEAM center  Very Satisfactory - Functioning STEAM center offers studios, labs, common collaborative areas to support multimedia distance and hands-on project based learning |   |   |     |   |   |     | Monitoring answer, but does not count toward overc     |        | 0.00 |
| N/A 9 - CTF and Ca           | Does not apply  reer Connected Learning  |   |   |     |   |   |     |  | 17.50  | 60%  |
| O 1 How close                | is your campus to a CTE cluster pathway that is aligned CTE programs (Middle School only)?   |   |   |     | 4 |   |     | Comments   | 1.00   | 4.00 |
| 1<br>2<br>3<br>4<br>5<br>N/A | Very unsatisfactory - No correlation to CTE cluster pathway, no CTE programs.  Unsatisfactory - School supports less than half of the CTE programs that are listed in the cluster pathway.  Average - School support half of CTE programs listed in the cluster pathway, but missing some.  Satisfactory - School support a majority of CTE programs listed in the CTE cluster pathway.  Very Satisfactory - School is aligned with CTE cluster pathway.  Does not apply   |   |   |     |   |   |     | Feeder splits to two high schools, so not all programs | align. |      |
| Do campus                    | s facilities align with the CTE Ed Spec Requirements for the thways offered?: Architecture and Construction  |   |   |     |   | 5 |     |  | 0.25   | 1.25 |
| 1<br>5<br>N/A                | No<br>Yes<br>Does not apply  |   |   |     |   |   |     |  |        |      |
| 9.3 Arts, Audio              | and Video Technology and Communications  |   |   |     |   | 5 |     |  | 0.25   | 1.25 |
| 9.4 Business, M              | Management and Administration  | 1 |   |     |   |   |     |  | 0.25   | 0.25 |
| 9.5 Education                | and Training   | 1 |   |     |   |   |     |  | 0.25   | 0.25 |
| 9.6 Health Scie              | ence   | 1 |   |     |   |   |     |  | 0.25   | 0.25 |

| 9 - CTE and Career Connected Learning (cont.)  | 1 | - 2 | 2 3 | 4 | 5 | N/A |   |               |             |
|--|---|-----|-----|---|---|-----|---|---------------|-------------|
| 9.7 Hospitality and Tourism  |   |     |     |   | 5 |     |   | 0.25          | 1.25        |
| 9.8 Human Services (high school only)  |   |     |     |   |   | N/A |   | 0.00          | 0.00        |
| 9.9 Information Technology   | 1 |     |     |   |   |     |   | 0.25          | 0.25        |
| 9.10 Agriculture, Food and Natural Resources   |   |     |     |   | 5 |     |   | 0.25          | 1.25        |
| 9.11 Science, Technology, Engineering, and Mathematics   | 1 |     |     |   |   |     |   | 0.25          | 0.25        |
| 9.12 Transportation, Distribution and Logistics  | 1 |     |     |   |   |     |   | 0.25          | 0.25        |
| 9.13 Finance (high school only)  |   |     |     |   |   | N/A |   | 0.00          | 0.00        |
| 9.14 Government and Public Administration / JROTC Military programs (high school only)   |   |     |     |   |   | N/A |   | 0.00          | 0.00        |
| 9.15 Law, Public Safety, Corrections and Security (high school only)   |   |     |     |   |   | N/A |   | 0.00          | 0.00        |
| 9.16 Manufacturing (high school only)  |   |     |     |   |   | N/A |   | 0.00          | 0.00        |
| 9.17 Marketing, Sales and Services (high school only)  |   |     |     |   |   | N/A |   | 0.00          | 0.00        |
| 10 - Visual and Performing Arts  |   |     |     |   |   |     |   | 0.00<br>35.00 | 0.00<br>37% |
| 10.1 Is there flexibility of space to also be used by CTE and Athletics?   |   |     |     |   | 5 |     | Comments  |               |             |
|  |   |     |     |   | 5 |     | Comments  | 0.00          | 0.00        |
| 1 No   |   |     |     |   |   |     | Monitoring answer, but doesn't affect overall score.  |               |             |
| 5 Yes  |   |     |     |   |   |     |   |               |             |
| 5 Yes  10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec?  |   | 1   | 2   | Τ |   |     | Comments  | 1.00          | 2.00        |
| Are band and support spaces (rehearsal and storage) appropriately  |   | 4   | 2   |   |   |     | Band is too small for size of program. Space lacks ade  |               |             |
| 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec?  1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition   |   | 2   | 2   |   |   |     |   |               |             |
| 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec?  1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs  |   | 4   | 2   |   |   |     | Band is too small for size of program. Space lacks ade  |               |             |
| 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec?  1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well.   |   | 2   | 2   |   |   |     | Band is too small for size of program. Space lacks ade  |               |             |
| 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec?  1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well.   |   |     | 2   |   |   |     | Band is too small for size of program. Space lacks ade  |               |             |
| 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec?  1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply  |   |     | 2   |   |   |     | Band is too small for size of program. Space lacks ade  |               |             |
| 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec?  1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply  10.3 Are orchestra and support spaces appropriately configured per the  |   |     | 2   |   |   |     | Band is too small for size of program. Space lacks ade  | equate storag | e and       |
| 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec?  1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply  |   |     |     |   |   |     | Band is too small for size of program. Space lacks add acoustics.   | equate storag | e and       |
| 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec?  1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply  10.3 Are orchestra and support spaces appropriately configured per the ed spec?   |   |     |     |   |   |     | Band is too small for size of program. Space lacks add acoustics.  Comments   | equate storag | e and       |
| 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec?  1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply  10.3 Are orchestra and support spaces appropriately configured per the ed spec?  1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs  |   |     |     |   |   |     | Band is too small for size of program. Space lacks add acoustics.  Comments  Orchestra is too small for size of program. Space lack | equate storag | e and       |
| 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec?  1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply  10.3 Are orchestra and support spaces appropriately configured per the ed spec?  1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. |   |     |     |   |   |     | Band is too small for size of program. Space lacks add acoustics.  Comments  Orchestra is too small for size of program. Space lack | equate storag | e and       |
| 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec?  1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply  10.3 Are orchestra and support spaces appropriately configured per the ed spec?  1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs  |   |     |     |   |   |     | Band is too small for size of program. Space lacks add acoustics.  Comments  Orchestra is too small for size of program. Space lack | equate storag | e and       |

|      |                          | Performing Arts (cont.)   | 1 | 2 | 3 | 4        | 5 | N/A |  |              |       |
|------|--------------------------|---|---|---|---|----------|---|-----|--|--------------|-------|
| () 4 | Are choir ar<br>spec?    | nd support spaces appropriately configured per the ed                 | 1 |   |   |          |   |     | Comments   | 1.00         | 1.0   |
|      | 1                        | Very unsatisfactory - Too small, missing program spaces               |   |   |   |          |   |     | Choir is taught in a general studio with parent-built rise | ers and no a | coust |
|      | 2                        | Unsatisfactory - Too small, poor condition                            |   |   |   |          |   |     | storage or office.   |              |       |
|      | 3                        | Neutral - Adequate size, adequate condition, needs                    |   |   |   |          |   |     |  |              |       |
|      |                          | updates or renovations to function well.                              |   |   |   |          |   |     |  |              |       |
|      | 4                        | Satisfactory - Good size, good condition                              |   |   |   |          |   |     |  |              |       |
|      | 5                        | Very Satisfactory - Generous size, excellent condition                |   |   |   |          |   |     |  |              |       |
|      | N/A                      | Does not apply  |   |   |   | 1        | 1 |     |  |              |       |
| 05   | spec?                    | and support spaces appropriately configured per the ed                | 1 |   |   |          |   |     | Comments   | 1.00         | 1.    |
|      | 1                        | Very unsatisfactory - Too small, missing program spaces               |   |   |   |          |   |     | In a portable.   |              |       |
|      | 2                        | Unsatisfactory - Too small, poor condition                            |   |   |   |          |   |     |  |              |       |
|      | 3                        | Neutral - Adequate size, adequate condition, needs                    |   |   |   |          |   |     |  |              |       |
|      |                          | updates or renovations to function well.                              |   |   |   |          |   |     |  |              |       |
|      | 4                        | Satisfactory - Good size, good condition                              |   |   |   |          |   |     |  |              |       |
|      | 5<br>N/A                 | Very Satisfactory - Generous size, excellent condition                |   |   |   |          |   |     |  |              |       |
|      | •                        | Does not apply and support spaces appropriately configured per the ed |   |   |   | Τ        |   |     |  |              |       |
| () 6 | spec?                    | und support spaces appropriately configured per tile ed               |   | 2 |   |          |   |     | Comments   | 1.00         | 2     |
|      | 1                        | Very unsatisfactory - Too small, missing program spaces               |   |   | ı | <u> </u> | 1 |     | Theater space appears small with little to no storage.     |              |       |
|      | 2                        | Unsatisfactory - Too small, poor condition                            |   |   |   |          |   |     |  |              |       |
|      | 3                        | Neutral - Adequate size, adequate condition, needs                    |   |   |   |          |   |     |  |              |       |
|      |                          | updates or renovations to function well.                              |   |   |   |          |   |     |  |              |       |
|      | 4                        | Satisfactory - Good size, good condition                              |   |   |   |          |   |     |  |              |       |
|      | 5                        | Very Satisfactory - Generous size, excellent condition                |   |   |   |          |   |     |  |              |       |
|      | N/A                      | Does not apply  | 1 |   |   |          |   |     |  |              |       |
| ()/  | Are visual a<br>ed spec? | rts and support spaces appropriately configured per the               |   |   |   | 4        |   |     | Comments   | 1.00         | 4.    |
|      | 1                        | Very unsatisfactory - Too small, missing program spaces               |   |   |   |          |   |     | Visual art spaces appear to meet Ed Spec.                  |              |       |
|      | 2                        | Unsatisfactory - Too small, poor condition                            |   |   |   |          |   |     |  |              |       |
|      | 3                        | Neutral - Adequate size, adequate condition, needs                    |   |   |   |          |   |     |  |              |       |
|      |                          | updates or renovations to function well.                              |   |   |   |          |   |     |  |              |       |
|      | 4                        | Satisfactory - Good size, good condition                              |   |   |   |          |   |     |  |              |       |
|      | 5                        | Very Satisfactory - Generous size, excellent condition                |   |   |   |          |   |     |  |              |       |
|      | N/A                      | Does not apply  |   |   |   |          |   |     | T  |              |       |
|      | Does the ca              | mpus have adequate space for the specialty arts                       | 1 |   |   |          |   |     | Community  |              |       |
| Λo.' | orograms (E              | Ensemble, Guitar, Music studies, Music theory and Piano)?             |   |   |   |          |   |     | Comments   | 1.00         |       |
|      |                          |   |   |   |   |          |   |     |  |              |       |
|      | 1                        | No  |   |   |   |          |   |     |  | 1.00         | 1.    |

Perkins&Will 02/11/2022 <sup>8</sup>

| 11 - Athletics and              | Wellness   |   |   |   |   |  | 18.75 | 73%  |
|---------------------------------|--|---|---|---|---|--|-------|------|
| 11.1 Does the camp              | ous meet ed spec standard for physical education<br>es?  |   |   | 4 |   | Comments   | 1.00  | 4.00 |
| 2 U<br>3 A<br>sc<br>4 Sc<br>5 V | rery unsatisfactory - Too small, missing program spaces Insatisfactory - Too small, poor condition exerage - Adequate size, adequate condition, needs ome renovations or updates to function well atisfactory - Good size, good condition ery Satisfactory - Generous size, excellent condition toos not apply |   |   |   |   | Physical education space appears to be in good condition   | 1.    |      |
| 11.2 Does the camp              | ous have a dedicated wellness center?  | 1 |   |   |   | Comments   | 0.50  | 0.50 |
| 1 N<br>5 Y                      | lo<br>es   |   |   |   |   |  |       |      |
| 11.3 Does the comm              | nunity have access to exterior playfields/courts?  |   |   |   | 5 | Comments   | 0.50  | 2.50 |
| 1 N<br>5 Y                      | lo<br>es   |   |   |   |   |  |       |      |
| 11.4 Are facilities av          | vailable to facilitate eSports (High School only)?   | 1 |   |   |   | Comments   | 0.00  | 0.00 |
| 1 N<br>5 Y                      | lo<br>es   |   |   |   |   | Monitoring answer, but doesn't affect overall score.       |       |      |
| 11.5 Are facilities se          | et up to support UIL sanctioned athletics for basketball?  |   |   |   | 5 | Comments   | 0.25  | 1.25 |
| 1 N<br>5 Y                      | lo<br>es   | I | ı |   | ı |  |       |      |
| 11.6 Are facilities se          | et up to support UIL sanctioned athletics for track?   |   |   |   | 5 | Comments   | 0.25  | 1.25 |
|                                 | lo<br>es   |   |   |   |   | Good condition track. Limited spectator seating            |       |      |
| 11.7 Are facilities se          | et up to support UIL sanctioned athletics for football?  |   |   |   | 5 | Comments   | 0.25  | 1.25 |
| 1 N<br>5 Y                      | lo<br>es   |   | • |   |   | Limited spectator seating.                                 |       |      |
| 11.8 Are facilities se          | et up to support UIL sanctioned athletics for volleyball?  |   |   |   | 5 | Comments   | 0.25  | 1.25 |
| 1 N<br>5 Y                      | lo<br>es   |   |   |   |   |  |       |      |
| 11.9 Are facilities se          | et up to support UIL sanctioned athletics for tennis?  | 1 |   |   |   | Comments   | 0.25  | 0.25 |
| 1 N<br>5 Y                      | lo<br>es   |   |   |   |   | 2 courts provided. Supports practice. No spectator seating | j.    | _    |
|                                 | et up to support UIL sanctioned athletics for soccer?  |   |   |   | 5 | Comments   | 0.25  | 1.25 |
| 1 N<br>5 Y                      | lo<br>es   |   |   |   |   |  |       |      |

Perkins&Will 02/11/2022 9

| 11 - Athletics and Well                                   | lness (cont.)  | 1 | 2 | 3 4 | 4 5 | N/  | A  |      |      |
|---|--|---|---|-----|-----|-----|--|------|------|
|   | ated storage) set up to support UIL sanctioned puntry (high school only)?  |   |   |     |     | N// | Comments   | 0.00 | 0.00 |
| 1 No<br>5 Yes   |  |   |   |     |     |     |  |      |      |
| 11.12 Are facilities (dedicated) athletics for golf (high | ated storage) set up to support UIL sanctioned gh school only)?  |   |   |     |     | N/A | Comments   | 0.00 | 0.00 |
| 1 No<br>5 Yes   |  |   |   |     | •   | •   |  |      |      |
|   | ated storage) set up to support UIL sanctioned ing (high school only)?   |   |   |     |     | N/A | Comments   | 0.00 | 0.00 |
| 1 No<br>5 Yes   |  |   |   |     |     |     |  |      |      |
| 11.14 Are facilities set up to the (high school only)?    | to support UIL sanctioned athletics for wrestling  |   |   |     |     | N// | A Comments   | 0.00 | 0.00 |
| 1 No<br>5 Yes   |  |   |   |     |     |     |  |      |      |
| (high school only)?                                       | to support UIL sanctioned athletics for baseball   |   |   |     |     | N/  | A Comments   | 0.00 | 0.00 |
| 1 No<br>5 Yes   |  |   | _ |     |     |     |  |      |      |
| (high school only)?                                       | to support UIL sanctioned athletics for softball   |   |   |     |     | N/  | A Comments   | 0.00 | 0.00 |
| 1 No<br>5 Yes   |  |   | 1 |     |     | -   |  |      |      |
|   | ated space outside of the gymnasium) available to espirit activities for cheerleading and drill team?              | 1 |   |     |     |     | Comments   | 0.25 | 0.25 |
| 1 No<br>5 Yes   |  |   |   |     | •   | •   |  |      |      |
| 11 - Athletics and Well                                   | lness (cont.)  | 1 | 2 | 3 4 | 4 5 | N/  | A  |      |      |
|   | s fields align with FMP Campus Improvements?<br>ot lighting, ADA accessible amenities (high School                 |   |   |     |     | N/A | A Comments   | 0.00 | 0.00 |
| l Very ui   | nsatisfactory - No turf, inaccessible, no site lighting  |   |   |     |     |     | Monitoring answer, but doesn't affect overall score. |      |      |
|   | sfactory - No turf/field in poor condition, some<br>ibility concerns, poor site lighting                           |   |   |     |     |     |  |      |      |
|   | ge - Field in adequate condition, needs some<br>es or renovations to function well                                 |   |   |     |     |     |  |      |      |
|   | ctory - Turf field in good condition, good ADA and site lighting   |   |   |     |     |     |  |      |      |
| 5 Very So<br>excelle                                      | atisfactory - Turf field with excellent maintenance, ant ADA access for spectators and athletes, and site lighting |   |   |     |     |     |  |      |      |
|   | ot apply.  |   |   |     |     |     |  |      |      |

Perkins&Will 02/11/2022 10

| 12 - F | ood Servi                      | ces   |   |   |   |   |   |     |   | 10.00            | 80%  |
|--------|--------------------------------|---|---|---|---|---|---|-----|---|------------------|------|
| 12.1   | Is the Dinin                   | g Commons appropriately configured per the ed spec?   |   |   | 3 |   |   |     | Comments  | 1.00             | 3.00 |
|        | 1 2 3 4 5 N/A                  | Very unsatisfactory - Too small, missing program spaces Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation Average - Adequate size and condition, needs updates or renovations to function well Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to outdoor eating space) Very Satisfactory - Generous size, excellent condition and circulation, multiple options for eating space (ex: connection to outdoor eating space) Does not apply |   |   |   |   |   |     | Missing table and chair storage.  |                  |      |
|        |                                | od Services support spaces appropriately configured per   |   |   |   |   | I | Ι   |   |                  |      |
| 12.2   | the ed spec                    |   |   |   |   |   | 5 |     | Comments  | 1.00             | 5.00 |
|        | 1<br>2<br>3<br>4<br>5          | Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent condition  |   |   |   | · |   |     | Food service spaces appear to function well.  |                  |      |
|        | N/A                            | Does not apply  |   |   |   |   |   |     |   |                  |      |
| 13 - N | Media Res                      |   | 1 | 2 | 3 | 4 | 5 | N/A |   | 30.00            | 63%  |
| 13.1   | Is the Libra<br>visitors to tl |   |   |   | 3 |   |   |     | Comments  | 1.00             | 3.00 |
|        | 1<br>2<br>3<br>4<br>5          | Very unsatisfactory - Not accessible Unsatisfactory - Limited access, difficult to find, no transparency Average - Adequate accessibility, needs updates or renovations to function well Satisfactory - Accessible, easy to find, good transparency, good condition Very Satisfactory - Accessible, easy to find, excellent transparency, excellent condition   |   |   |   |   |   |     | Library appears to be in good condition. The library of<br>entry and is not located in a clear sightline to an entr<br>doors. The secondary corridor entry for after-hours un<br>not have adequate exterior signage for wayfinding. | ry due to corrid | or   |
|        | N/A                            | Does not apply  |   |   |   |   |   |     |   |                  |      |

| 13 - Media Res        | ources - Continued  | 1 | 2 | 3 | 4 | 5 | N/A | A   |      |      |
|-----------------------|---|---|---|---|---|---|-----|---|------|------|
| 13.2 How well d       | oes the Library/Media Center support quiet study?   |   |   | 3 |   |   |     | Comments                                  | 1.00 | 3.00 |
| 1<br>2<br>3<br>4<br>5 | Very unsatisfactory - No quiet study spaces Unsatisfactory - One area in poor condition, poor acoustic privacy Average - One or more areas provided, needing updates or renovations to function well Satisfactory - Clusters or small rooms adjacent to media center, good condition, good acoustic privacy Very Satisfactory - Multiple clusters or small rooms adjacent to media center, excellent condition, excellent   |   |   |   |   |   |     | Few small breakout rooms for quiet study. |      |      |
| N/A                   | acoustic privacy<br>Does not apply  |   |   |   |   |   |     |   |      |      |
| 13.3 How well d       | oes the Library/Media Center support social interaction?  |   |   |   | 4 |   |     | Comments                                  | 1.00 | 4.00 |
| 1<br>2<br>3<br>4<br>5 | Very unsatisfactory - No space Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well Average - Adequate size and condition, needs updates or renovations to function well. Satisfactory - Good size, good condition, layout and furnishings support informal interactions Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions                                |   |   |   |   | l | •   | Large space to congregate is available.   |      |      |
| N/A                   | Does not apply  |   | 1 | ı |   |   | 1   |   |      |      |
| 13.7                  | loes the Library/Media Center support collaborative work bups (4-8 students)?   | 1 |   |   |   |   |     | Comments                                  | 1.00 | 1.00 |
| 1<br>2<br>3<br>4<br>5 | Very unsatisfactory - No breakout rooms, no flexible furniture, no support Unsatisfactory - Too small, one area, poor condition Average - Adequate size, multiple areas provided, needing updates or renovations to function well Satisfactory - Clusters or small rooms adjacent to media center, flexible furniture, good condition Very Satisfactory - Multiple clusters or small rooms adjacent to media center, flexible furniture, excellent condition Does not apply |   |   |   |   |   |     | No small group rooms.                     |      |      |
| 13 5                  | loes the Library/Media Center support collaborative work oups (10-25)?  |   |   |   |   | 5 |     | Comments                                  | 1.00 | 5.00 |
| 1<br>2<br>3<br>4      | Very unsatisfactory - No gathering areas Unsatisfactory - Too small, one common space, limited seating, poor condition Average - Adequate size, one common space, needs updates or renovations to function well   |   | , |   |   |   |     | Large space to congregate is available.   |      |      |
| 5                     | Satisfactory - Good size, multiple common spaces with seating, good condition  Very Satisfactory - Generous size, multiple commons  |   |   |   |   |   |     |   |      |      |
| N/A                   | spaces with seating, excellent condition  Does not apply  |   |   |   |   |   |     |   |      |      |

|   | 13 - Media Re | esources - Continued   | 1        | 2        | 3 | 4 | 5        | N/A      |   |           |      |
|---|---------------|--|----------|----------|---|---|----------|----------|---|-----------|------|
|   | 13.6 How well | does the Library/Media Center support technology?                                      |          |          | 3 |   |          |          | Comments  | 1.00      | 3.00 |
|   | 1             | Very unsatisfactory - No vis comm tools  |          |          |   |   |          |          | Media technology was noted but most isn't up to date  | ∍.        |      |
|   | 2             | Unsatisfactory - Outdated, poorly functioning, or                                      |          |          |   |   |          |          |   |           |      |
|   |               | insufficient   |          |          |   |   |          |          |   |           |      |
|   | 3             | Average - Mix of old and new   |          |          |   |   |          |          |   |           |      |
|   | 4             | whiteboards/projectors/etc.  |          |          |   |   |          |          |   |           |      |
|   | 4             | Satisfactory - projectors, marker boards, smart boards in most spaces - good condition |          |          |   |   |          |          |   |           |      |
|   | 5             | Very Satisfactory - projectors, marker boards, smart                                   |          |          |   |   |          |          |   |           |      |
|   |               | boards in most spaces - new condition  |          |          |   |   |          |          |   |           |      |
|   | N/A           | Does not apply   |          |          |   |   |          |          |   |           |      |
|   | 14 - Technolo | dv.  | 1        | 2        | 3 | 4 | 5        | N/A      |   | 20.00     | 50%  |
|   | 14 1661111616 | 9)   | 1        |          |   | 1 | Т        | 1 1 1    |   | 20.00     | 0070 |
|   | 14.1 How well | equipped are the facilities with instructional technology?                             |          |          | 3 |   |          |          | Comments  |           |      |
|   |               | 37   |          |          |   |   |          |          |   | 1.00      | 3.00 |
|   | 1             | Very unsatisfactory - Limited to no technology present in                              | •        |          | • |   |          | •        | Media technology was noted but most isn't up to date  | <b>9.</b> |      |
|   |               | instructional spaces   |          |          |   |   |          |          |   |           |      |
|   | 2             | Unsatisfactory - One type of technology present  |          |          |   |   |          |          |   |           |      |
|   | 3             | Average - Multiple types of technology, smart boards.                                  |          |          |   |   |          |          |   |           |      |
|   |               | Poor condition. Limited to only certain areas of school.                               |          |          |   |   |          |          |   |           |      |
|   | 4             | Satisfactory - Multiple types of technology, smart                                     |          |          |   |   |          |          |   |           |      |
|   | _             | boards. Good condition.  |          |          |   |   |          |          |   |           |      |
|   | 5             | Very Satisfactory - Multiple types of technology, smart                                |          |          |   |   |          |          |   |           |      |
|   | N/A           | boards. Excellent condition  |          |          |   |   |          |          |   |           |      |
| ŀ |               | Does not apply n adequate number of power and data outlets in learning                 | ı        | <u> </u> | 1 |   | 1        | T .      |   |           |      |
|   | 14.2 spaces?  | n adequate number or power and data outlets in learning                                | 1        |          |   |   |          |          | Comments  | 1.00      | 1.00 |
|   | spaces:       | Very unsatisfactory - Outlet configuration does not                                    | <u> </u> |          |   |   | <u> </u> | <u> </u> |   |           | 1.00 |
|   | ı             | support digital devices throughout school (1 per wall)                                 |          |          |   |   |          |          | Power outlets are lacking; several power cords observ | ea.       |      |
|   | 2             | Unsatisfactory - Outlet configuration support digital                                  |          |          |   |   |          |          |   |           |      |
|   | 2             | devices only in certain areas of school (2 per wall)                                   |          |          |   |   |          |          |   |           |      |
|   | 3             | Average - Outlet configuration support digital devices                                 |          |          |   |   |          |          |   |           |      |
|   | _             | but limited capacity throughout school (3 per wall)                                    |          |          |   |   |          |          |   |           |      |
|   | 4             | Satisfactory - Outlet configuration support digital                                    |          |          |   |   |          |          |   |           |      |
|   | 7             | devices with adequate coverage and capacity in limited                                 |          |          |   |   |          |          |   |           |      |
|   |               | locations (>3 per wall)  |          |          |   |   |          |          |   |           |      |
|   | 5             | Very Satisfactory - Excellent outlet configuration to                                  |          |          |   |   |          |          |   |           |      |
|   |               | support digital devices throughout school (>3 per wall)                                |          |          |   |   |          |          |   |           |      |
|   | N/A           | Does not apply   |          |          |   |   |          |          |   |           |      |

Perkins&Will 02/11/2022 13

| 14 - Technology  | y (cont.)  | 1 | 2 | 3 | 4 | 5 | N/ | 'A  |      |      |
|------------------|--|---|---|---|---|---|----|---|------|------|
| 14.3 Are there a | dequate charging locations for devices?  | 1 |   |   |   |   |    | Comments  | 1.00 | 1.00 |
| 1                | Very unsatisfactory - Not enough charging locations                                    |   |   |   |   |   |    | Power outlets are lacking; several power cords observed | d.   |      |
|                  | throughout school for 1:1  |   |   |   |   |   |    |   |      |      |
| 2                | Unsatisfactory - Charging locations, haphazard   |   |   |   |   |   |    |   |      |      |
|                  | locations, and inadequate in size for number of devices                                |   |   |   |   |   |    |   |      |      |
| 3                | Average - Charging locations well organized but not                                    |   |   |   |   |   |    |   |      |      |
|                  | enough capacity for 1:1  |   |   |   |   |   |    |   |      |      |
| 4                | Satisfactory - Charging locations, haphazard locations,                                |   |   |   |   |   |    |   |      |      |
| _                | but supports 1:1.  |   |   |   |   |   |    |   |      |      |
| 5                | Very Satisfactory - Charging locations throughout school                               |   |   |   |   |   |    |   |      |      |
| N/A              | to support 1:1. Does not apply   |   |   |   |   |   |    |   |      |      |
|                  | equate AV for presentations spaces – cafeteria, gym, aux                               |   |   | 1 | _ | T | 1  |   |      |      |
| 4.4 gym?         | equate AV for presentations spaces – careteria, gym, aux                               |   |   |   |   | 5 |    | Comments  | 1.00 | 5.0  |
| gyiii:<br>1      | Very unsatisfactory - AV not present in one or more                                    |   |   |   |   |   |    | A/V equipment was noted in the large gym and cafeteri   |      | 5.0  |
| '                | space  |   |   |   |   |   |    | A/ v equipment was noted in the large gym and careteri  | ia.  |      |
| 2                | Unsatisfactory - AV undersized for room. Poor condition                                |   |   |   |   |   |    |   |      |      |
|                  | •  |   |   |   |   |   |    |   |      |      |
| 3                | Average - AV adequately sized / poor condition OR AV                                   |   |   |   |   |   |    |   |      |      |
| 4                | undersized / average condition<br>Satisfactory - AV adequately sized for room. Average |   |   |   |   |   |    |   |      |      |
| 4                | Condition.   |   |   |   |   |   |    |   |      |      |
| 5                | Very Satisfactory - AV adequately sized for room.                                      |   |   |   |   |   |    |   |      |      |
| Ü                | Excellent condition.   |   |   |   |   |   |    |   |      |      |
| N/A              | Does not apply   |   |   |   |   |   |    |   |      |      |
| 15 Is there digi | ital media signage at the reception area?  | 1 |   |   |   |   |    | Comments  |      |      |
|                  |  | - |   |   |   |   |    | Comments  | 0.00 | 0.00 |
| 1                | Very unsatisfactory - No digital media present in                                      |   |   |   |   |   |    | No digital media signage noted.                         |      |      |
|                  | reception area   |   |   |   |   |   |    |   |      |      |
| 2                | Unsatisfactory - Undersized, poor condition  |   |   |   |   |   |    |   |      |      |
| 3                | Average - Adequately sized / poor condition OR   |   |   |   |   |   |    |   |      |      |
| 4                | undersized / adequate condition  |   |   |   |   |   |    |   |      |      |
| 4                | Satisfactory - Media signage present, good sized, good condition                       |   |   |   |   |   |    |   |      |      |
| 5                | Very Satisfactory - Generously sized, excellent condition                              |   |   |   |   |   |    |   |      |      |
| N/A              | Does not apply   |   |   |   |   |   |    |   |      |      |

| 15 - Administro   | ation Spaces  | 1 | 2 | 3 | 4 | 5 | N/A |   | 20.00 | 70%  |
|-------------------|---|---|---|---|---|---|-----|---|-------|------|
| 15.1 Is there a r | eception area that functions as a security checkpoint for all |   |   |   |   |   |     | Comments  | 1.00  |      |
| 1                 | Very unsatisfactory - No security checkpoint                  | - |   | • | - | • | •   |   |       |      |
| 2                 | Unsatisfactory - Checkpoint is too small, poor condition      |   |   |   |   |   |     |   |       |      |
| 3                 | Average - Needs updates or renovations to function well       |   |   |   |   |   |     |   |       |      |
| 4                 | Satisfactory - Good size, good condition                      |   |   |   |   |   |     |   |       |      |
| 5                 | Very Satisfactory - Generous size, excellent condition        |   |   |   |   |   |     |   |       |      |
| N/A               | Does not apply  |   |   |   |   |   |     |   |       |      |
| 15.2 Does the a   | dministration area feel welcoming?                            |   |   |   | 4 |   |     | Comments  | 1.00  | 4.00 |
| 1                 | Very unsatisfactory - No welcome space                        |   |   | • |   | • |     | Administration area is good size and well-maintained. |       |      |
| 2                 | Unsatisfactory - Too small, poor lighting and                 |   |   |   |   |   |     | _   |       |      |
|                   | transparency, limited informal seating, poor condition        |   |   |   |   |   |     |   |       |      |
| 3                 | Average - Adequate size and layout, needs updates or          |   |   |   |   |   |     |   |       |      |
|                   | renovations to feel welcoming                                 |   |   |   |   |   |     |   |       |      |
| 4                 | Satisfactory - Good size and layout, good lighting and        |   |   |   |   |   |     |   |       |      |
|                   | transparency, informal seating provided                       |   |   |   |   |   |     |   |       |      |
| 5                 | Very Satisfactory - Generous size and layout, plenty of       |   |   |   |   |   |     |   |       |      |
|                   | light and transparency, informal seating provided,            |   |   |   |   |   |     |   |       |      |
|                   | excellent condition   |   |   |   |   |   |     |   |       |      |
| N/A               | Does not apply  |   |   |   |   |   |     |   |       |      |
| For those s       | spaces that require it, does the administration area have     |   |   |   |   | _ |     | Community   |       |      |
| adequate          | acoustic privacy?   |   |   |   |   | 5 |     | Comments  | 1.00  | 5.00 |
| 1                 | Very unsatisfactory - No acoustic separations                 |   |   | • |   | • |     | Sound transmission does not seem to be an issue.      |       |      |
| 2                 | Unsatisfactory - Acoustic separations do not perform          |   |   |   |   |   |     |   |       |      |
|                   | well  |   |   |   |   |   |     |   |       |      |
| 3                 | Average - Some acoustic separations function okay, but        |   |   |   |   |   |     |   |       |      |
|                   | portions need updates or renovations                          |   |   |   |   |   |     |   |       |      |
| 4                 | Satisfactory - Good acoustic separations                      |   |   |   |   |   |     |   |       |      |
| 5                 | Very Satisfactory - Excellent acoustic separations            |   |   |   |   |   |     |   |       |      |
| N/A               | Does not apply  |   |   |   |   |   |     |   |       |      |
| 15.4 Are conferen | ence rooms easily accessed for public / parent use?           |   |   |   | 4 |   |     | Comments  | 1.00  | 4.00 |
| 1                 | Very unsatisfactory - Not accessible for public/parent        |   |   |   |   |   |     | They are accessed from the administration suite.      |       |      |
|                   | use   |   |   |   |   |   |     |   |       |      |
| 2                 | Unsatisfactory - Limited access, no transparency, poor        |   |   |   |   |   |     |   |       |      |
|                   | condition, difficult to find                                  |   |   |   |   |   |     |   |       |      |
| 3                 | Average - Adequate accessibility, needs updates or            |   |   |   |   |   |     |   |       |      |
|                   | renovations to function well                                  |   |   |   |   |   |     |   |       |      |
| 4                 | Satisfactory - Good accessibility, good transparency,         |   |   |   |   |   |     |   |       |      |
|                   | good size and condition                                       |   |   |   |   |   |     |   |       |      |
| 5                 | Very Satisfactory - Excellent accessibility, excellent        |   |   |   |   |   |     |   |       |      |
|                   | transparency, generous size, excellent condition              |   |   |   |   |   |     |   |       |      |
| N/A               | Does not apply  |   |   |   |   |   |     |   |       |      |