



Educational Suitability Summary Report

Anita Ferrales Coy Facility

Date: 01/08/2021

Score 63% Average

The Alternative Learning Center at the Anita Ferrales Coy Facility has a student enrollment that varies from 5 to 180 students in east Austin. It is a school community built on second chances and a deeply rooted believe that every student desires to achieve their greatest potential. Students attend the school for a predetermined number of days when they have discipline issues at their school or in the community. Low student-to-teacher ratios foster specialized instruction and help improve student behavior. As a specialized facility, the school does not provide many of the programs common at other high schools in the district. The 82,000-square-foot school was built in 1957 and sits on just over 19 acres.

The facilities are dated but in generally good condition, although signage and wayfinding on the campus could be improved. Due to the low number of students, the small drop-off area may be adequate. All studios have ample natural light and adequate lighting controls.

Interview Overview

The interview with Principal Christie Jones provided insights into the unique nature of the Anita Ferrales Coy Facility. He listed many issues the current facility faces and raised the idea of a new facility numerous times. According to the Principal, when the school is at capacity, there is not enough space to safely operate PE classes in the gym or serve food in the cafeteria.

It is challenging to assess the ALC using the same metrics as typical schools because they do not offer electives other than PE. The agriculture program is one program that is working well for the school, and there have been attempts to start other electives in the past. The school does not support the AISD pathways, nor does it provide art and music classes.



Assessment Findings

The Educational Suitability Assessment of Anita Ferrales Coy Facility earned a 63% overall score and places the campus in a category of Average. The assessment consists of seven General Building categories and eight Academic categories to determine areas that need more attention.

N/A Categories: CTE and Career Connected Learning Visual and Performing Arts Anita Ferrales Coy Facility

Very Unsatisfactory Categories (0-35%):

Academics & Learning

Score is very unsatisfactory.

Studios are slightly undersized, and storage is dated. There are no breakout or social spaces in corridors and limited transparency into learning spaces.

Unsatisfactory Categories (36-50%):

Security

Score is unsatisfactory.

General Building

Score is unsatisfactory.

Interior circulation routes are wide with some areas for display of student work, but they are mostly empty. Only the gym can operate after-hours without giving the public access to the rest of the school. There is no community room, and the limited number of murals and displays does not promote pride for the students and community.

Average Categories (51-65%):

Exterior

Score is average.

Exterior of the building looks dated but in good condition. The lack of drop-off canopies makes it difficult to identify the main entry. Monument sign is small and unlit, with letters and paint peeling.

Outdoor Learning and Activity

Score is very average.

No outdoor studios seen during assessment. Learning gardens are small but have access to storage and a hose.

Food Services

Score is average.

If school is at capacity of 180 students, the cafeteria is adequately sized per Ed Spec with good natural light. The kitchen and serving lines are also in average condition.

Media Resources

Score is average.

Library is on the main building corridor with good transparency and natural light. The space is small but has numerous seating areas. Seating is flexible with a good variety of formal and informal options.

Technology

Score is average.

Educational Suitability Summary Report

Anita Ferrales Coy Facility

Studios are equipped with large TVs on mobile carts, although charging locations are limited. A/V in cafeteria is in good condition, with a large projections screen and speakers.

Administration Spaces

Score is average.

Administration spaces are spacious and welcoming with attached conference spaces. Acoustic privacy is poor; hard surfaces in the spaces create an echo. The main office does not have views or access control of the main entry.

Satisfactory Categories (66-80%):

Athletics and Wellness

Score is satisfactory.

Gym space is original to the facility, with original hoops, scoreboard and bleachers. Outdoor spaces are undersized, although there is access to a small playing field, outdoor basketball court and tennis court.

Very Satisfactory Categories (81-100%):

Environmental Quality

Score is very satisfactory.

The building is clean and in good condition, with no odor or pest issues. Studios have ample windows and good views. Acoustics in studios are average, with some sound transfer between studios and hallways.

Controllability of Systems

Score is very satisfactory.

Each studio has an individual thermostat and good lighting controls. Blinds are in good condition, and studios are equipped with three lighting zones.

Furniture, Fixtures, Equipment


Score is very satisfactory.

Furniture throughout the school is a mix of old and new, but all is in good condition. Loose chairs and nesting desks allow the furniture to be rapidly reconfigured for individual or group activities.

Educational Suitability Summary Report

Anita Ferrales Coy Facility

Supporting Photographs




Planted courtyard at main entry.

02/11/2022 Perkins&Will

Educational Suitability Summary Report

Anita Ferrales Coy Facility

Supporting Photographs




02/11/2022 Perkins&Will

Educational Suitability Summary Report

Anita Ferrales Coy Facility

Supporting Photographs




Cafeteria is adequately sized with good natural light. At time of assessment, this area was being partially used as furniture storage due to COVID-19 protocols.

02/11/2022 Perkins&Will

Educational Suitability Summary Report Anita Ferrales Coy Facility

Supporting Photographs



Outdoor furniture and shade structure in poor condition.

02/11/2022



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria

General Building

School Name	Walk Attendees:	Date:
Anita Ferrales Coy Facility	Patrick Reinhard, Kevin Kinsey	12.21.20

1 -	Ext	terior		1	2	3	4	5	N/	Ά	8.75	57%
		Does the site pedestrian t	e permit desirable separation of vehicular, bus and raffic?			3				Comments	1.00	3.00
		1	Very unsatisfactory - Bus, car and pedestrian all happen at the same location							Seems to have separate car and bus drop-off. No cove	r.	
		2	Unsatisfactory - Cars and buses mix, pedestrians are separated									
		3	Average - Buses, cars, and pedestrians are separate but stack space is small									
		4	Satisfactory - Buses, cars, and pedestrians are separate but drop off does not have a canopy or a holding place like a commons or cafeteria									
		5	Very satisfactory - Buses, cars, and pedestrians are separate and drop off area has a canopy and destination									
		N/A	Does not apply									
1		ls the buildir wayfinding?	ng easily identified with appropriate signage and community		2					Comments	0.25	0.50
		1	Very unsatisfactory - Campus has no signage / wayfinding							Raised monument sign is small and unlit. Letters are pe signage but far from street.	eling. Some bu	iilding
		2	Unsatisfactory - Signage/wayfinding is faded/hidden									
		3	Average - Signage / wayfinding visible but not apparent									
		4	Satisfactory - Signage / wayfinding is visible but not good condition									
		5	Very satisfactory - Signage and wayfinding is visible and easy to use									
		N/A	Does not apply									

02/11/2022 ²

1 - Exterior (cont	t.)	1	2	3	4	5	N/A			
1.3 Is the dumps	ster accessible for trash / compost disposal?			3				Comments	0.50	1.50
1	Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster							Compost, recycling and trash present. Very close to car free.	s. Route is not	barrier
2	Unsatisfactory - Compost is present. Route has obstacles to dumpster									
3	Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent.									
4	Satisfactory - Compost and dumpster are directly adjacent and route is barrier free									
5	Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free. Dumpster are shaped / positioned so people of all heights can access it.									
N/A	Does not apply							<u></u>		
2 - Outdoor Lea	rning and Activity	1	2	3	4	5	N/A		10.00	60%
2.1 Are outdoor the ed spec?	studios and support spaces appropriately configured per	1						Comments	1.00	1.00
1	Very unsatisfactory - No dedicated outdoor studios						-	No outdoor learning spaces	•	
2	Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no shade provided									
3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over studio area									
4	Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade coverage over studio area									
5	Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full shade coverage over studio area									
N/A	Does not apply									
	aygrounds (elementary only) and support spaces per the ed spec?						NA	Comments	0.00	0.00
1	Very unsatisfactory - No dedicated active playground				•					
2	Unsatisfactory - Too small, poor condition, no shade provided									
3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over play structure									
4	Satisfactory - Good size, good condition, more than 50% shade coverage over play structure									
5	Very satisfactory - Generous size, excellent condition, full shade coverage over play structure									
N/A	Does not apply									

02/11/2022 ³


2 - 0	utdoor Lea	rning and Activity (cont)	1	2	3	4	5	N/A	N		
2.3		and support spaces appropriately configured per the ed ation on infrastructure not condition of plants)		2					Comments	0.00	0.00
	1	Very unsatisfactory - No dedicated gardens							Monitoring answer, does not affect score for Outdoor I	O.00 O.00	ctivity.
	2	Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no accessible water source							Very small. Several raised planters with no infrastructu space does have hose and some storage.	•	
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, water source is difficult to access									
	4	Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, water source is accessible with 100 ft hose									
	5	Very Satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, water source is less than 50ft from the garden or has irrigation									
	N/A	Does not apply				-					
2.4	Are the rain ed spec?	gardens and/or cisterns appropriately configured per the	1						Comments	0.00	0.00
	1	Very unsatisfactory - No rain gardens or cisterns							Monitoring answer, does not affect score for Outdoor I	earning and A	ctivity.
	2	Unsatisfactory - Too small, poor condition, not functioning, disconnected							No cisterns	-	-
	3	Average - Adequate size, adequate condition, is connected, needs some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, functions properly									
	5	Very Satisfactory - Generous size, excellent condition, exceptional functionality, connected to learning spaces, educational signage provided									
	N/A	Does not apply									
2.5	Does the sch	ool have animal husbandry? (optional)	1						Comments	0.00	0.00
	1	No									
	5	Yes									
2.6	Does the sch	ool have nature loop trails? (optional)	1						Comments	0.00	0.00
	1 5	No Yes									
2.7		nool have a learning pond? (optional)	1						Comments	0.00	0.00
	1	No									
	5	Yes									
2.8	Does the sch	ool have a grass play field and walking trail?					5		Comments	1.00	5.00
	-	No							•		
	I	INO									

3	- Gene	ral Buil	ding	1	2	3	4	5	N/A	N .	11.25	47%
			circulation routes wide enough to safely and effectively ate student movement?					5		Comments	0.50	
		1	Very unsatisfactory - Primary circulation is 5'-0" to 6'-0"							Vac Main hallumu 15 facturida	0.50	2.50
		1	wide							Yes. Main hallways 15 feet wide.		
		2	Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide									
		3	Average - Primary circulation is 7'-0" to 8'-0" wide									
		4	Satisfactory - Primary circulation is 8'-0"-10'-0" wide									
		5	Very satisfactory - Primary circulation is 10'-0"+ wide									
		N/A	Does not apply									
			nity use areas arranged so that the school can allow night thout full school access?		2					Comments	0.75	1.50
		1	Very unsatisfactory - Cafeteria, gym, and library cannot be accessed after hours							Gym has separate entrance. Cafeteria and library are area. All access points to studio wings are securable, b	•	
		2	Unsatisfactory - Only one of the public spaces (Cafeteria, Gym and Library) can be accessed from parking and secured after hours							is open to the rest of the school.	ut one egress p	atriway
		3	Average - Only two of the public spaces can be accessed from parking and secured after hours									
		4	Satisfactory - All of the public spaces can be accessed from parking and secured from the rest of the building but not individually									
		5	Very satisfactory - Cafeteria, gym, and library can be accessed from parking and locked off from rest of campus for night/evening use with their own entrance									
		N/A	Does not apply									
		here a co ool funct	mmunity room that is a dedicated meeting space outside of ion?	1						Comments	0.75	0.75
		1 2	Very unsatisfactory - No dedicated community room Unsatisfactory - Community room but within school function, no access after school hours							None provided.		
		3	Average - Community room, moderate size, but need some renovations or updates to function well									
		4	Satisfactory - Community room, good size /layout, meets needs /functions well									
		5	Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function									
_		N/A	Does not apply							-	-	
			neral appearance of the school convey pride for the d community?		2					Comments	0.25	0.50
		1	Very unsatisfactory - General appearance is poor							Some displays but mostly empty. No exterior murals.		
		2	Unsatisfactory - General appearance is aged but ok									
		3	Average - General appearance is good									
		4	Satisfactory - General appearance shows pride in campus and student works									
		5	Very satisfactory - General appearance shows pride in campus and student works and is welcoming to the community									
		N/A	Does not apply									

- Security		1 2	3	4 5 N	I/A		16.25	
	ility have key card access at all major entries?					Comments	0.25	
1 2 3 4 5 N/A	Very unsatisfactory - No entries Unsatisfactory - 1/4 of major entries Average - 1/2 of major entries Satisfactory - 3/4 of major entries Very satisfactory - All of major entries Does not apply						0.23	
.2 How adequa	ate is site lighting and security for the campus overall?					Comments	1.00	
1	Very unsatisfactory - No exterior lighting, no secure perimeter		<u> </u>					
2	Unsatisfactory - Lighting is limited to front entry only, parking lot lighting poor, security is minimal							
3	Average - Lighting at all night-use entries and parking lot, but poor condition. Security is moderate							
4	Satisfactory - Lighting at all night-use entries and parking lots, good condition, signage less visible, perimeter is well secured but needs updates							
5	Very satisfactory - Signage, parking lots, and entries are well lit, visible and easy to use, perimeter is very secure							
N/A	Does not apply							
	office located at the school entry and configured with a bule to the main corridor?					Comments	1.00	
1	Very unsatisfactory - No secure vestibule, office located far from main entry, allows visitors access to school unsupervised							
2	Unsatisfactory - No secure vestibule, office located somewhat far from main entry, minimal supervision of visitors							
3	Average - Office close to entry, views of front door, but no secure vestibule							
4	Satisfactory - Office is well-located with a secure vestibule, but needs updates							
5	Very satisfactory - Office well-located with secure vestibule and all appropriate security features							
N/A	Does not apply						1	
	ugh interior transparency for faculty to passively supervise I their activities who are not in studios?	2				Comments	1.00	2
1	Very unsatisfactory - No transparency of walls				5	Small windows in doors.		
2	Unsatisfactory - Limited transparency in certain locations							
3	Average - Good transparency in certain locations but inadequate or missing in other locations of school							
4	Satisfactory - Adequate transparency throughout the school							
5	Very satisfactory - Excellent transparency throughout the school							
N/A	Does not apply							

02/11/2022 °

5 - Environmen	tal Quality	1	2	3	4	5	N/A		25.00	84%
5.1 How are ac	oustics in studios in general?			3				Comments	1.00	3.00
1	Very unsatisfactory - Recognized word/sound from adjacent studio/corridor							Can hear some from hallway but it is not disruptive.		
2	Unsatisfactory - Audible sound from adjacent									
	studio/corridor									
3	Average - Slight sound from outside room									
4	Satisfactory - Walls to deck insulated only white noise from mechanical system									
5	Very satisfactory - Able to hear quiet speaking from across the room									
N/A	Does not apply							<u></u>		
5.2 Is the studic	o artificial lighting adequate quality?			3				Comments	1.00	3.00
1	Very unsatisfactory - Sporadic lights work, glare, less than 20 FC				•			Fluorescent tubes with textured plastic shields.		
2	Unsatisfactory - 10-19 FC or serious glare									
3	Average- 20-29 FC minor glare									
4	Satisfactory - 30-39 FC and no glare									
5	Very satisfactory - 40+ FC and no glare									
N/A	Does not apply									
5.3 Is there acco	ess to natural light in studios?					5		Comments	1.00	5.00
1	Very unsatisfactory - No learning spaces have natural light							Lots of windows in studios.		
2	Unsatisfactory - 1-25% of learning spaces have natural light or windows are too small to let in light									
3	Average - 26-50% of learning spaces have natural light									
4	Satisfactory - 51-75% of learning spaces have natural light									
5	Very satisfactory - 76-100% of learning spaces have natural light									
N/A	Does not apply							<u></u>		
5.4 Is there acce	ess to outside views from learning spaces?					5		Comments	1.00	5.00
1	Very unsatisfactory - No learning spaces have views		I	1	_	1		Windows at and below eye level.		
2	Unsatisfactory - 1-25% of learning spaces have views or									
_	windows are too small to see out									
3	Average - 26-50% of learning spaces have views									
4	Satisfactory - 51-75% of learning spaces have views									
5	Very satisfactory - 76-100% of learning spaces have views									
N/A	Does not apply									



5 - E	nvironmen	tal Quality (cont.)	1	2	3	4	5	N/A			
5.5	Does the bu	uilding have odor or pest problems?					5		Comments	1.00	5.00
6 - C	1 2 3 4 5 N/A Controllabil	Very unsatisfactory - Evidence of both pests and odors Unsatisfactory - Evidence of pests or odors Average - Limited evidence of pests, no odors Satisfactory - No evidence of pests / odors, school cleanliness in good condition Very Satisfactory - No evidence, school cleanliness in excellent condition Does not apply ity of Systems	1	2	3	4	5	N/A		12.50	84%
6.1	Does the st	udio thermostat allow for individual control?					5		Comments	0.50	2.50
	1 5	No Yes				- -			·		
6.2	Are shades	provided to control natural light in learning spaces?				4			Comments	1.00	4.00
	1 2 3 4 5 N/A	Very unsatisfactory - No, windows are covered with boards/paper Unsatisfactory - No, windows have no light control Average - Yes, but poor condition blinds Satisfactory - Yes, blinds Very satisfactory - Blackout shades Does not apply							Blinds are old but in good condition.		
6.3		quality of lighting controls in the studios?				4			Comments	1.00	4.00
	1 2 3 4 5 N/A	Very unsatisfactory - Single switch only per room Unsatisfactory - Alternating rows switch off Average - Alternating lamps in single fixtures switch off Satisfactory - Tri level switching Very satisfactory - Dimmable Does not apply			<u>.</u>		<u>.</u>		Three light zones are individually switched.		

7 - F	urniture. Fi	xtures & Equipment	1	2	3	4	5	N/A		18.75	91%
		current condition of the furniture?			-	4			Comments		-
										0.75	3.00
	1	Very unsatisfactory - Damaged or broken, non-functioning							Mix of old and new but in good condition.		
	2	Unsatisfactory - Torn/ bent/ wrong size									
	3	Average - Scratched/dented/marked									
	4	Satisfactory - Not new, but sturdy and clean									
	5	Very satisfactory - New									
	N/A	Does not apply				_					
7.2	Are a variet school - lea	y of furniture types being accommodated throughout the rning commons, dining commons, other multi-use spaces?					5		Comments	1.00	5.00
	1	Very Unsatisfactory - Same furniture used in all spaces									
	2	Unsatisfactory - Furniture variety in one multi-use space									
	3	Average - Furniture variety in more than one multi-use space									
	4	Satisfactory - All multi-use spaces have greater than one type of furniture									
	5	Very satisfactory - All multi-use spaces have greater than two types of furniture									
	N/A	Does not apply					r				
7.3	How well do space?	pes furniture accommodate rapid reconfiguration of a				4			Comments	1.00	4.00
	1	Very Unsatisfactory - Furniture is fixed or very heavy							Nesting desks and loose chairs. Allows individual or gro	oup activities.	
	2	Unsatisfactory - Furniture does not allow desks to be configured as individuals, small groups, or large groups									
	3	Average - Mix of furniture that can reconfigure but is cumbersome to move									
	4	Satisfactory - Furniture is flexible for multiple configurations of space									
	5	Very satisfactory - Furniture is flexible for multiple configurations of space, easy to move and stack									
	N/A	Does not apply									
7.4	ls the furnitu	ure ergonomic and size appropriate for grade level?					5		Comments	1.00	5.00
	1	Very unsatisfactory - Desk with attached chair combinations too small for grade level							Yes		
	2	Unsatisfactory - Desk with attached chair combinations									
	3	Average - Mix of studios with tables/loose chairs and desks with fixed seats									
	4	Very satisfactory - Tables with loose chairs									
	5	Very satisfactory - Tables with loose chairs that allow students to be active									
	N/A	Does not apply									

02/11/2022 °

Waste		1	2	3	4	5	N/A		5.00	30
	and corridors have blue recycle bins with bilingual s and/or image sorting instructions?			3				Comments	0.50	1.
1	Very unsatisfactory - There are no recycling and landfill bins and signage are sparse or infrequent, OR there are only landfill bins with no recycling bins.							Does not affect overall score. Studios all had bins but n corridors.	o labels. No bi	ns in
2	Unsatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage.									
3	Average - 50% of corridors and studios have both a landfill bin and a recycle bin in an accessible location. The containers have clear signage.									
4	Satisfactory - 75% of studios and corridors have a visible landfill and recycle collection containers in an accessible location. The containers have clear signage.									
5	Very satisfactory - All studios / corridors (100%) have visible landfill and recycle collection containers in accessible locations. The containers have clear signage, and the style and format is consistent and uniform across campus.									
N/A	Does not apply									
each: gree	afeteria (or wherever meals are served) have at least one of on compost bin, blue recycle bin, and landfill bin? Are the bins early with bilingual and/or image sorting?						Na	Comments	0.50	0.
1	Very unsatisfactory- There may be landfill bins, but there are no compost and/or recycle bins. There is not clear sorting signage.		I	I		I	I	Can't determine as cafeteria is not functioning at time	of visit.	
2	Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located next to one another. Signage is absent or inconsistent.									
3	Average- There is at least one waste station with all three bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and consistent.									
3	bins (recycle, compost, landfill) located with close proximity									
	bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and consistent. Satisfactory- There are several waste stations as described									

02/11/2022



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria

Academics - Middle School / High School

School Name	Walk Attendees:	Date:
Anita Ferrales Coy Facility	Patrick Reinhard, Kevin Kinsey	12.21.20


8 - Acade	mics 8	& Learning	1	2	3	4	5	N/A	A	50.00	34%
8.1 Ares	studios	appropriately configured per the ed spec?		2					Comments	1.00	2.00
	1	Very unsatisfactory - Too small, no flexibility, disconnected			-				768 s.f. studios. Only one area for teaching.		
	2	Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected									
	3	Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.									
	4	Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces									
	5	Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces									
	N/A	Does not apply									
8.2 Do st spec		have appropriate support spaces such as storage per the ed			3				Comments	1.00	3.00
	1 2	Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition							Undersized and dated, but built in studio.		
	3	Neutral - Adequate size, average condition, needs updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent condition									
- I	N/A	Does not apply									

02/11/2022 ²

8 - A	cademics &	& Learning (cont.)	1	2	3	4	5	N/A	N	
8.3		earning neighborhoods have small and medium (high school rooms and open collaboration space?	1						Comments 1.00	1.00
	1	Very unsatisfactory - No breakout rooms or open collaboration spaces are provided							Traditional studios along hallway. No breakout spaces near studios.	
	2	Unsatisfactory - Too small or too few, poor condition, no flexibility, lacks visual connection to learning neighborhood, poor acoustic privacy								
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well								
	4	Satisfactory - Good size, good condition and flexibility, transparency and connection to learning neighborhood, acoustic privacy								
	5	Very Satisfactory - Generous size, excellent condition and flexibility, transparency and connection to learning neighborhood, acoustic privacy								
	N/A	Does not apply								
8.4	Are Science spec?	Labs and support spaces appropriately configured per the ed			3				Comments 1.00	3.00
	1	Very unsatisfactory - No dedicated science room							New adjustable-height lab tables. Connected room is occupied by nurse's	
	2	Unsatisfactory - Too small, poor condition, no connected support space							office but has storage. No vent hood.	
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well								
	4	Satisfactory - Good size, good condition, connected support spaces								
	5	Very Satisfactory - Generous size, excellent condition, connected support spaces								
	N/A	Does not apply								
8.5		Spaces and support spaces appropriately configured per the ross reference with CTE below)	1						Comments 1.00	1.00
	1	Very unsatisfactory - No dedicated maker spaces								
	2	Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility								
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well								
	4	Satisfactory - Good size, good condition, connected to learning spaces								
	5	Very Satisfactory - Generous size, excellent condition, connected to learning spaces								
		Does not apply								




8 - A	ademics &	Learning (cont.)	1	2	3	4	5	N/A			
8.6	Is there a Pro	ofessional Learning Center in the learning neighborhood?	1						Comments	1.00	1.00
	1	Very unsatisfactory - No dedicated space for Professional Learning Center			•				None provided		
	2	Unsatisfactory - Too small, poor condition, disconnected									
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected									
	5	Very Satisfactory - Generous size, excellent condition, connected									
8.7		equate places to display the evidence and artifacts of the 2D and 3D)?			3				Comments	1.00	3.00
	1	Very unsatisfactory - No dedicated space							Some 3D display cases. Space above lockers has artwork	k and collages.	
	2	Unsatisfactory - Too small, non-dedicated, poor condition									
	3	Average - Adequate size, adequate condition, needs updates or renovations to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply	1			-	1				
8.8		lding / learning neighborhood provide adequate s for students/teachers to collaborate in varying group sizes?	1						Comments	1.00	1.00
	1	Very unsatisfactory - No space to support collaboration in various sizes.							None		
	2	Unsatisfactory - Too small, inflexible, only one option, does not support a variety of group sizes									
	3	Average - Adequate space for collaboration, needs updates or renovations to function well.									
	4	Satisfactory - Good size, good condition, multiple options to support a variety of group sizes									
	5	Very Satisfactory - Generous size, excellent condition, multiple options to support a variety of group sizes									
	N/A	Does not apply	1	1		-					
8.9	Does the bui	lding provide opportunities for informal interaction?	1						Comments	1.00	1.00
	1	Very unsatisfactory - No space							Just hallways with no breakout areas.		
	2	Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well									
	3	Average - Adequate size and condition, needs updates or renovations to function well.									
	4	Satisfactory - Good size, good condition, layout and furnishings support informal interactions									
	5	Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions									
	N/A	Does not apply									




		k Learning (cont.)	1	2	3	4	5	N/A		· · · · ·	
	Does the bu independer	ilding provide adequate opportunities for students to work tly?	1						Comments	1.00	1.0
	1	Very unsatisfactory - No breakout rooms/small study spaces							No breakout spaces near studios.		
	2	Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood									
	3	Average - Adequate size and condition, needs updates or renovations to function well.									
	4	Satisfactory - Good size and condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood									
	5	Very Satisfactory - Generous size, excellent condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood									
	N/A	Does not apply									
	Special Edu	cation									
8.11	Are Special	Education spaces appropriately configured per the ed spec?						Na	Comments	0.00	0
	1	Very unsatisfactory - Too small, no flexibility, disconnected									
	2	Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected									
	3	Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.									
	4	Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces									
	5	Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces									
	N/A	Does not apply									
		Education support spaces, such as storage, space for er, appropriately configured per the ed spec?						Na	Comments	0.00	0
	1	Very unsatisfactory - None provided									
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent condition									
	N/A	Does not apply									

8 - Ao		Learning (cont.)	1	2	3	4	5	N/A		1	
8.13		le restrooms and changing rooms readily available to the ation spaces?						Na	Comments	0.00	0.00
	1 5	No Yes									
	STEAM Cent										
0.14		npus have space to support a "STEAM" center?	1		T				Comments		
0.14										0.00	0.00
	1	Very unsatisfactory - No available space for STEAM center and inadequate studio / collaborative space							Monitoring answer, but does not count toward overall s	core	
	2	Unsatisfactory - Collaborative areas / studios for CTE/CCL are completely separate but adequate size									
	3	Neutral - Collaborative areas / studios for CTE/CCL are adjacent but function separately									
	4	Satisfactory - Collaborative areas / studios for CTE/CCL function and have space availability to create STEAM center									
	5	Very Satisfactory - Functioning STEAM center offers studios, labs, common collaborative areas to support multimedia distance and hands-on project based learning									
	N/A	Does not apply									
9 - C1	E and Care	eer Connected Learning								0.00	N/A
9.1		your campus to a CTE cluster pathway that is aligned with grams (Middle School only)?						NA	Comments	0.00	0.00
	1 2	Very unsatisfactory - No correlation to CTE cluster pathway, no CTE programs. Unsatisfactory - School supports less than half of the CTE programs that are listed in the cluster pathway.									
	3	Average - School support half of CTE programs listed in the cluster pathway, but missing some.									
	4	Satisfactory - School support a majority of CTE programs listed in the CTE cluster pathway.									
	5 N/A	Very Satisfactory - School is aligned with CTE cluster pathway. Does not apply									
9.2		acilities align with the CTE Ed Spec Requirements for the ways offered?: Architecture and Construction						NA		0.00	0.00
	1 5 N/A	No Yes Does not apply									
9.3		nd Video Technology and Communications						NA		0.00	0.00
9.4	Business, Mo	nagement and Administration						NA		0.00	0.00
9.5	Education ar	nd Training						NA		0.00	0.00
9.6	Health Scien	ce						NA		0.00	0.00




9 - CTE and Career Connected Learning (cont.)	1	2	3	4	5	N/A			
9.7 Hospitality and Tourism						NA		0.00	0.00
9.8 Human Services (high school only)						NA		0.00	0.00
9.9 Information Technology						NA		0.00	0.00
9.10 Agriculture, Food and Natural Resources						NA		0.00	0.00
9.11 Science, Technology, Engineering, and Mathematics						NA		0.00	0.00
9.12 Transportation, Distribution and Logistics						NA		0.00	0.00
9.13 Finance (high school only)						NA		0.00	0.00
9.14 Government and Public Administration / JROTC Military programs (high school only)						NA		0.00	0.00
9.15 Law, Public Safety, Corrections and Security (high school only)						NA		0.00	0.00
9.16 Manufacturing (high school only)						NA		0.00	0.00
9.17 Marketing, Sales and Services (high school only)						NA		0.00	0.00
10 - Visual and Performing Arts								0.00	N/A
10.1 Is there flexibility of space to also be used by CTE and Athletics?						N/A	Comments	0.00	0.00
1 No 5 Yes							Monitoring answer, but doesn't affect overall score.		
10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec?						N/A	Comments	0.00	0.00
1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply									
10.3 Are orchestra and support spaces appropriately configured per the ed spec?						N/A	Comments	0.00	0.00
1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition									



10 - Visual and Performing Arts (cont.)	1	2	3	4	5	N//	4		
10.4 Are choir and support spaces appropriately configured per the ed spec?						N/A	A Comments	0.00	0.0
1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply									
10.5 Are dance and support spaces appropriately configured per the ed spec?				T		N/A	Comments	0.00	0.
 Very unsatisfactory - Too small, missing program spaces Unsatisfactory - Too small, poor condition Neutral - Adequate size, adequate condition, needs updates or renovations to function well. Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition 									
N/A Does not apply 10.6 Are theater and support spaces appropriately configured per the ed spec?						N/A	Comments	0.00	0
 Very unsatisfactory - Too small, missing program spaces Unsatisfactory - Too small, poor condition Neutral - Adequate size, adequate condition, needs updates or renovations to function well. Satisfactory - Good size, good condition 				-					
5 Very Satisfactory - Generous size, excellent condition N/A Does not apply									
10.7 Are visual arts and support spaces appropriately configured per the ed spec?						N/A	A Comments	0.00	0.
 Very unsatisfactory - Too small, missing program spaces Unsatisfactory - Too small, poor condition Neutral - Adequate size, adequate condition, needs updates or renovations to function well. Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition 									
N/A Does not apply		1			_	r			
10.8 Does the campus have adequate space for the specialty arts programs (Ensemble, Guitar, Music studies, Music theory and Piano)?						N/A	A Comments	0.00	0
1 No 5 Yes									

11 - Athletics and Wellness							10.00	80%
11.1 Does the campus meet ed spec standard for physical education program spaces?			3			Comments	1.00	3.00
1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply						Original hoops, scoreboard and bleachers. Could not fu gym.	nction as a com	petition
11.2 Does the campus have a dedicated wellness center?				5		Comments	0.50	2.50
1 No 5 Yes								
11.3 Does the community have access to exterior playfields/courts?				5		Comments	0.50	2.50
1 No 5 Yes	_	_		-		Community uses soccer and playgrounds.		
1].4 Are facilities available to facilitate eSports (High School only)?					N/A	Comments	0.00	0.00
1 No 5 Yes						Monitoring answer, but doesn't affect overall score.		
11.5 Are facilities set up to support UIL sanctioned athletics for basketball?					N/A	Comments	0.00	0.00
1 No 5 Yes								
11.6 Are facilities set up to support UIL sanctioned athletics for track?					N/A	Comments	0.00	0.00
1 No 5 Yes								
1].7 Are facilities set up to support UIL sanctioned athletics for football?					N/A	Comments	0.00	0.00
1 No 5 Yes								
1].8 Are facilities set up to support UIL sanctioned athletics for volleyball?					N/A	Comments	0.00	0.00
1 No 5 Yes								
1].9 Are facilities set up to support UIL sanctioned athletics for tennis?					N/A	Comments	0.00	0.00
1 No 5 Yes								
11.10 Are facilities set up to support UIL sanctioned athletics for soccer?					N/A	Comments	0.00	0.00
1 No 5 Yes								



1 No 5 Yes 11.12 Are facilities (dedicated storage) set up to support UIL sanctioned athletics N/A Comments 0.00 0.0 1 No 5 Yes 1 No 5 1 1 No 5 Yes 1 N/A Comments 0.00 0										V/	11/20
1 No 0.00	11 - /	thletics and Wellness (cont.)	1	2	3	4	5	N/A			
5 Yes 11.12 Are facilities (dedicated storage) set up to support UIL sonctioned athletics 11/4 Are facilities (dedicated storage) set up to support UIL sonctioned athletics 11/4 Are facilities (dedicated storage) set up to support UIL sonctioned athletics 11/4 11/4 Comments 0.00 0.00 0.00 1 No 1 No 1 1/4 Comments 0.00 0.00 0.00 1 No 1 No 1 1/4 Comments 0.00 0.00 0.00 1 No 1 No 1 1/4 No 0.00 0.00 0.00 1 No 1 No 1 1/4 No 0.00 0.00 0.00 0.00 1 No 1 No 1 1/4 Comments 0.00 0.0	11.11	Are facilities (dedicated storage) set up to support UIL sanctioned athletics for cross-country (high school only)?						N/A	Comments	0.00	0.00
III.2 for golf (high school only)? N/A Comments 0.00 0.00 III.3 Are facilities (dedicated storage) set up to support UIL sonctioned athletics for westing (high school only)? N/A Comments 0.00 0.00 III.4 No N/A Comments 0.00 0.00 III.5 Yes N/A Comments 0.00 0.00 III.5 Xer facilities set up to support UIL sanctioned athletics for baseball (high school only)? N/A Comments 0.00 0.00 III.6 Are facilities set up to support UIL sanctioned athletics for baseball (high school only)? N/A Comments 0.00 0.00 III.6 Are facilities set up to support UIL sanctioned athletics for softboll (high school only)? N/A Comments 0.00 0.00 III.7 Are facilities set up to support UIL sanctioned athletics for softboll (high school only) N/A Comments 0.00 0.00 <td></td> <td>•</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>		•									
s Yes 11.13 Are facilities (deficited torge) is tup to support UIL sonctioned athletics N/A Comments 0.00 0.00 1 No N/A Comments 0.00 0.00 1 No N/A Comments 0.00 0.00 1 No N/A Comments 0.00 0.00 <td< td=""><td>11.12</td><td></td><td></td><td></td><td></td><td></td><td></td><td>N/A</td><td>Comments</td><td>0.00</td><td>0.00</td></td<>	11.12							N/A	Comments	0.00	0.00
II.13 for swimming (high school only)? N/A Comments 0.00 0.00 1 No N/A Comments		•									
5 Yes 11.4 Are facilities set up to support UIL sometioned athletics for wrestling (high school only)? N/A Comments 0.00 0.00 1 No No Comments 0.00 0.00 1 No N/A Comments 0.00 0.00 1 No No Comments 0.00 0.00 1 No N/A N/A Comments 0.00 0.00 1 No N/A N/A Comments 0.00 0.00 1 No N/A <	11.13							N/A	Comments	0.00	0.00
III.4 school only)? Comments 0.00 0.00 0.00 0.00 1 No No N/A Comments 0.00 0.00 1 No No N/A N/A Comments 0.00 0.00 1 No No N/A N/A Comments 0.00 0.00 1 No No N/A Comments 0.0		•									
S Yes 11.15 Are facilities set up to support UIL sonctioned athletics for baseball (high school only)? No No 0.00 0.00 0.00 1 No	11.14							N/A	Comments	0.00	0.00
II.16 school only)? No O.00 O.											
s Yes 11.6 Are facilities set up to support UIL sanctioned athletics for softball (high school only)? N/A Comments 0.00 0.00 1 No 5 Yes N/A Comments 0.00 0.00 1.17 Are facilities (dedicated space outside of the gymnasium) available to support competitive spirit activities for cheerleading and drill team? N/A Comments 0.00 0.00 0.00 1 No 5 Yes N/A Comments 0.00 0.00 0.00 1 No 5 Yes N/A Comments 0.00 0.00 0.00 1 No 5 Yes N/A Comments 0.00 0.00 0.00 1 No 5 Yes N/A Comments 0.00 <td>11.15</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>N/A</td> <td>Comments</td> <td>0.00</td> <td>0.00</td>	11.15							N/A	Comments	0.00	0.00
II.10 school only? N/A Comments 0,00 0,00 0,00 1 No 5 Yes N/A Comments 0,00		•				•					
5 Yes 11.17 Are facilities (dedicated space outside of the gymnasium) available to support competitive spirit activities for cheerleading and drill team? N/A Comments 0.00 0.00 1 No 5 Yes Yes N/A Comments 0.00 0.00 1 No 5 Yes Yes N/A Comments 0.00 0.00 1 No 5 Yes Yes N/A Comments 0.00 0.00 1 No 5 Yes N/A Comments 0.00 0.00 1 No 5 Yes N/A Comments 0.00 0.00 1.18 How do the athletics fields align with FMP Campus Improvements? Turf Field, Parking Iot lighting, ADA accessible amenities (high School only) N/A Comments 0.00 0.00 1 Very unsatisfactory - No turf, inaccessible, no site lighting N/A Monitoring answer, but doesn't affect overall score. 0.00 0.00 2 Unsatisfactory - No turf/field in good condition, some accessibility concerns, poor site lighting N/A Monitoring answer, but doesn't affect overall score. Very Satisfact	11.16							N/A	Comments	0.00	0.00
III.17 support competitive spirit activities for cheerleading and drill team? IV/A Comments 0.00 0.00 1 No 5 Yes 0.00 <						•					
5 Yes I1 - Athletics and Wellness (cont.) 1 2 3 4 5 N/A 11.18 How do the athletics fields align with FMP Campus Improvements? Turf Field, Parking lot lighting, ADA accessible amenities (high School only) 1 2 3 4 5 N/A 11.18 How do the athletics fields align with FMP Campus Improvements? Turf Field, Parking lot lighting, ADA accessible amenities (high School only) 1 2 3 4 5 N/A 1 Very unsatisfactory - No turf, inaccessible, no site lighting 3 Average - Field in adequate condition, some accessibility concerns, poor site lighting 3 Average - Field in adequate condition, needs some updates on renovations to function well 4 Satisfactory - Turf field in good condition, good ADA access and site lighting 5 Very Satisfactory - Turf field with excellent maintenance, excellent ADA access for spectators and athletes, excellent site lighting 5 Very Satisfactory - Turf field with excellent maintenance, excellent ADA access for spectators and athletes, excellent site lighting 5 5 Very Satisfactory - Turf field with excellent maintenance, excellent site lighting 6 Very Satisfactory - Turf field with excellent maintenance, excellent ADA access for spectators and athletes, excellent site lighting 5 8 5 5 5 5 <	11.17							N/A	Comments	0.00	0.00
11.18 How do the athletics fields align with FMP Campus Improvements? Turf N/A Comments 0.00 0.0 1 Very unsatisfactory - No turf, inaccessible, no site lighting M/A Monitoring answer, but doesn't affect overall score. 2 Unsatisfactory - No turf/field in poor condition, some accessibility concerns, poor site lighting Monitoring answer, but doesn't affect overall score. 3 Average - Field in adequate condition, needs some updates or renovations to function well Monitoring answer, but doesn't affect overall score. 4 Satisfactory - Turf field in good condition, good ADA access and site lighting Very Satisfactory - Turf field with excellent maintenance, excellent ADA access for spectators and athletes, excellent site lighting											
II.18 Field, Parking lot lighting, ADA accessible amenities (high School only) IV/A Comments 0.00 0.0 1 Very unsatisfactory - No turf, inaccessible, no site lighting Monitoring answer, but doesn't affect overall score. 0.00 0.0 2 Unsatisfactory - No turf/field in poor condition, some accessibility concerns, poor site lighting Monitoring answer, but doesn't affect overall score. 1 Very unsatisfactory - No turf/field in good condition, some accessibility concerns, poor site lighting Monitoring answer, but doesn't affect overall score. 1 Very attisfactory - Turf field in good condition, some access and site lighting Monitoring answer, but doesn't affect overall score. 1	11 - /	thletics and Wellness (cont.)	1	2	3	4	5	N/A			
 2 Unsatisfactory - No turf/field in poor condition, some accessibility concerns, poor site lighting 3 Average - Field in adequate condition, needs some updates or renovations to function well 4 Satisfactory - Turf field in good condition, good ADA access and site lighting 5 Very Satisfactory - Turf field with excellent maintenance, excellent ADA access for spectators and athletes, excellent site lighting 	11.18	How do the athletics fields align with FMP Campus Improvements? Turf Field, Parking lot lighting, ADA accessible amenities (high School only)						N/A	Comments	0.00	0.00
 accessibility concerns, poor site lighting Average - Field in adequate condition, needs some updates or renovations to function well Satisfactory - Turf field in good condition, good ADA access and site lighting Very Satisfactory - Turf field with excellent maintenance, excellent ADA access for spectators and athletes, excellent site lighting 		1 Very unsatisfactory - No turf, inaccessible, no site lighting							Monitoring answer, but doesn't affect overall score.	L	
or renovations to function well Satisfactory - Turf field in good condition, good ADA access and site lighting Very Satisfactory - Turf field with excellent maintenance, excellent ADA access for spectators and athletes, excellent site lighting 											
and site lighting 5 Very Satisfactory - Turf field with excellent maintenance, excellent ADA access for spectators and athletes, excellent site lighting											
excellent ADA access for spectators and athletes, excellent site lighting		, , , , , , , , , , , , , , , , , , ,									
N/A Does not apply.		excellent ADA access for spectators and athletes, excellent									
		N/A Does not apply.						L			

2 - Food Services								10.00	609
12.1 Is the Dining Commons appropriately configured per the ed spec?			3				Comments	1.00	3.0
 Very unsatisfactory - Too small, missing program spaces Unsatisfactory - Too small, poor condition, only one option 		•				•	Adequate size with views of the exterior.	•	
for eating space provided, inadequate circulation									
3 Average - Adequate size and condition, needs updates or renovations to function well									
4 Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to outdoor eating space)									
5 Very Satisfactory - Generous size, excellent condition and circulation, multiple options for eating space (ex: connection to outdoor eating space)									
N/A Does not apply		-						-	
12.2 Are the Food Services support spaces appropriately configured per the ed spec?			3				Comments	1.00	3.
1 Very unsatisfactory - None provided				•	•		Connected with good transparency and two serving wir	ndows.	
2 Unsatisfactory - Too small, disconnected, poor condition									
3 Neutral - Adequate size, average condition, needs updates or renovations to function well									
4 Satisfactory - Good size, connected, good condition									
5 Very Satisfactory - Generous size, connected, excellent condition									
N/A Does not apply									
3 - Media Resources	1	2	3	4	5	N/A	、	30.00	60
13.1 Is the Library/Media Center easily accessible for the occupants and visitors to the school?				4			Comments	1.00	4.(
1 Very unsatisfactory - Not accessible							Off main entry corridor. Good signage. Adequate trans	parency.	
2 Unsatisfactory - Limited access, difficult to find, no transparency									
3 Average - Adequate accessibility, needs updates or renovations to function well									
4 Satisfactory - Accessible, easy to find, good transparency, good condition									
5 Very Satisfactory - Accessible, easy to find, excellent transparency, excellent condition									
N/A Does not apply									

02/11/2022 "

13 - Media Reso	urces - Continued	1	2	3	4	5	N/A			
13.2 How well do	es the Library/Media Center support quiet study?		2					Comments	1.00	2.0
1	Very unsatisfactory - No quiet study spaces							One large area. Small breakout space with half-height v	valls.	
2	Unsatisfactory - One area in poor condition, poor acoustic privacy									
3	Average - One or more areas provided, needing updates or renovations to function well									
4	Satisfactory - Clusters or small rooms adjacent to media center, good condition, good acoustic privacy									
5	Very Satisfactory - Multiple clusters or small rooms adjacent to media center, excellent condition, excellent acoustic privacy									
N/A	Does not apply									
13.3 How well do	es the Library/Media Center support social interaction?				4			Comments	1.00	4.0
1	Very unsatisfactory - No space							Lots of different seating areas and movable furniture.		
2	Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well									
3	Average - Adequate size and condition, needs updates or renovations to function well.									
4	Satisfactory - Good size, good condition, layout and furnishings support informal interactions									
5	Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions									
N/A	Does not apply									
	es the Library/Media Center support collaborative work in : (4-8 students)?		2					Comments	1.00	2.00
1	Very unsatisfactory - No breakout rooms, no flexible furniture, no support							Only one space, but furniture is flexible.		
2	Unsatisfactory - Too small, one area, poor condition									
3	Average - Adequate size, multiple areas provided, needing updates or renovations to function well									
4	Satisfactory - Clusters or small rooms adjacent to media center, flexible furniture, good condition									
5	Very Satisfactory - Multiple clusters or small rooms adjacent to media center, flexible furniture, excellent condition									
N/A	Does not apply									
13.5 How well doo larger group	es the Library/Media Center support collaborative work in s (10-25)?			3				Comments	1.00	3.0
1	Very unsatisfactory - No gathering areas							One space with lots of different seating types.		
2	Unsatisfactory - Too small, one common space, limited seating, poor condition									
3	Average - Adequate size, one common space, needs updates or renovations to function well									
4	Satisfactory - Good size, multiple common spaces with seating, good condition									
5	Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition									
N/A	Does not apply									



13 -	Media Reso	ources - Continued	1	2	3	4	5	N/A			
13.	6 How well do	pes the Library/Media Center support technology?			3				Comments	1.00	3.00
	1	Very unsatisfactory - No vis comm tools							Mobile TV, projector and screen and computer carts.		
	2	Unsatisfactory - Outdated, poorly functioning, or insufficient									
	3	Average - Mix of old and new whiteboards/projectors/etc.									
	4	Satisfactory - projectors, marker boards, smart boards in most spaces - good condition									
	5	Very Satisfactory - projectors, marker boards, smart boards in most spaces - new condition									
	N/A	Does not apply							<u></u>		
14 -	Technology	/	1	2	3	4	5	N/A		20.00	60%
14.] How well ec	quipped are the facilities with instructional technology?			3				Comments	1.00	3.00
	1	Very unsatisfactory - Limited to no technology present in instructional spaces		<u> </u>		1			Projector and mobile screen.		
	2	Unsatisfactory - One type of technology present									
	3	Average - Multiple types of technology, smart boards. Poor condition. Limited to only certain areas of school.									
	4	Satisfactory - Multiple types of technology, smart boards. Good condition.									
	5	Very Satisfactory - Multiple types of technology, smart boards. Excellent condition									
	N/A	Does not apply									
14.	2 Is there an a spaces?	adequate number of power and data outlets in learning		2					Comments	1.00	2.00
	1	Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall)							2 walls with multiple outlets and 2 walls with only one.		
	2	Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall)									
	3	Average - Outlet configuration support digital devices but limited capacity throughout school (3 per wall)									
	4	Satisfactory - Outlet configuration support digital devices with adequate coverage and capacity in limited locations (>3 per wall)									
	5	Very Satisfactory - Excellent outlet configuration to support digital devices throughout school (>3 per wall)									
	N/A	Does not apply							<u> </u>		

1 - Technology	r (cont.)	1	2	3	8 4	5	N/A			
4.3 Are there ac	dequate charging locations for devices?			3				Comments	1.00	3.0
1	Very unsatisfactory - Not enough charging locations throughout school for 1:1				•			Power distribution is limited. Computers located on corr is where the power outlets are.	idor wall becau	ise tha
2	Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices									
3	Average - Charging locations well organized but not enough capacity for 1:1									
4	Satisfactory - Charging locations, haphazard locations, but supports 1:1.									
5	Very Satisfactory - Charging locations throughout school to support 1:1.									
N/A	Does not apply									
4.4 Is there ade	quate AV for presentations spaces – cafeteria, gym, aux gym?				4			Comments	1.00	4
1	Very unsatisfactory - AV not present in one or more space							A/V in cafeteria and gym looks to be in good condition. and speakers in good condition.	Large projection	n scr
2	Unsatisfactory - AV undersized for room. Poor condition							3 1 1 1		
3	Average - AV adequately sized / poor condition OR AV undersized / average condition									
4	Satisfactory - AV adequately sized for room. Average Condition.									
5	Very Satisfactory - AV adequately sized for room. Excellent condition.									
N/A	Does not apply									
4.5 Is there digit	tal media signage at the reception area?	1						Comments	0.00	0
1	Very unsatisfactory - No digital media present in reception area							None seen		
2	Unsatisfactory - Undersized, poor condition									
3	Average - Adequately sized / poor condition OR undersized / adequate condition									
4	Satisfactory - Media signage present, good sized, good condition									
5	Very Satisfactory - Generously sized, excellent condition									
	Does not apply									

5 - Admin	nistra	tion Spaces	1	2	3	4	5	N/A		20.00	55
5.1 Is the visito		eception area that functions as a security checkpoint for all							Comments	1.00	
	1	Very unsatisfactory - No security checkpoint									
	2	Unsatisfactory - Checkpoint is too small, poor condition									
	3	Average - Needs updates or renovations to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
N	N/A	Does not apply	_				-				
5.2 Does the administration area feel welcoming?					4			Comments	1.00	4	
	1	Very unsatisfactory - No welcome space							Good size, transparency, and a variety of seating.		
	2	Unsatisfactory - Too small, poor lighting and transparency, limited informal seating, poor condition									
	3	Average - Adequate size and layout, needs updates or renovations to feel welcoming									
	4	Satisfactory - Good size and layout, good lighting and transparency, informal seating provided									
	5	Very Satisfactory - Generous size and layout, plenty of light and transparency, informal seating provided, excellent condition									
Ν	N/A	Does not apply									
		paces that require it, does the administration area have acoustic privacy?		2					Comments	1.00	2
	1	Very unsatisfactory - No acoustic separations							Acoustic separation is not great. Hard surfaces create of	an echo.	
	2 Unsatisfactory - Acoustic separations do not perform well										
	3	Average - Some acoustic separations function okay, but portions need updates or renovations									
	4	Satisfactory - Good acoustic separations									
	5	Very Satisfactory - Excellent acoustic separations									
N	N/A	Does not apply	-								
5.4 Are co	onfere	ence rooms easily accessed for public / parent use?				4			Comments	1.00	4.
Very unsatisfactory - Not accessible for public/parent use									Two conference spaces in main office. Both have secondary access from corridor. Good transparency.		
	2	Unsatisfactory - Limited access, no transparency, poor condition, difficult to find									
	3	Average - Adequate accessibility, needs updates or renovations to function well									
	4	Satisfactory - Good accessibility, good transparency, good size and condition									
	5	Very Satisfactory - Excellent accessibility, excellent transparency, generous size, excellent condition									