

Educational Suitability Summary Report

Paredes Middle School

Date: 01/25/2021 Score 61% Average

Paredes Middle School, serving an enrollment of approximately 830 students, is in far south Austin. It was built in 2000 and consists of approximately 150,100 square feet on nearly 55 acres. The school is known for supporting multiple programs, including ACE after-school, AVID, Career and Technical Education (CTE) including robotics, Communities in Schools (CIS), dual-language education, band, dance, theater arts and Project Help.

The campus is open and consists of different buildings with some connected via exterior, canopied walkways. The campus is near a public park and has extensive playfields that are far from the building.

The campus has a main administration building. Near this is a smaller building for the nurse and special education spaces (Life Skills classrooms including a kitchenette and accessible restrooms). The layout is well configured, but there is a lack of storage. Items are stacked in a space between the two special education studios within the life skills kitchen. The calming/wellness room is being used as the School Resource Officer room. The campus has a large, internal courtyard space that has potential to provide multiple outdoor learning areas, but lacks shading, furniture, technology access and a strong Wi-Fi connection. Gated access is also lacking. The fine arts building supports choir, band and orchestra and has multiple practice rooms as well as an auxiliary space for other group practice. The library is undersized to accommodate more than one large group and the connected breakout space is being used as a professional learning center for the administration.

There are specialty studios in a basement area that comprises two art rooms and spaces for wood shop. The wood shop room is connected to other spaces for computer rooms but is being used as storage currently due to Covid protocols. The campus has the space to create a maker lab with adjacent space for technology. These spaces are toward the back of the campus and next to the only developed outdoor learning space.


Interview Overview

An interview was held with assistant principals Susie Smith, Tisha Gonzales-Reynolds and Rian Evans, bookkeeper Tina Cortinas, and head custodian Celerina Cazares. They identified spaces that are not suitable for programs. The theater arts program has a studio connected to the stage within the cafeteria but lacks functions for dance. Special education is well configured but lacks storage, has drainage issues and needs a new washer. The special education unit has a fully functioning restroom with shower for the students but needs a dedicated staff restroom. The staff expressed that community members would like gender-neutral restrooms. The campus has one area set up for performances at the cafeteria stage, but its capacity of 300 cannot accommodate all the campus at once. CIS, AVID, SCORES and SBS are all in portables.

Educational Suitability Summary Report

Paredes Middle School

The campus would like to create more interest in construction trades/hands-on programs by utilizing the existing wood shop that is being used for storage. This area also could be used as a STEM and robotics space. They would like space for a culinary arts program. They expressed a need for working gym bleachers. The bleachers are not easily operable and are in worn condition. Digital media support is also needed in the gym.



Assessment Findings

The Educational Suitability Assessment of Paredes Middle School earned a 61% overall score and places the campus in a category of Average. The assessment consists of seven General Building categories and eight Academic categories to determine areas that need more attention.

Unsatisfactory Categories (36-50%):

Administration Spaces

Score is unsatisfactory.

Acoustic privacy was observed to be poor within the administrative building.

Academics & Learning

Score is unsatisfactory.

Many studios have no provided storage. A few spaces listed in the Ed Spec are missing from the existing school program, including professional learning centers and maker space. There is limited to no collaboration spaces or breakout spaces, and visibility from the studios to the corridor is limited.

Furniture, Fixtures, Equipment

Score is unsatisfactory.

Furniture will need to be replaced in the near future. Much of the furniture cannot be easily reconfigured into group or single study arrangements.

Security

Score is unsatisfactory.

Average Categories (51-65%):

Controllability of Systems

Score is average.

Educational Suitability Summary Report

Paredes Middle School

Studios have individual control over the temperature and blinds were observed on most studio windows. However, one single switching was available for artificial lighting controls.

Athletics and Wellness

Score is average.

The majority of the athletic spaces are of a generous size and in good condition. Outdoor athletic fields are adequate but do not support UIL competitions. Restrooms and water fountains need to be closer to the fields. The four tennis courts are in very poor condition.

Media Resources

Score is average.

The library appears to support technology well but is not easily accessible to the public. The library space is configured as one, large open space but does not provide for individual study or any large groups.

Technology

Score is average.

Smart boards were noted in most every studio, but digital media signage is missing and charging outlets for devices are lacking.

Satisfactory Categories (66-80%):

Exterior

Score is satisfactory.

Bus, car and pedestrian traffic appears to be well-separated. However, minimal signage makes the school difficult to find.

Outdoor Learning and Activity

Score is average.

The outdoor studio on campus is large and well-covered. Outdoor learning space is generous but somewhat disconnected from most of the school.

General Building

Score is satisfactory.

Corridors are well sized, and each building can be locked off after-hours.

Environmental Quality

Score is satisfactory.

Good acoustic privacy was observed during the site visit. The majority of studios have access to daylight and views.

Visual and Performing Arts

Score is satisfactory.

Many of the music and theater spaces are of good size and condition. Space for dance is not provided. The stage in cafeteria is in adequate shape.

Food Services

Educational Suitability Summary Report

Paredes Middle School


Score is satisfactory.

Options for a variety of seating environments are lacking. The size and condition of the dining and food prep areas appears to be in good condition.

CTE and Career Connected Learning

Score is satisfactory.


Many CTE options are available and are closely aligned with CTE cluster pathways.








Sporting fields are generously sized but lack facilities for spectators. The school requests bleachers.



Wood shop studio being used as storage for furniture, bicycles and an AISD police all-terrain vehicle. Program space is underutilized as it has been used for storage prior to COVID.



Special education lacks storage. Part of the life skills kitchen area serves as storage for various items. Area also needs a sensory room.




Academics and Learning: Typical studio has adequate daylight, dated furniture and some upgraded technology.



General Building: Corridors are good size and condition. Very little visibility between studios and corridors, limiting the possibility of independent study. School reports hallways lack ventilation.



Outdoor studio is provided by Austin Energy pavilion (typical of many schools throughout the District) and is in average shape. School reports this space has been updated since the evaluation occurred.



Visual and Performing Arts: Band/orchestra facilities are good size and condition. Bathroom in this area has the problematic sewage smell.



Studio furniture is unsatisfactory. Attached desks and chairs limit the ability to reconfigure for various teaching formats.



Athletics and Wellness: Gym is large and in good condition, but bleachers do not work well. Half are not usable.

Paredes Middle School



Food Services: Cafeteria is in good shape but only has one type of seating available. Stage is in good shape.



Media Resources: Library is open light filled space. Some furniture is heavy and not easily reconfigurable. Library was updated last year.



Austin ISD Educational Suitability Assessment Criteria

General Building

School Name	Walk Attendees:	Date:	
Paredes Middle School	Lane Green & Anacleto Rojas Jr.	1/25/2021	

1 - E	xterior		1	2	3	4	5	N/A		8.75	74%
1.1	Does the sit pedestrian	te permit desirable separation of vehicular, bus and traffic?				4			Comments	1.00	4.00
	1	Very unsatisfactory - Bus, car and pedestrian all happen							Separate drop-offs but no canopy or holding space p	orovided.	
	2	at the same location Unsatisfactory - Cars and buses mix, pedestrians are separated									
	3	Average - Buses, cars, and pedestrians are separate but stack space is small									
	4	Satisfactory - Buses, cars, and pedestrians are separate but drop off does not have a canopy or a holding place like a commons or cafeteria									
	5	Very satisfactory - Buses, cars, and pedestrians are separate and drop off area has a canopy and									
	N/A	Does not apply									
1.2		ing easily identified with appropriate signage and vwayfinding?		2					Comments	0.25	0.50
	1	Very unsatisfactory - Campus has no signage / wayfinding							Entrance to school is hidden.		
	2	Unsatisfactory - Signage/wayfinding is faded/hidden									
	3	Average - Signage / wayfinding visible but not apparent									
	4	Satisfactory - Signage / wayfinding is visible but not good condition									
	5	Very satisfactory - Signage and wayfinding is visible and easy to use									
	N/A	Does not apply									

O2/11/2022 ²

1 - E	xterior (co	nt.)	1	2	3	4	5	N/A			
1.3	ls the dump	oster accessible for trash / compost disposal?				4			Comments	0.50	2.00
	1 2 3 4 5	Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster Unsatisfactory - Compost is present. Route has obstacles to dumpster Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent. Satisfactory - Compost and dumpster are directly adjacent and route is barrier free Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free. Dumpster are shaped / positioned so people of all heights can access it.									
	N/A	Does not apply									
2 - 0	Dutdoor Le	arning and Activity	1	2	3	4	5	N/A		10.00	80%
2.1	Are outdoo the ed spec	or studios and support spaces appropriately configured per e?			3				Comments	1.00	3.00
	1	Very unsatisfactory - No dedicated outdoor studios							Connected to other outdoor learning spaces, large co	over.	
	2	Unsatisfactory - Too small, poor condition, disconnected									
	3	from learning spaces, no flexibility, no shade provided Average - Adequate size, adequate condition, needs									
	4	some renovations or updates to function well, 50% or less shade coverage over studio area Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade									
	5	coverage over studio area Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full shade coverage over studio area									
	N/A	Does not apply									
2.2		playgrounds (elementary only) and support spaces per the ed spec?						N/A	Comments	0.00	0.00
	1	Very unsatisfactory - No dedicated active playground									
	2	Unsatisfactory - Too small, poor condition, no shade									
	2	provided									
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less									
	4	shade coverage over play structure Satisfactory - Good size, good condition, more than 50% shade coverage over play structure									
	5	Very satisfactory - Generous size, excellent condition, full shade coverage over play structure									
	N/A	Does not apply									

2 - Outdoor Learning and Activity (cont)	1	2	3	4	5	N/A	1		
Are gardens and support spaces appropriately configured per the ed			0				Commande		
2.3 spec? (evaluation on infrastructure not condition of plants)			3				Comments	0.00	0.00
l Very unsatisfactory - No dedicated gardens							Average size and somewhat inaccessible to most of t	he campus (do	wn
 Unsatisfactory - Too small, poor condition, disconnected 							flight of stairs). (Monitoring answer, does not affect s	core for Outdo	or
from learning spaces, no flexibility, no accessible water							Learning and Activity.)		
source									
Average - Adequate size, adequate condition, needs									
some renovations or updates to function well, water									
source is difficult to access 4 Satisfactory - Good size, good condition, connected to									
4 Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, water source is									
accessible with 100 ft hose									
5 Very Satisfactory - Generous size, excellent condition,									
connected to learning spaces, excellent flexibility, water									
source is less than 50ft from the garden or has irrigation									
N/A Does not apply									
Are the rain gardens and/or cisterns appropriately configured per the	-								
ed spec?	ı						Comments	0.00	0.00
l Very unsatisfactory - No rain gardens or cisterns							No rain gardens or cisterns noted. (Monitoring answe	er, does not aff	ect
 Unsatisfactory - Too small, poor condition, not 							score for Outdoor Learning and Activity.)		
functioning, disconnected							,,,		
3 Average - Adequate size, adequate condition, is									
connected, needs some renovations or updates to									
function well									
4 Satisfactory - Good size, good condition, functions									
properly 5 Very Satisfactory - Generous size, excellent condition.									
5 Very Satisfactory - Generous size, excellent condition, exceptional functionality, connected to learning spaces,									
educational signage provided									
N/A Does not apply									
2.5 Does the school have animal husbandry? (optional)	1						Comments	0.00	0.00
1 No									
5 Yes									
2.6 Does the school have nature loop trails? (optional)					5		Comments	0.00	0.00
1 No									
5 Yes	_	1			1				
Does the school have a learning pond? (optional) No							Comments	0.00	0.00
i No 5 Yes									
2.8 Does the school have a grass play field and walking trail?					5		Comments	1.00	5.00
1 No							Commonts		3.00
5 Yes									

3 - G	eneral Bu	ilding	1	2	3	4	5	N/A	4	11.25	
3.1	Are interior	circulation routes wide enough to safely and effectively							Comments		
3.1	accommod	late student movement?							Comments		
	1	Very unsatisfactory - Primary circulation is 5'-0" to 6'-0"									
		wide									
	2	Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide									
	3	Average - Primary circulation is 7'-0" to 8'-0" wide									
	4	Satisfactory - Primary circulation is 8'-0"-10'-0" wide									
	5	Very satisfactory - Primary circulation is 10'-0"+ wide									
	N/A	Does not apply									
	Are commu	unity use areas arranged so that the school can allow night									
3.2		vithout full school access?							Comments		
	1	Very unsatisfactory - Cafeteria, gym, and library cannot		•	•			•			
		be accessed after hours									
	2	Unsatisfactory - Only one of the public spaces (Cafeteria,									
		Gym and Library) can be accessed from parking and									
	•	secured after hours									
	3	Average - Only two of the public spaces can be accessed from parking and secured after hours									
	4	Satisfactory - All of the public spaces can be accessed									
	7	from parking and secured from the rest of the building									
		but not individually									
	5	Very satisfactory - Cafeteria, gym, and library can be									
		accessed from parking and locked off from rest of									
		campus for night/evening use with their own entrance									
	N/A	Does not apply									
2.2	Is there a c	ommunity room that is a dedicated meeting space outside							Commonto		
3.3	of school fu								Comments		
	1	Very unsatisfactory - No dedicated community room									
	2	Unsatisfactory - Community room but within school									
		function, no access after school hours									
	3	Average - Community room, moderate size, but need									
	4	some renovations or updates to function well Satisfactory - Community room, good size /layout, meets									
	4	needs /functions well									
	5	Very Satisfactory - Community room, generous size, nice									
		condition, functions appropriately outside of school									
		function									
	N/A	Does not apply			,						
3.4		eneral appearance of the school convey pride for the				4			Comments		
<u> </u>	students ar	nd community?								0.25	1.00
	1	Very unsatisfactory - General appearance is poor							Exterior looks well maintained.		
	2	Unsatisfactory - General appearance is aged but ok									
	3	Average - General appearance is good									
	4	Satisfactory - General appearance shows pride in campus and student works									
	5	Very Satisfactory - General appearance shows pride in									
	Ū	campus and student works and is welcoming to the									
		community									
	N/A	Does not apply									

4 - Security		1 2	3 4	1 5 N	I/A		16.25	
4.1 Does the	facility have key card access at all major entries?				Co	omments	0.25	
1	Very unsatisfactory - No entries							
2	Unsatisfactory - 1/4 of major entries							
3	Average - 1/2 of major entries							
4	Satisfactory - 3/4 of major entries							
5	Very satisfactory - All of major entries							
N/A	Does not apply				•			
4.2 How adea	quate is site lighting and security for the campus overall?				Co	mments	1.00	
1	Very unsatisfactory - No exterior lighting, no secure perimeter)
2	Unsatisfactory - Lighting is limited to front entry only, parking lot lighting poor, security is minimal							
3	Average - Lighting at all night-use entries and parking lot, but poor condition. Security is moderate							
4	Satisfactory - Lighting at all night-use entries and							
	parking lots, good condition, signage less visible,							
	perimeter is well secured but needs updates							
5	Very satisfactory - Signage, parking lots, and entries are							
	well lit, visible and easy to use, perimeter is very secure							
N/A	Does not apply							
Is the mai	in office located at the school entry and configured with a						1	
1 /1 /2	stibule to the main corridor?				Co	mments	1.00	
1	Very unsatisfactory - No secure vestibule, office located		1 1					
	far from main entry, allows visitors access to school							
	unsupervised							
2	Unsatisfactory - No secure vestibule, office located							
	somewhat far from main entry, minimal supervision of							
	visitors							
3	Average - Office close to entry, views of front door, but							
4	no secure vestibule Satisfactory - Office is well-located with a secure							
4	vestibule, but needs updates							
5	Very satisfactory - Office well-located with secure							
ŭ	vestibule and all appropriate security features							
N/A	Does not apply							
Is there e	nough interior transparency for faculty to passively supervise							
1 /1 /1	and their activities who are not in studios?	2			Co	mments	1.00	2.00
1	Very unsatisfactory - No transparency of walls				Windows observed in c	orridor doors.		
2	Unsatisfactory - Limited transparency in certain locations							
3	Average - Good transparency in certain locations but							
3	inadequate or missing in other locations of school							
4	Satisfactory - Adequate transparency throughout the							
·	school							
5	Very satisfactory - Excellent transparency throughout the school							
N/A	Does not apply							

Perkins&Will 02/11/2022 ⁶

5 -	Environme	ntal Quality	1	2	3	4	5	N/A		25.00	72%
5.] How are a	coustics in studios in general?				4			Comments	1.00	4.00
	1 2 3 4 5 N/A	Very unsatisfactory - Recognized word/sound from adjacent studio/corridor Unsatisfactory - Audible sound from adjacent studio/corridor Average - Slight sound from outside room Satisfactory - Walls to deck insulated only white noise from mechanical system Very satisfactory - Able to hear quiet speaking from across the room Does not apply							Observed to be satisfactory.		
5.		o artificial lighting adequate quality?			3				Comments	1.00	3.00
	1 2 3 4 5 N/A	Very unsatisfactory - Sporadic lights work, glare, less than 20 FC Unsatisfactory - 10-19 FC or serious glare Average- 20-29 FC minor glare Satisfactory - 30-39 FC and no glare Very satisfactory - 40+ FC and no glare Does not apply		l					Observed to have minor glare.		
5.	3 Is there acc	cess to natural light in studios?				4			Comments	1.00	4.00
	1 2 3 4 5	Very unsatisfactory - No learning spaces have natural light Unsatisfactory - 1-25% of learning spaces have natural light or windows are too small to let in light Average - 26-50% of learning spaces have natural light Satisfactory - 51-75% of learning spaces have natural light Very satisfactory - 76-100% of learning spaces have natural light							Most studios have access to natural light.		
5.	N/A 4 Is there acc	Does not apply tess to outside views from learning spaces?				4			Comments	100	4.00
	1 2 3 4 5	Very unsatisfactory - No learning spaces have views Unsatisfactory - 1-25% of learning spaces have views or windows are too small to see out Average - 26-50% of learning spaces have views Satisfactory - 51-75% of learning spaces have views Very satisfactory - 76-100% of learning spaces have views Does not apply							Several windows have views to nature.	1.00	4.00

5 - Environme	ntal Quality (cont.)	1	2	3	4	5	N/A	A		
5.5 Does the b	uilding have odor or pest problems?			3				Comments	1.00	3.00
1	Very unsatisfactory - Evidence of both pests and odors							Sewage odor from restrooms noticed near choir roon	n. School repor	ts the
2	Unsatisfactory - Evidence of pests or odors							odor has been an ongoing problem that has been ur	nsuccessfully	
3	Average - Limited evidence of pests, no odors							addressed.	·	
4	Satisfactory - No evidence of pests / odors, school									
	cleanliness in good condition									
5	Very Satisfactory - No evidence, school cleanliness in									
	excellent condition									
N/A	Does not apply									
6 - Controllab	ility of Systems	1	2	3	4	5	N/A	A	12.50	60%
6.1 Does the st	tudio thermostat allow for individual control?					5		Comments	0.50	2.50
1	No						1			
5	Yes									
6.2 Are shades	s provided to control natural light in learning spaces?				4			Comments	1.00	4.00
1	Very unsatisfactory - No, windows are covered with							Blinds in good condition		
	boards/paper									
2	Unsatisfactory - No, windows have no light control									
3	Average - Yes, but poor condition blinds									
4	Satisfactory - Yes, blinds									
5	Very satisfactory - Blackout shades									
N/A	Does not apply									
6.3 What is the	e quality of lighting controls in the studios?	1						Comments	1.00	1.00
1	Very unsatisfactory - Single switch only per room							Single switch per room		
2	Unsatisfactory - Alternating rows switch off									
3	Average - Alternating lamps in single fixtures switch off									
4	Satisfactory - Tri level switching									
5	Very satisfactory - Dimmable									
N/A	Does not apply							1		

7 - Furniture, Fixtures & Equipment	1	2	3	4	5	N/A		18.75	44%
7.1 What is the current condition of the furniture?			3				Comments	0.75	2.25
 Very unsatisfactory - Damaged or broken, non- 							Several pieces in poor condition, attached chairs to de	sks.	
functioning									
2 Unsatisfactory - Torn/ bent/ wrong size									
3 Average - Scratched/dented/marked									
4 Satisfactory - Not new, but sturdy and clean									
5 Very satisfactory - New									
N/A Does not apply									
Are a variety of furniture types being accommodated throughout the		2					Comments		
school - learning commons, dining commons, other multi-use spaces?								1.00	2.00
1 Very Unsatisfactory - Same furniture used in all spaces							The only furniture variety noted in library.	1.00	2.00
o and a second s									
onsatisfactory Turnitare variety in one mater ass space									
3 Average - Furniture variety in more than one multi-use									
space 4 Satisfactory - All multi-use spaces have greater than one									
type of furniture									
5 Very satisfactory - All multi-use spaces have greater than									
two types of furniture									
N/A Does not apply									
7.3 How well does furniture accommodate rapid reconfiguration of a		2					Comments		
space?		_						1.00	2.00
1 Very Unsatisfactory - Furniture is fixed or very heavy							Minimal ability to reconfigure		
2 Unsatisfactory - Furniture does not allow desks to be									
configured as individuals, small groups, or large groups									
3 Average - Mix of furniture that can reconfigure but is									
cumbersome to move 4 Satisfactory - Furniture is flexible for multiple									
4 Satisfactory - Furniture is flexible for multiple configurations of space									
5 Very satisfactory - Furniture is flexible for multiple									
configurations of space, easy to move and stack									
N/A Does not apply									
				1					
7.4 Is the furniture ergonomic and size appropriate for grade level?		2					Comments	1.00	2.00
Very unsatisfactory - Desk with attached chair				ı		L	Some desks with attached chairs noted		
combinations too small for grade level									
2 Unsatisfactory - Desk with attached chair combinations									
3 Average - Mix of studios with tables/loose chairs and									
desks with fixed seats									
4 Very satisfactory - Tables with loose chairs									
5 Very satisfactory - Tables with loose chairs that allow									
students to be active									
N/A Does not apply									

Perkins&Will 02/11/2022 ⁹

Waste		1	2	3	4	5	N/A	5.00	4
	and corridors have blue recycle bins with bilingual s and/or image sorting instructions?	1						Comments 0.50	(
1 2 3 4	Very unsatisfactory - There are no recycling and landfill bins and signage are sparse or infrequent, OR there are only landfill bins with no recycling bins. Unsatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage. Average - 50% of corridors and studios have both a landfill bin and a recycle bin in an accessible location. The containers have clear signage. Satisfactory - 75% of studios and corridors have a visible landfill and recycle collection containers in an accessible location. The containers have clear signage. Very satisfactory - All studios / corridors (100%) have visible landfill and recycle collection containers in accessible locations. The containers have clear signage, and the style and format is consistent and uniform across							A score for this category is being recorded, but this category is no calculated in the overall ESA average. None observed	
of each: gr	campus. Does not apply afeteria (or wherever meals are served) have at least one reen compost bin, blue recycle bin, and landfill bin? Are the ed clearly with bilingual and/or image sorting?			3				Comments	
1 2 3 4	Very unsatisfactory- There may be landfill bins, but there are no compost and/or recycle bins. There is not clear sorting signage. Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located next to one another. Signage is absent or inconsistent. Average- There is at least one waste station with all three bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and consistent. Satisfactory- There are several waste stations as described above							Noted one set of recycle/compost/landfill bins.	



Austin ISD Educational Suitability Assessment Criteria

Academics - Middle School / High School

School Name	Walk Attendees:	Date:
Paredes Middle School	Lane Green & Anacleto Rojas Jr.	2/1/2021

- Academics	& Learning	1	2	3	4	5	N/A		65.00	48%
8.1 Are studios	appropriately configured per the ed spec?			3				Comments	1.00	3.00
1	Very unsatisfactory - Too small, no flexibility,						•	Transparency could be improved. Typical classroom	is 780 SF - sligh	itly
	disconnected							undersized.		
2	Unsatisfactory - Too small, only one area for all teaching									
	methods, limited flexibility, disconnected									
3	Neutral - Adequate size, multiple areas for different									
	teaching methods, adequate flexibility, limited									
	transparency and connection to other studios and									
	shared learning spaces, needs updates or renovations to function well.									
4	Satisfactory - Good size, multiple areas for different									
7	teaching methods, good flexibility, good transparency									
	and connection to other studios and shared learning									
	spaces									
5	Very Satisfactory - Generous size, multiple areas for									
	different teaching methods, excellent flexibility, generous									
	display area and visual teaching tools, excellent									
	transparency and connection with other studios and									
	shared learning spaces									
N/A	Does not apply		1			ı			1	
3 2	nave appropriate support spaces such as storage per the		2					Comments	1.00	
ed spec?	Very unsatisfactory - None provided							Manageration in the contract of the contract o	1.00	2.00
2	, , ,							Many studios noted without built-in storage.		
	Unsatisfactory - Too small, disconnected, poor condition									
3	Neutral - Adequate size, average condition, needs									
4	updates or renovations to function well									
4 5	Satisfactory - Good size, connected, good condition									
Э	Very Satisfactory - Generous size, connected, excellent condition									
	Condition									

Perkins&Will 02/11/2022 ²

8 - 8	Academics	& Learning (cont.)	_1	2	3	4	5	N/A			
8.3	Do typical I	earning neighborhoods have small and medium (high	1						Community		
8.3	school only) group rooms and open collaboration space?	ı						Comments	1.00	1.00
	1	Very unsatisfactory - No breakout rooms or open									
		collaboration spaces are provided									
	2	Unsatisfactory - Too small or too few, poor condition, no									
		flexibility, lacks visual connection to learning									
		neighborhood, poor acoustic privacy									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition and flexibility,									
		transparency and connection to learning neighborhood,									
		acoustic privacy									
	5	Very Satisfactory - Generous size, excellent condition and									
		flexibility, transparency and connection to learning									
		neighborhood, acoustic privacy									
	N/A	Does not apply							<u>, </u>		
8.4		Labs and support spaces appropriately configured per			3				Comments		
0	the ed spec	?			Ü				Comments	1.00	3.00
	1	Very unsatisfactory - No dedicated science room							In good condition but not connected to prep lab spac	es.	
	2	Unsatisfactory - Too small, poor condition, no connected									
		support space									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected									
		support spaces									
	5	Very Satisfactory - Generous size, excellent condition,									
	N1/A	connected support spaces									
	N/A	Does not apply		1	1	1	1	1	T		
8.5		Spaces and support spaces appropriately configured per	1						Comments		
	the ed spec	? (cross reference with CTE below)								1.00	1.00
	1	Very unsatisfactory - No dedicated maker spaces							No maker space available.		
	2	Unsatisfactory - Too small, poor condition, disconnected									
		from learning spaces, no flexibility									
	3	Average - Adequate size, adequate condition, needs									
	_	some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected to									
	-	learning spaces									
	5	Very Satisfactory - Generous size, excellent condition,									
	N/A	connected to learning spaces Does not apply									

8 - Academics	& Learning (cont.)	1	2	3	4	5	N/A	4		
8.6 Is there a P	Professional Learning Center in the learning neighborhood?	1						Comments	1.00	1.00
1 2 3 4 5	Very unsatisfactory - No dedicated space for Professional Learning Center Unsatisfactory - Too small, poor condition, disconnected Average - Adequate size, adequate condition, needs some renovations or updates to function well Satisfactory - Good size, good condition, connected Very Satisfactory - Generous size, excellent condition, connected							No dedicated PLCs located in proximity to studios, currently library.	y located i	'n
	adequate places to display the evidence and artifacts of both 2D and 3D)?				4			Comments	1.00	4.00
1 2 3 4 5 N/A	Very unsatisfactory - No dedicated space Unsatisfactory - Too small, non-dedicated, poor condition Average - Adequate size, adequate condition, needs updates or renovations to function well Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition Does not apply							Several cabinets noted.		
Does the b	uilding / learning neighborhood provide adequate ies for students/teachers to collaborate in varying group		2					Comments	1.00	2.00
1 2 3 4 5 N/A	Very unsatisfactory - No space to support collaboration in various sizes. Unsatisfactory - Too small, inflexible, only one option, does not support a variety of group sizes Average - Adequate space for collaboration, needs updates or renovations to function well. Satisfactory - Good size, good condition, multiple options to support a variety of group sizes Very Satisfactory - Generous size, excellent condition, multiple options to support a variety of group sizes Does not apply							None observed but furniture improvements could allow for	this.	
8.9 Does the b	uilding provide opportunities for informal interaction?		2					Comments	1.00	2.00
1 2 3 4 5	Very unsatisfactory - No space Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well Average - Adequate size and condition, needs updates or renovations to function well. Satisfactory - Good size, good condition, layout and furnishings support informal interactions Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions							None observed but furniture improvements could allow for	this.	

8 - Academics	& Learning (cont.)	1	2	3	4	5	N/A	4		
8.10 Does the bound work indep	uilding provide adequate opportunities for students to pendently?		2					Comments	1.00	2.00
1 2 3 4 5 N/A	Very unsatisfactory - No breakout rooms/small study spaces Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood Average - Adequate size and condition, needs updates or renovations to function well. Satisfactory - Good size and condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood Very Satisfactory - Generous size, excellent condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood Does not apply							Visibility into corridor is minimal.	1.00	2.00
Special Edi	ucation									
8.11 Are Special spec?	l Education spaces appropriately configured per the ed			3				Comments	1.00	3.00
1 2 3 4	Very unsatisfactory - Too small, no flexibility, disconnected Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well. Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces							Facilities are good but not connected to other studios Sensory room and storage are needed.	s and learning	spaces.
N/A Are Special	Does not apply I Education support spaces, such as storage, space for		1	1	T					
812	yer, appropriately configured per the ed spec?		2					Comments	1.00	2.00
1	Very unsatisfactory - None provided							No storage provided. Equipment needs to be replace	ed.	
2	Unsatisfactory - Too small, disconnected, poor condition									
3 4 5	Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent condition									
N/A	Does not apply									

Perkins&Will 02/11/2022 ⁵

8 - Academics & Learning (cont.)	1	2	2 3	4	5	N/A			
8.13 Are Accessible restrooms and changing rooms readily available to the Special Education spaces?					5		Comments	1.00	5.00
1 No							Flooding is an issue.		
5 Yes STEAM Center									
8.14 Does the campus have space to support a "STEAM" center?				4			Comments	0.00	0.00
1 Very unsatisfactory - No available space for STEAM center and inadequate studio / collaborative space 2 Unsatisfactory - Collaborative areas / studios for CTE/CCL are completely separate but adequate size 3 Neutral - Collaborative areas / studios for CTE/CCL are adjacent but function separately 4 Satisfactory - Collaborative areas / studios for CTE/CCL function and have space availability to create STEAM center 5 Very Satisfactory - Functioning STEAM center offers studios, labs, common collaborative areas to support multimedia distance and hands-on project based learning	ı				•	ı	There are several rooms that appear to not be fully u converted.		
N/A Does not apply								17.50	==0/
9 - CTE and Career Connected Learning								17.50	71%
How close is your campus to a CTE cluster pathway that is aligned with your CTE programs (Middle School only)?				4			Comments	1.00	4.00
 Very unsatisfactory - No correlation to CTE cluster pathway, no CTE programs. Unsatisfactory - School supports less than half of the CTE programs that are listed in the cluster pathway. Average - School support half of CTE programs listed in the cluster pathway, but missing some. Satisfactory - School support a majority of CTE programs listed in the CTE cluster pathway. Very Satisfactory - School is aligned with CTE cluster pathway. N/A Does not apply 									
9.2 Do campus facilities align with the CTE Ed Spec Requirements for the current pathways offered?: Architecture and Construction	1							0.25	0.25
1 No 5 Yes N/A Does not apply									
9.3 Arts, Audio and Video Technology and Communications					5			0.25	1.25
9.4 Business, Management and Administration					5			0.25	1.25
9.5 Education and Training					5			0.25	1.25
9.6 Health Science	1							0.25	0.25

9 - CTE and Career Connected Learning (cont.)	1	2	3	4	5	N/A			
9.7 Hospitality and Tourism					5			0.25	1.25
9.8 Human Services (high school only)						N/A		0.00	0.00
9.9 Information Technology					5			0.25	1.25
9.10 Agriculture, Food and Natural Resources	1							0.25	0.25
9.]] Science, Technology, Engineering, and Mathematics					5			0.25	1.25
9.12 Transportation, Distribution and Logistics	1							0.25	0.25
9.13 Finance (high school only)						N/A		0.00	0.00
9.14 Government and Public Administration / JROTC Military programs (high school only)						N/A			
9,15 Law, Public Safety, Corrections and Security (high school only)	+					N/A		0.00	0.00
9.16 Manufacturing (high school only)	+					N/A		0.00	0.00
7.10	-					,		0.00	0.00
9.17 Marketing, Sales and Services (high school only)						N/A		0.00	0.00
10 - Visual and Performing Arts								35.00	71%
10.1 Is there flexibility of space to also be used by CTE and Athletics?	1						Comments	0.00	0.00
1 No 5 Yes							Monitoring answer, but doesn't affect overall score.		
10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec?				4			Comments	1.00	4.00
1 Very unsatisfactory - Too small, missing program spaces							Good size, updated condition, storage may be needed.		
2 Unsatisfactory - Too small, poor condition									
Neutral - Adequate size, adequate condition, needs									
updates or renovations to function well. 4 Satisfactory - Good size, good condition									
5 Very Satisfactory - Generous size, excellent condition									
N/A Does not apply									
10.3 Are orchestra and support spaces appropriately configured per the ed spec?				4			Comments	1.00	4.00
Very unsatisfactory - Too small, missing program spaces							Appears to be of good size and condition.		
2 Unsatisfactory - Too small, poor condition									
Neutral - Adequate size, adequate condition, needs updates or renovations to function well.									
4 Satisfactory - Good size, good condition									
5 Very Satisfactory - Generous size, excellent condition									
N/A Does not apply									

10 - Visual and	d Performing Arts (cont.)	1	2	3	4	5	N/A	4		
Are choir a	nd support spaces appropriately configured per the ed			3				Comments		
spec?				5				Comments	1.00	3.00
1	Very unsatisfactory - Too small, missing program spaces							Adequate but only minimal storage and risers.		
	Harakista kana Tarangula ang ang dikina									
2 3	Unsatisfactory - Too small, poor condition									
3	Neutral - Adequate size, adequate condition, needs updates or renovations to function well.									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply									
Are dance	and support spaces appropriately configured per the ed							_		
10.5 spec?		1						Comments	1.00	1.00
1	Very unsatisfactory - Too small, missing program spaces	1						No space provided. Program is expanding and needs	s its own space	
	11 of 6 of T									
2	Unsatisfactory - Too small, poor condition									
3	Neutral - Adequate size, adequate condition, needs updates or renovations to function well.									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply									
Are theate	r and support spaces appropriately configured per the ed	П						_		
10.6 spec?					4			Comments	1.00	4.00
1	Very unsatisfactory - Too small, missing program spaces	1						Good size and condition, adjacent to the stage.		
2	Unsatisfactory - Too small, poor condition									
3	Neutral - Adequate size, adequate condition, needs									
	updates or renovations to function well.							School reports they need more space since this progr	am is expandir	ng.
4	Satisfactory - Good size, good condition							Lunches disrupt use of the stage.		
5 N/A	Very Satisfactory - Generous size, excellent condition									
	Does not apply arts and support spaces appropriately configured per the			ı		I			ı	
10.7 ed spec?	arts and support spaces appropriately configured per the				4			Comments	1.00	4.00
1	Very unsatisfactory - Too small, missing program spaces	1		<u> </u>		<u> </u>		Good size and condition.	1.00	4.00
2	Unsatisfactory - Too small, poor condition									
3	Neutral - Adequate size, adequate condition, needs									
Ĭ	updates or renovations to function well.									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply									
Desert										
	ampus have adequate space for the specialty arts (Ensemble, Guitar, Music studies, Music theory and Piano)?					5		Comments		
programs	Ensemble, Outer, ividale studies, ividale trieory drid Fidilo)?								1.00	5.00
1	No							Lab space provided		
5	Yes									

11 - Athletics and Wellness							18.75	57%
11.1 Does the campus meet ed spec standard for physical education program spaces?			4			Comments	1.00	4.00
1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply						Spaces are large and in fairly good condition. Outdoor some attention.	amenities ne	∍ed
11.2 Does the campus have a dedicated wellness center?	1					Comments	0.50	0.50
1 No 5 Yes								
11.3 Does the community have access to exterior playfields/courts?				5		Comments	0.50	2.50
1 No 5 Yes						Yes, and school reports wear and tear on track.		
17.4 Are facilities available to facilitate eSports (High School only)?					N/A	Comments	0.00	0.00
1 No 5 Yes						Monitoring answer, but doesn't affect overall score.		
11.5 Are facilities set up to support UIL sanctioned athletics for basketball?				5		Comments	0.25	1.2
1 No 5 Yes			ı					
11.6 Are facilities set up to support UIL sanctioned athletics for track?	1					Comments	0.25	0.2
1 No 5 Yes						supports practice, but no spectator seating and water/rare too distant.	estroom fac	ilities
11.7 Are facilities set up to support UIL sanctioned athletics for football?	1					Comments	0.25	0.2
1 No 5 Yes						supports practice, but no spectator seating and water/r are too distant.	estroom fac	ilities
11.8 Are facilities set up to support UIL sanctioned athletics for volleyball?				5		Comments	0.25	1.2
1 No 5 Yes								
11.9 Are facilities set up to support UIL sanctioned athletics for tennis?	1					Comments	0.25	0.2
1 No 5 Yes						4 courts in poor condition.		
11.10 Are facilities set up to support UIL sanctioned athletics for soccer?	1					Comments	0.25	0.25
1 No 5 Yes						supports practice, but no spectator seating and water/rare too distant.	restroom fac	ilities

Perkins&Will 02/11/2022 9

11 - Athletics and Wellness (cont.)		1	2	3 4	5	N/A			
11.11 Are facilities (dedicated storage) set up to support UIL sanction athletics for cross-country (high school only)?	ned					N/A	Comments	0.00	0.00
1 No 5 Yes									
11.12 Are facilities (dedicated storage) set up to support UIL sanction athletics for golf (high school only)?	ned					N/A	Comments	0.00	0.00
1 No 5 Yes									
11.13 Are facilities (dedicated storage) set up to support UIL sanction athletics for swimming (high school only)?	ned					N/A	Comments	0.00	0.00
1 No 5 Yes									
11.14 Are facilities set up to support UIL sanctioned athletics for wres (high school only)?	stling					N/A	Comments	0.00	0.00
1 No 5 Yes									
11.15 Are facilities set up to support UIL sanctioned athletics for base (high school only)?	eball					N/A	Comments	0.00	0.00
1 No 5 Yes					ı	ı			
11.16 Are facilities set up to support UIL sanctioned athletics for softb (high school only)?	ball					N/A	Comments	0.00	0.00
1 No 5 Yes					ſ	1			
11.17 Are facilities (dedicated space outside of the gymnasium) avai support competitive spirit activities for cheerleading and drill to		1					Comments	0.25	0.25
1 No 5 Yes									
11 - Athletics and Wellness (cont.)		1	2	3 4	5	N/A			
How do the athletics fields align with FMP Campus Improveme 11.18 Turf Field, Parking lot lighting, ADA accessible amenities (high sonly)						N/A	Comments	0.00	0.00
l Very unsatisfactory - No turf, inaccessible, no site	lighting						Monitoring answer, but doesn't affect overall score.		
2 Unsatisfactory - No turf/field in poor condition, so accessibility concerns, poor site lighting	ome								
3 Average - Field in adequate condition, needs som updates or renovations to function well	ne								
4 Satisfactory - Turf field in good condition, good A access and site lighting	ADA								
5 Very Satisfactory - Turf field with excellent mainte excellent ADA access for spectators and athletes, excellent site lighting									
N/A Does not apply.									

12 - Food Se	rvices								10.00	70%
12.1 Is the Di	ning Commons appropriately configured per the ed spec?				3				Comments 1.00	3.00
1	Very unsatisfactory - Too small, missing program spaces			•					Options for seating not provided but could be available in outdo courtyard space.	or
2	Unsatisfactory - Too small, poor condition, only one									
	option for eating space provided, inadequate circulation									
3	Average - Adequate size and condition, needs updates									
4	or renovations to function well Satisfactory - Good size and condition, good circulation,									
4	multiple options for eating space (ex: connection to									
	outdoor eating space)									
5	Very Satisfactory - Generous size, excellent condition and	1								
	circulation, multiple options for eating space (ex:									
	connection to outdoor eating space)									
N/A	117									
122	Food Services support spaces appropriately configured per				4	1			Comments	
the ed s	•								1.00	4.00
1	Very unsatisfactory - None provided								Appears to be in good condition and size. The school notes there	are
2	Unsatisfactory - Too small, disconnected, poor condition								cracks in the walls in two areas of the cafeteria offices.	
•										
3	Neutral - Adequate size, average condition, needs updates or renovations to function well									
4	Satisfactory - Good size, connected, good condition									
5	Very Satisfactory - Generous size, connected, excellent									
J	condition									
N/A	Does not apply									
13 - Media R	Pesoturces	1	2		3 4	1	5	N/A	30.00	57%
	prary/Media Center easily accessible for the occupants and	Ť	T	Т		T				0770
131	to the school?		2						Comments 1.00	2.00
1	Very unsatisfactory - Not accessible								Not readily apparent, not very transparent.	
2	Unsatisfactory - Limited access, difficult to find, no									
	transparency									
3	Average - Adequate accessibility, needs updates or									
4	renovations to function well Satisfactory - Accessible, easy to find, good									
4	transparency, good condition									
5	Very Satisfactory - Accessible, easy to find, excellent									
Ü	transparency, excellent condition									
N/A	• •								L	

13 - Media Res	sources - Continued	1	2	3	4	5	N/A	4		
13.2 How well d	does the Library/Media Center support quiet study?		2					Comments	1.00	2.00
1 2 3 4 5	Very unsatisfactory - No quiet study spaces Unsatisfactory - One area in poor condition, poor acoustic privacy Average - One or more areas provided, needing updates or renovations to function well Satisfactory - Clusters or small rooms adjacent to media center, good condition, good acoustic privacy Very Satisfactory - Multiple clusters or small rooms adjacent to media center, excellent condition, excellent acoustic privacy Does not apply							No small study spaces available.		
	does the Library/Media Center support social interaction?			3				Comments	1.00	3.00
1 2 3 4 5	Very unsatisfactory - No space Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well Average - Adequate size and condition, needs updates or renovations to function well. Satisfactory - Good size, good condition, layout and furnishings support informal interactions Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions							Open but congregation spaces are not large.		
N/A How well d	Does not apply does the Library/Media Center support collaborative work			3				Comments		
1 2 3 4 5	Very unsatisfactory - No breakout rooms, no flexible furniture, no support Unsatisfactory - Too small, one area, poor condition Average - Adequate size, multiple areas provided, needing updates or renovations to function well Satisfactory - Clusters or small rooms adjacent to media center, flexible furniture, good condition Very Satisfactory - Multiple clusters or small rooms adjacent to media center, flexible furniture, excellent condition			3				Small group tables provided but otherwise open.	1.00	3.00
N/A	Does not apply does the Library/Media Center support collaborative work				1					
13 5	roups (10-25)?			3				Comments	1.00	3.00
1 2 3	Very unsatisfactory - No gathering areas Unsatisfactory - Too small, one common space, limited seating, poor condition Average - Adequate size, one common space, needs updates or renovations to function well							Small group tables provided but otherwise open.		
4 5	Satisfactory - Good size, multiple common spaces with seating, good condition Very Satisfactory - Generous size, multiple commons									
N/A	spaces with seating, excellent condition Does not apply									

1	3 - Media Res	sources - Continued	1	2	3	4	5	N,	/A		
	13.6 How well o	does the Library/Media Center support technology?				4			Comments	1.00	4.00
	1 2 3 4 5	Very unsatisfactory - No vis comm tools Unsatisfactory - Outdated, poorly functioning, or insufficient Average - Mix of old and new whiteboards/projectors/etc. Satisfactory - projectors, marker boards, smart boards in most spaces - good condition Very Satisfactory - projectors, marker boards, smart boards in most spaces - new condition							Floor outlets provided, several teaching screens.		
1	N/A 4 - Technolog	Does not apply	1	2	3	4	5	N,	/A	20.00	65%
		equipped are the facilities with instructional technology?			3			11/	Comments	1.00	3.00
	1 2 3 4 5 N/A	Very unsatisfactory - Limited to no technology present in instructional spaces Unsatisfactory - One type of technology present Average - Multiple types of technology, smart boards. Poor condition. Limited to only certain areas of school. Satisfactory - Multiple types of technology, smart boards. Good condition. Very Satisfactory - Multiple types of technology, smart boards. Excellent condition							Smart board observed in most studios but old TVs ne	ed to be remo	ved.
Ī		Does not apply adequate number of power and data outlets in learning			3				Comments	1.00	3.00
	1 2 3	Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall) Average - Outlet configuration support digital devices		1			1	1	Some rooms have 3 outlets per wall; others have only		
	4 5	but limited capacity throughout school (3 per wall) Satisfactory - Outlet configuration support digital devices with adequate coverage and capacity in limited locations (>3 per wall) Very Satisfactory - Excellent outlet configuration to									
	N/A	support digital devices throughout school (>3 per wall) Does not apply									

Perkins&Will 02/11/2022 13

14 - Technolog	y (cont.)	1	2	3	3 4	5	1	N/A			
14.3 Are there o	dequate charging locations for devices?		2						Comments	1.00	2.00
1 2 3 4 5	Very unsatisfactory - Not enough charging locations throughout school for 1:1 Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices Average - Charging locations well organized but not enough capacity for 1:1 Satisfactory - Charging locations, haphazard locations, but supports 1:1. Very Satisfactory - Charging locations throughout school to support 1:1.								No capacity for 1:1		
N/A	Does not apply equate AV for presentations spaces – cafeteria, gym, aux			1			_	I			
14.4 gym?	equate AV 101 presentations spaces – caretena, gynn, aux				5				Comments	1.00	5.00
1 2 3 4 5 N/A	Very unsatisfactory - AV not present in one or more space Unsatisfactory - AV undersized for room. Poor condition Average - AV adequately sized / poor condition OR AV undersized / average condition Satisfactory - AV adequately sized for room. Average Condition. Very Satisfactory - AV adequately sized for room. Excellent condition. Does not apply								Large screens available		
14.5 Is there dig	ital media signage at the reception area?	1							Comments	0.00	0.00
1 2 3 4 5	Very unsatisfactory - No digital media present in reception area Unsatisfactory - Undersized, poor condition Average - Adequately sized / poor condition OR undersized / adequate condition Satisfactory - Media signage present, good sized, good condition Very Satisfactory - Generously sized, excellent condition								None observed		
N/A	Does not apply										

	15 - Administration Spaces			2	3	4	5	N/A		20.00	40%
	15.1 Is there a reception visitors?	n area that functions as a security checkpoint for all							Comments		
,	•	unsatisfactory - No security checkpoint									
	2 Unsat	isfactory - Checkpoint is too small, poor condition									
	3 Avero	ge - Needs updates or renovations to function well									
	4 Satisf	actory - Good size, good condition									
	5 Very S	Satisfactory - Generous size, excellent condition									
	N/A Does	not apply									
	15.2 Does the administr	ration area feel welcoming?			3				Comments	1.00	3.00
	1 Very	unsatisfactory - No welcome space							Good size but not much character		
	2 Unsat	transparency, limited informal seating, poor condition									
	Average - Adequate size and layout, needs updates or										
		renovations to feel welcoming									
		4 Satisfactory - Good size and layout, good lighting and									
		transparency, informal seating provided Very Satisfactory - Generous size and layout, plenty of									
	,	light and transparency, informal seating provided, excellent condition									
	•										
	N/A Does not apply										
	For those spaces th	nat require it, does the administration area have		0					Community		
	adequate acoustic	privacy?		2					Comments	1.00	2.00
	1 Very								Observed little privacy		
		,									
		well									
	·	portions need updates or renovations									
		4 Satisfactory - Good acoustic separations 5 Very Satisfactory - Excellent acoustic separations N/A Does not apply									
	•										
	N/A Does										
	15.4 Are conference roo	oms easily accessed for public / parent use?		2					Comments	1.00	2.00
	1 Very	unsatisfactory - Not accessible for public/parent							Limited access to conference room		
	use										
		isfactory - Limited access, no transparency, poor									
		tion, difficult to find									
		Average - Adequate accessibility, needs updates or repoyations to function wall.									
	renovations to function well Satisfactory - Good accessibility, good transparency,										
		size and condition									
		Satisfactory - Excellent accessibility, excellent									
		parency, generous size, excellent condition									
	·	not apply									